

# **Moraga Storm Drain Master Plan**

## **July 2015**

## **APPENDICES**

A – V&A Condition Assessment

B – Culvert Assessment Field Sheets and  
Photos

C – Street Pavement Storm Drain Repairs

D – Capacity Improvement Project Sheets

E – Creek Culvert Improvement Project  
Sheets



# APPENDIX A

## V&A Storm Drain Condition Assessment

# TECHNICAL MEMORANDUM

## TOWN OF MORAGA STORM DRAINAGE CONDITION ASSESSMENT

Prepared for: Robin Lee, PE, Schaaf & Wheeler Consulting Civil Engineers

Prepared by: Clinton McAdams, EIT, ENV SP, V&A Consulting Engineers

Reviewed by: Michael Johannessen, PE, V&A Consulting Engineers, Inc.  
Glenn Willson, PE, V&A Consulting Engineers, Inc.



Date: July 2, 2015

V&A Project No.: 13-0390

# ES EXECUTIVE SUMMARY

V&A Consulting Engineers, Inc. (V&A) was retained by Schaaf & Wheeler (S&W) to conduct a condition assessment of storm drain facilities in support of the Storm Drain Master Plan (SDMP) for the Town of Moraga, California (Town). The field work was performed over a total of four days during the months of May, June, October, and November 2014. Based on the findings from the condition assessment activities, V&A presents the following conclusions:

- A total of 80 features (approximately 3 percent of the storm drainage system) were documented.
- 7 of the evaluated features have a prioritization rating of 5. The Rheem Shopping Center Pipeline is one of these features, and was documented having a severe/significant amount of damage. This pipeline along with the other features given this rating, require immediate repair or replacement.
- 2 of the evaluated features have a prioritization rating of 4. This rating requires prioritization for rehabilitation within the next 5 years.
- 71 of the evaluated features have a prioritization rating of 3 or lower. These features have moderate to minor defects and should be reassessed within the next 5 to 15 years.
- 15 of the evaluated features have signs of infiltration.

Before performing any of the suggested recommendations, appropriate analysis of alternatives and detailed design should be conducted for each item. The suggested rehabilitation methods are based on industry standards and may not apply to all situations. Based on the findings from the condition assessment activities, V&A presents the following recommendations for consideration:

- Continue to collect storm drainage feature information to update and develop the Town's GIS for the storm drainage system. This includes features that are not currently on the Town's system wide GIS.
- Conduct further investigations and rehabilitate specific features mentioned in this report based on the timeframes provided. A list of general suggested rehabilitation methods is provided as follows:
  - Pour a new concrete invert in pipes noted with significant surface corrosion and perforations at the invert. Ensure that the pipe bedding is restored below and around the pipe and that the new invert has structural strength for the anticipated loading on the pipe.

- Consider methods such as cast-in-place-pipe liner, slip-lining, pipe bursting in conjunction with replacement materials/liners, and also conventional open-cut construction for pipes noted with significant defects.
- Establish a routine cleaning schedule for pipes noted with significant sediment/debris.
- Install retaining walls or similar erosion control devices in areas that have a high potential for burial/overgrowth.
- Alternatives for rehabilitation and replacement of the Rheem Shopping Center Pipeline should be considered to determine the best viable approach, preferably considering the economic, social, and environmental aspects of the project.

# 1.0 INTRODUCTION

V&A Consulting Engineers, Inc. (V&A) was retained by Schaaf & Wheeler (S&W) to conduct a condition assessment of storm drain facilities in support of the Storm Drain Master Plan (SDMP) for the Town of Moraga, California (Town). The findings of the assessment will serve as a guide for future improvements, rehabilitation, and expansion of the City's storm water infrastructure. A total of 25 locations were selected for condition assessment. For the purpose of this report, the locations will be referenced as storm drainage facility areas (SDFA). The SDFA contained, but are not limited to, catch basins, pipes, manholes, and channels. The criteria for picking the SDFA is as follows:

- Needed field verification/documentation
- Known areas of concern
- Areas marked for proposed pavement repair projects

The field work was performed over a total of four days during the months of May, June, October, and November 2014. Each SDFA consisted of evaluating a point feature (e.g. a catch basin or manhole) and all the connecting pipe features accessible from that point. Figure 1-1 shows the SDFA where the condition assessment activities were performed.




Figure 1-1. Map of Selected SDFAs for Condition Assessment

# 2.0 CONDITION ASSESSMENT

Qualitative condition assessment observations were based on V&A's extensive experience evaluating potable water, wastewater, and storm water structures and pipelines. Assessment methods included the following:

- Feature IDs for the assets evaluated were taken from the Town's storm drainage geographic information system (GIS). Features that were not within the GIS were assigned a new ID.
- Visual examinations and documentation with photographs. A pole-mounted camera was used to evaluate features through video documentation that were unable to be properly assessed from a topside evaluation. When applicable, a confined space entry was conducted to document some of the features.
- Pipes were evaluated starting with the effluent pipe and moving in a clockwise direction to the subsequent pipes found at each access point. When the effluent, or outlet, pipe was unknown, a sketch was provided depicting the estimated direction of flow.
- Feature locations were recorded using a handheld GPS unit and/or through written documentation. The feature was identified as being on public or private property.
- Relevant dimensions and grade/rim to invert depth were measured or estimated, depending on access and the surrounding environment.
- Sediment/debris was briefly described and its depth was measured or estimated. Also, water depth within the feature was measured or estimated.
- Deflections, cracking, corrosion, displacement, and other defects and concerns were documented.
- VANDA Condition Index ratings were used as appropriate (Table 2-1 and Table 2-2).
- Observations of infiltration were rated according to the National Association of Sewer Service Companies (NASSCO) Pipeline Assessment and Certification Program (PACP) codes (Table 2-3).
- V&A used a prioritization rating scale of 1 to 5 to classify the storm drainage facilities needing attention. The rating is in the order of increasing priority from 1 to 5, with facilities rated 5 needing immediate attention. Table 2-4 summarizes the methods used to prioritize the facilities and some example defects associated with each priority level.

The condition assessment data gathered for this project was limited to what was visible from the available access points. Defects may exist in portions of the pipe segments not visible to the evaluator. In some situations, a view into the pipe was not possible due to access limitations, sediment/debris, or other factors. In some cases, the condition assessment data did not provide enough useful information to apply ratings for an asset.

## 2.1 VANDA™ Reinforced Concrete Condition Index

The VANDA™ Reinforced Concrete Condition Index was created by V&A to provide consistent reporting of corrosion damage based on qualitative, objective criteria. Condition of corrosion can vary from Level 1 to Level 4 based upon visual observations and field measurements, with Level 1 indicating the best condition and Level 4 indicating severe damage. Table 2-1 describes the concrete condition index system.

**Table 2-1. VANDA™ Reinforced Concrete Condition Index Rating System**

Condition Rating	Description	Representative Photograph
Level 1	<b>None/Minimal Damage to Concrete</b> Hardness: No Loss Surface Profile: No Loss Cracking: Shrinkage Cracks Spalling: None Reinforcing Steel (Rebar): Not Exposed or Damaged	
Level 2	<b>Damage to Concrete Mortar</b> Hardness: Damage to Concrete Mortar Surface Profile: Some Loss Cracking: Thumbnail Sized Cracks of Minimal Frequency Spalling: Shallow Spalling of Minimal Frequency, Related Rebar Damage Reinforcing Steel (Rebar): May Be Exposed but Not Damaged	
Level 3	<b>Loss of Concrete Mortar/Damage to Rebar</b> Hardness: Complete Loss Surface Profile: Large Diameter Exposed Aggregate Cracking: 1/4-inch to 1/2-inch Cracks, Moderate Frequency Spalling: Deep Spalling of Moderate Frequency, Related Rebar Damage Reinforcing Steel (Rebar): Exposed and Damaged, Can Be Rehabilitated	
Level 4	<b>Rebar Severely Corroded/Significant Damage to Structure</b> Hardness: Complete Loss Surface Profile: Large Diameter Exposed Aggregate Cracking: 1/2-inch Cracks or Greater, High Frequency Spalling: Deep Spalling at High Frequency, Related Rebar Damage Reinforcing Steel (Rebar): Damaged or Consumed, Loss of Structural Integrity	

© 2014 V&A Consulting Engineers, Inc. All rights reserved.

## 2.2 VANDA™ Metal Condition Index

The VANDA™ Metal Condition Index was created by V&A to provide consistent reporting of metal corrosion damage based on qualitative, objective criteria. Condition of metal can vary from Level 1 to Level 4 based upon visual observations and field measurements, with Level 1 indicating the best condition and Level 4 indicating severe damage. Table 2-2 displays the metal condition index system.

**Table 2-2. VANDA™ Metal Condition Index Rating System**

Condition Rating	Description	Representative Photograph
<b>Level 1</b>	<b>Little or No Corrosion</b> Loss of Wall Thickness %: None Pitting Depth (as % of Wall Thickness): None to Minimal Extent (Area) of Corrosion: None	
<b>Level 2</b>	<b>Minor Surface Corrosion</b> Loss of Wall Thickness %: < 25% Pitting Depth (as % of Wall Thickness): < 25% Extent (Area) of Corrosion: Localized	
<b>Level 3</b>	<b>Moderate to Significant Corrosion</b> Loss of Wall Thickness %: 25%-75% Pitting Depth (as % of Wall Thickness): 25%-75% Extent (Area) of Corrosion: 25%-75%	
<b>Level 4</b>	<b>Severe Corrosion; Immediate Repair/Replacement Needed</b> Loss of Wall Thickness %: > 75% Pitting Depth (as % of Wall Thickness): 75% or More Extent (Area) of Corrosion: Affects Most or All of Surface	

© 2014 V&A Consulting Engineers, Inc. All rights reserved.

## 2.3 Infiltration Ratings

Groundwater infiltration (groundwater leaking into the storm drain system) was observed in some locations. These observations were rated according to the NASSCO PACP codes and broken down into the categories shown in Table 2-3.




**Table 2-3. Infiltration Ratings**

Category	NASSCO PACP Code	Code Meaning	Type of Infiltration
<b>None</b>	-	-	No observed infiltration
<b>Evidence</b>	IS	Infiltration, Stains	Stains or dry encrustations
	IW	Infiltration, Weeper	Wet marks or stains (water weeping in)
<b>Active</b>	ID	Infiltration, Dripper	Dripping water
	IR	Infiltration, Runner	Small stream of flowing water
	IG	Infiltration, Gusher	Larger stream of flowing water under apparent external pressure

## 2.4 Storm Drainage Facility Prioritization Scale

Storm drain features received overall evaluations according to the prioritization ratings shown in Table 2-4. Note that this scale is used for reporting the overall priority ratings of the storm water drainage facilities, while the material conditions, with respect to corrosion, are reported using the VANDA ratings. The prioritization ratings take into account the overall condition of the structure or pipeline, isolated defects that were noted, and factors such as the possible effects on the surrounding area. Some features may need immediate attention for certain problems even if they are in good condition otherwise. The table also provides a recommended timeline for repair or reassessment of the facilities.

**Table 2-4. Storm Drainage Facility Prioritization Scale**

Color Code	Rating	Reassessment or Repair Priority	Structural Rating Example	
	<b>1</b> <b>Excellent</b>	Failure unlikely in the foreseeable future. Reassess on a 15-year interval.		Minor or no defects
	<b>2</b> <b>Good</b>	Reassess on a 10-year interval.		Defects that have not begun to deteriorate
			 Longitudinal Cracking	
	<b>3</b> <b>Fair</b>	Reassess on a 5-year interval and consider conducting repairs.		Moderate defects that will continue to deteriorate
			 Multiple Fractures	
	<b>4</b> <b>Poor</b>	Prioritize for rehabilitation within 5 years.		Severe defects
			 Broken Pipe	
	<b>5</b> <b>Immediate Attention</b>	Repair or replace immediately.		Defect requires immediate action
			 Collapsed Pipe	

Rationale for each prioritization rating was made based on the categories described in Table 2-5. Please note that more than one category may influence the provided prioritization rating for each feature.

**Table 2-5. Prioritization Rating Rationale**

Rationale	Description
<b>Condition</b>	The condition of the structure warrants the specified rating level due to likelihood and consequence of asset failure.
<b>Location</b>	The location of the asset warrants the specified rating level due to effects on the surrounding area (e.g. the asset is located under a roadway and would have a higher consequence upon failing).
<b>Sediment/Debris</b>	The level of sediment/debris within the asset warrants the specified rating level due to likelihood of hindering asset performance. High levels of sediment/debris can block a pipe and subsequently flood the surrounding area.
<b>Safety</b>	There is a safety concern which warrants the specified prioritization rating (e.g. public access is permitted to an asset that has potential trip and fall or other hazards).
<b>Obstruction</b>	There is an object that has blocked the asset to a degree which warrants the specified prioritization rating due to limitation in feature performance and operation.
<b>Other</b>	There are other aspects that need to be taken into account and warrant the specified prioritization rating

# 3.0 FINDINGS AND ANALYSIS

The selected features assessed at each SDFA received ratings per the VANDA Condition Index scales and the storm drainage facility prioritization scale. Note that the VANDA Condition Index only applies to metal and concrete corrosion damage. Features without a VANDA condition rating were assigned a prioritization rating based on other criteria, such as integrity, operational capabilities, and safety concerns. The features that pose the most significant concern have received a prioritization rating of 4 or 5 and are displayed in Table 3-1. Detailed information regarding all of the individual features that were evaluated is presented in Appendix A – Facility Inventory. Prioritization ratings and recurring notable concerns are analyzed in more detail in the following subsections. Please note that for SDFA 19, 20, 21, and 22, the culverts for each of these locations are divided into two nodes and one pipe feature. These features were not divided, but rather considered a single feature for each location for the analysis since the access points, or nodes, are the culvert itself.

Feature IDs for known features were taken from the Town's storm drainage GIS, and new IDs were assigned to features found in the field that were not shown on the GIS. Assigned IDs were based on the Town zone the feature was located in, the type of feature, the SDFA the feature was associated with, and order of evaluation. Based on these criteria, a feature (e.g., a catch basin or manhole) evaluated in Zone 1 at SDFA 1 would have the ID of Z1\_NODE\_S1, and a pipe at the same location would have the ID of Z1\_LINK\_S1\_P1. The pipes were evaluated starting with the effluent pipe and moving in a clockwise direction to the subsequent pipes found at each access point.

**Table 3-1. Features with a Prioritization Rating of 4 or 5**

SDFA	Feature ID	Type	Location	Dia. (in)	Matl.	VANDA Rating	Priority Rating	Priority Rationale
20	Z5_LINK_S20	Culvert	1528 St Marys Rd	50	CMP	Level 2	Level 5	Sediment Safety
6	Z3_LINK_S6_P1	Pipe	Moraga Rd	24	CMP	Level 4	Level 5	Condition Location
11	Z5_LINK_S11_P3	Pipe	Joseph Dr/Bollinger Canyon Rd	18	RCP	Level 4	Level 5	Condition Location
21	Z6_LINK_S21	Culvert	423 Canyon Rd	10H x 15W	CMP	Level 4	Level 5	Condition Location
10	Z3_LINK_S10_P1	Pipe	Donald Dr/Fernwood Dr	Unknown	RCP	Unknown	Level 5	Condition Obstruction
18	Z3_LINK_S18_P1	Catch Basin	Rheem Blvd/Center St	96	CMP	Level 4	Level 5	Condition Location
18	Z3_LINK_S18_P2	Catch Basin	Rheem Blvd/Center St	96	CMP	Level 4	Level 5	Condition Location
6	Z3_LINK_S6_P3	Pipe	Moraga Rd	24	CMP	Level 3	Level 4	Condition Location
11	Z5_LINK_S11_P1	Pipe	Joseph Dr/Bollinger Canyon Rd	18	CMP	Level 3	Level 4	Condition Location

### 3.1 Prioritization Ratings

The condition assessment analysis shows that 9 of the evaluated features have a prioritization rating of Level 4 or 5. These features require immediate replacement/rehabilitation, or prioritization for rehabilitation within the next 5 years. The majority of the features evaluated are in good to adequate condition with 71 features having a prioritization rating of 3 or lower. The results of this analysis are displayed in Table 3-2 and Figure 3-1.

Table 3-2. Prioritization of Evaluated Features

Prioritization Rating	Number of Features	Percentage of Evaluated Features
5	7	9%
4	2	3%
3	13	16%
2	41	51%
1	17	21%




Figure 3-1. Prioritization Percentages of Evaluated Features

## 3.2 Condition Ratings

There are 7 features that were observed to have severe/significant to moderate amount of damage due to corrosion. 65 features were observed to have minor to no corrosion damage. The remaining 8 features evaluated were not assigned a VANDA condition rating due to materials of construction (plastic pipes, for example) or limited amount of information available for evaluation. These features are listed under the “Not Rated” category. The results of this analysis are displayed in Table 3-3 and Figure 3-2.

Table 3-3. Condition of Evaluated Features

VANDA Level	Number of Features	Percentage of Evaluated Features
4	5	6%
3	2	2%
2	15	19%
1	50	63%
Not Rated	8	10%





Figure 3-2. Condition Percentages of Evaluated Features

### 3.3 Infiltration

Out of the 80 features evaluated, 15 features were noted with signs of groundwater infiltration. The majority of the features evaluated do not appear to have infiltration. Features with a lack of information available to determine if infiltration is present are listed under "Not Rated". The results of this analysis are displayed in Table 3-4 and Figure 3-3.

**Table 3-4. Infiltration Ratings for Evaluated Features**

Infiltration Rating	Number of Features	Percentage of Evaluated Features
None	62	77%
Evidence	15	19%
Active	0	0%
Not Rated	3	4%



**Figure 3-3. Percentage of Evaluated Features with Infiltration**

### 3.4 Rheem Shopping Center Pipeline

A confined space entry was performed to evaluate the 96-inch corrugated metal pipe (CMP)/reinforced-concrete pipe (RCP) that is located under the Rheem Shopping Center. Entry to the pipeline was through a catch basin located at the intersection of Rheem Blvd and Center St. The approximate location of the pipeline is shown in Figure 3-4. To allow access, the Town scheduled to remove a filter from the catch basin prior to the assessment. The assessment consisted of an Attendant/Supervisor who remained topside, an Entrant who accessed the pipe and conducted the evaluation, and a Standby-Rescue who was positioned within the pipeline near the entry point. A ventilation blower was utilized to provide additional airflow during the assessment. Approximately 81 feet of pipe was evaluated upstream (heading north) from the entry point. This stretch of pipe consisted of about 46 feet of CMP, followed by 35 feet of RCP. There were numerous defects documented including surface corrosion, holes with voids visible, and infiltration staining. Approximately 440 feet of CMP was evaluated downstream from the entry point. Similar defects were noted as seen upstream, along with additional defects such as deformations. The end point of the downstream assessment was at a storm drainage grate near the drive-through exit for the building in the northeast corner of the shopping center parking lot. At this point, the pipe bends from heading southeast to south. Figure 3-5 through Figure 3-7 present the condition assessment findings and approximate observation locations on the features evaluated. More detailed findings from the assessment are presented under SDFA 18 in Appendix A – Facility Inventory.





Figure 3-4. Location of Rheem Shopping Center Pipeline



**Figure 3-5. Assessment of Entry Point (Section View)**




Figure 3-6. Assessment Downstream from Entry Point (Plan View)




Figure 3-7. Assessment Upstream from Entry Point (Plan View)

# 4.0 CONCLUSIONS

Based on the findings from the condition assessment activities, V&A presents the following conclusions:

- A total of 80 features (approximately 3 percent of the storm drainage system) were documented.
- 7 of the evaluated features have a prioritization rating of 5. The Rheem Shopping Center Pipeline is one of these features, and was documented having a severe/significant amount of damage. This pipeline along with the other features given this rating, require immediate repair or replacement.
- 2 of the evaluated features have a prioritization rating of 4. This rating requires prioritization for rehabilitation within the next 5 years.
- 71 of the evaluated features have a prioritization rating of 3 or lower. These features have moderate to minor defects and should be reassessed within the next 5 to 15 years.
- 15 of the evaluated features have signs of infiltration.

# 5.0 RECOMMENDATIONS

Before performing any of the suggested recommendations, proper planning and evaluation procedures for specified areas must be conducted. The suggested rehabilitation methods are based on industry standards and may not apply to all situations. Based on the findings from the condition assessment activities, V&A presents the following recommendations for consideration:

- Continue to collect storm drainage feature information to update and develop the Town's GIS for the storm drainage system. This includes features that are not currently on the Town's system wide GIS.
- Conduct further investigations and rehabilitate specific features mentioned in previous sections and in Appendix A – Facility Inventory based on the timeframe provided in the storm drainage facility prioritization scale. A list of general suggested rehabilitation methods is provided as follows:
  - Pour a new concrete invert in pipes noted with significant surface corrosion and perforations at the invert. Ensure that the pipe bedding is restored below and around the pipe and that the new invert has structural strength for the anticipated loading on the pipe.
  - Consider methods such as cast-in-place-pipe liner, slip-lining, pipe bursting in conjunction with replacement materials/liners, and also conventional open-cut construction for pipes noted with significant defects.
  - Establish a routine cleaning schedule for pipes noted with significant sediment/debris.
  - Install retaining walls or similar erosion control devices in areas that have a high potential for burial/overgrowth.
- Alternatives for rehabilitation and replacement of the Rheem Shopping Center Pipeline should be considered to determine the best viable approach, preferably considering economic, social, and environmental aspects of the project.

# APPENDIX A - FACILITY INVENTORY

## Table of Contents

Description	App. Page No.
<b>SDFA 1 - 143 Natalie Dr</b>	<b>1</b>
Z1_NODE_0060	2
Z1_LINK_0041	5
Z1_LINK_0040	6
<b>SDFA 2 - Buckingham Dr</b>	<b>7</b>
Z1_NODE_0042	8
Z1_LINK_0012	11
Z1_LINK_0013	12
<b>SDFA 3 - Scofield Dr</b>	<b>13</b>
Z2_NODE_0065	14
Z2_LINK_0040	17
Z2_LINK_S3_P1	18
Z2_LINK_S3_P2	19
<b>SDFA 4 - Chalda Way</b>	<b>20</b>
Z3_NODE_S4	21
Z3_LINK_S4_P1	24
Z3_LINK_S4_P2	25
Z3_LINK_S4_P3	26
Z3_LINK_S4_P4	27
<b>SDFA 5 - Camino Ricardo</b>	<b>28</b>
Z4_NODE_0197	29
Z4_LINK_S5_P1	31
Z4_LINK_S5_P2	32
<b>SDFA 6 - Moraga Rd</b>	<b>33</b>
Z3_NODE_0068	34
Z3_LINK_S6_P1	37
Z3_LINK_S6_P2	38


Description	App. Page No.
Z3_LINK_S6_P3	39
<b>SDFA 7 - Willow Springs Ct</b>	<b>40</b>
Z3_NODE_S7	41
Z3_LINK_S7_P1	43
<b>SDFA 8 - Corliss Dr</b>	<b>44</b>
Z4_NODE_0160	45
Z4_LINK_0052	48
Z4_LINK_0053	49
Z4_LINK_0067	50
<b>SDFA 9 - Bedford Pl and Fernwood Dr</b>	<b>51</b>
Z3_NODE_0027	52
Z3_LINK_0019	55
Z3_LINK_0020	56
Z3_LINK_0037	57
Z3_LINK_0046	58
<b>SDFA 10 - Donald Dr and Fernwood Dr</b>	<b>59</b>
Z3_NODE_0141	60
Z3_LINK_0133	62
Z3_LINK_0141	63
Z3_LINK_S10_P1	64
Z3_LINK_0142	65
<b>SDFA 11 - Joseph Dr and Bollinger Canyon Rd</b>	<b>66</b>
Z5_NODE_0126	67
Z5_LINK_S11_P1	70
Z5_LINK_S11_P2	71
Z5_LINK_S11_P3	72
<b>SDFA 12 - Del Rio Way</b>	<b>73</b>
Z5_NODE_0056	74
Z5_LINK_S12_P1	77
Z5_LINK_S12_P2	78
<b>SDFA 13 - Country Club Dr and School St</b>	<b>79</b>
Z6_NODE_0039	80

Description	App. Page No.
Z6_LINK_S13_P1	83
Z6_LINK_S13_P2	84
<b>SDFA 14 - Country Club Dr</b>	<b>85</b>
Z7_NODE_0089	86
Z7_LINK_S14_P1	88
Z7_LINK_S14_P2	89
Z7_LINK_S14_P3	90
<b>SDFA 15 - Rimer Dr</b>	<b>91</b>
Z7_NODE_S15	92
Z7_LINK_S15_P1	94
Z7_LINK_S15_P2	95
Z7_LINK_S15_P3	96
<b>SDFA 16 - Deerfield Dr</b>	<b>97</b>
Z7_NODE_0158	98
Z7_LINK_S16_P1	101
Z7_LINK_S16_P2	102
<b>SDFA 17 - Deerfield Dr and Stoneridge Pl</b>	<b>103</b>
Z7_NODE_0203	104
Z7_LINK_S17_P1	107
Z7_LINK_S17_P2	108
<b>SDFA 18 - Rheem Blvd and Center St</b>	<b>109</b>
Z3_NODE_S18	110
Z3_LINK_S18_P1	113
Z3_LINK_S18_P2	117
<b>SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr</b>	<b>123</b>
Z5_NODE_S19_N1	124
Z5_LINK_S19	127
Z5_NODE_S19_N2	129
<b>SDFA 20 - 1528 St Marys Rd</b>	<b>131</b>
Z5_NODE_S20_N1	132
Z5_LINK_S20	134
Z5_NODE_S20_N2	136

Description	App. Page No.
<b>SDFA 21 - 423 Canyon Rd</b>	<b>139</b>
Z6_NODE_S21_N1	140
Z6_LINK_S21	142
Z6_NODE_S21_N2	144
<b>SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd</b>	<b>146</b>
Z7_NODE_S22_N1	147
Z7_LINK_S22	150
Z7_NODE_S22_N2	154
<b>SDFA 23 - Larch Ave and Ross Dr</b>	<b>157</b>
Z7_NODE_0022	158
Z7_LINK_S23_P1	161
Z7_LINK_S23_P2	162
<b>SDFA 24 - Paseo Del Rio</b>	<b>163</b>
Z1_NODE_0204	164
Z1_LINK_0162	167
Z1_LINK_0175	168
Z1_LINK_0163	169
Z1_LINK_0176	170
<b>SDFA 25 - Draeger Dr</b>	<b>171</b>
Z3_NODE_0174	172
Z3_LINK_0173	174
Z3_LINK_0174	175

SDFA 1 - 143 Natalie Dr

## *Area Map*



**SDFA 1 - 143 Natalie Dr****Catch Basin Z1\_NODE\_0060**

Evaluation date/time: 6/27/2014 12:17 PM

Address/location: 143 Natalie Dr

Weather: Dry


**General Information**

Latitude:	37.8671	Susceptible to burial/overgrowth:	No
Longitude:	-122.12022	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	5
Access:	Good	Type of sediment/debris	Rock
Traffic:	None	Infiltration:	None
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 2 - Good
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	4.25		
Water level (%):	0		
Devices:	None		

**Notes**

Fractures in catch basin walls. RI in sketch signifies rim-to-invert.

**Photos**

**SDFA 1 - 143 Natalie Dr**
**Catch Basin Z1\_NODE\_0060**


Sketch



Location view.



Down view of structure.



View of outlet.

## SDFA 1 - 143 Natalie Dr

## Catch Basin Z1\_NODE\_0060



View of inlet.

**SDFA 1 - 143 Natalie Dr*****Pipe Z1\_LINK\_0041***

Evaluation date/time: 6/27/2014 12:17 PM

Address/location: 143 Natalie Dr

Weather: Dry

**General Information**

Property type:	Private	Sediment depth (%):	0
Diameter (in):	24	Type of sediment:	None
Upstream feature ID:	Z1_NODE_0061	Infiltration:	Stain
Downstream feature ID:	Z1_NODE_0060	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	4	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

**Notes**

Inlet pipe. Pipe runs under residence. Please refer to included videos for visuals.

**Photos**

**SDFA 1 - 143 Natalie Dr*****Pipe Z1\_LINK\_0040***

Evaluation date/time: 6/27/2014 12:17 PM

Address/location: 143 Natalie Dr

Weather: Dry

**General Information**

Property type:	Public	Sediment depth (%):	10
Diameter (in):	30	Type of sediment:	Rock, Gravel
Upstream feature ID:	Z1_NODE_0060	Infiltration:	None
Downstream feature ID:	Z1_NODE_0059	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	4.25	VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 1 - Excellent
Material:	RCP	Prioritization Rationale:	Condition


**Notes**

Outlet pipe. Pipe runs under road shoulder. Please refer to included videos for visuals.

**Photos**

## SDFA 2 - Buckingham Dr

## Area Map



## SDFA 2 - Buckingham Dr

### ***Catch Basin Z1\_NODE\_0042***

Evaluation date/time: 6/27/2014 9:40 AM

Address/location: Buckingham Dr

Weather: Dry


#### General Information

Latitude:	37.864522	Susceptible to burial/overgrowth:	No
Longitude:	-122.122176	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	5
Access:	Good	Type of sediment/debris	Rock
Traffic:	None	Infiltration:	Weeper
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 1 - No Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 2 - Good
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	12.5		
Water level (%):	5		
Devices:	None		

#### Notes

Rungs in sound condition. Projecting reinforcing steel at bottom of structure appears to be a construction defect. Infiltration between segments.

#### Photos

**SDFA 2 - Buckingham Dr**
**Catch Basin Z1\_NODE\_0042**


Sketch



Location View



Location View



Down view of structure.

## SDFA 2 - Buckingham Dr

## Catch Basin Z1\_NODE\_0042



Water infiltration staining.

## SDFA 2 - Buckingham Dr

### **Pipe Z1\_LINK\_0012**

Evaluation date/time: 6/27/2014 9:40 AM

Address/location: Buckingham Dr

Weather: Dry

#### General Information

Property type: Private

Diameter (in): 24

Upstream feature ID: Z1\_NODE\_0037

Downstream feature ID: Z1\_NODE\_0042

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 12.5

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

0

VANDA Condition Rating: Level 2 - Minor Damage

Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Condition, Location

#### Notes

Outlet pipe. Scouring on invert. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 2 - Buckingham Dr

### **Pipe Z1\_LINK\_0013**

Evaluation date/time: 6/27/2014 9:40 AM

Address/location: Buckingham Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	24	Type of sediment:	None
Upstream feature ID:	Z1_NODE_0042	Infiltration:	None
Downstream feature ID:	Z1_NODE_0043	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	12.5	VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location


#### Notes

Inlet pipe appears to be offset. Pipe runs under residence. Please refer to included videos for visuals.

#### Photos

## SDFA 3 - Scofield Dr

## *Area Map*



## SDFA 3 - Scofield Dr

### Manhole Z2\_NODE\_0065

Evaluation date/time: 6/27/2014 2:35 PM

Address/location: Scofield Dr

Weather: Dry


#### General Information

Latitude:	37.863235	Susceptible to burial/overgrowth:	No
Longitude:	-122.133545	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	5
Access:	Good	Type of sediment/debris	Silt, Gravel, Rock
Traffic:	Light	Infiltration:	None
Ground surface type:	Asphalt	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	24	Prioritization Rating:	Level 2 - Good
Width (in.):		Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	4		
Water level (%):	0		
Devices:	None		

#### Notes

Exposed reinforcing steel on structure appears to be a construction defect.

#### Photos

**SDFA 3 - Scofield Dr**
**Manhole Z2\_NODE\_0065**


Sketch



Location view.



View of manhole.



Down view of structure.

## SDFA 3 - Scofield Dr

## Manhole Z2\_NODE\_0065



View of outlet.



View of inlets.

## SDFA 3 - Scofield Dr

### **Pipe Z2\_LINK\_0040**

Evaluation date/time: 6/27/2014 2:35 PM

Address/location: Scofield Dr

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 20

Upstream feature ID: Z2\_NODE\_0065

Downstream feature ID: Z2\_NODE\_0064

Upstream rim-inv. (ft.): 3.9

Downstream rim-inv. (ft.):

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 1 - Excellent

Prioritization Rationale: Condition

#### Notes

Outlet pipe. Please refer to included videos for visuals.

#### Photos

## SDFA 3 - Scofield Dr

### **Pipe Z2\_LINK\_S3\_P1**

Evaluation date/time: 6/27/2014 2:35 PM

Address/location: Scofield Dr

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 20

Upstream feature ID:

Downstream feature ID: Z2\_NODE\_0065

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 4

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 10

Type of sediment: Silt, Vegetation

Infiltration: None

Obstruction/Deflection (%) 0

VANDA Condition Rating: N/A

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition

#### Notes

South inlet. Please refer to included videos for visuals.

#### Photos

## SDFA 3 - Scofield Dr

### **Pipe Z2\_LINK\_S3\_P2**

Evaluation date/time: 6/27/2014 2:35 PM

Address/location: Scofield Dr

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 18

Upstream feature ID:

Downstream feature ID: Z2\_NODE\_0065

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 3.8

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 5

Type of sediment: Vegetation

Infiltration: None

Obstruction/Deflection (%)

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 1 - Excellent

Prioritization Rationale: Condition

#### Notes

West inlet pipe. 5% joint offset. Please refer to included videos for visuals.

#### Photos

**SDFA 4 - Chalda Way*****Area Map***

## SDFA 4 - Chalda Way

### ***Catch Basin Z3\_NODE\_S4***

Evaluation date/time: 6/26/2014 2:36 PM

Address/location: Chalda Way

Weather: Dry


#### General Information

Latitude:	37.858458	Susceptible to burial/overgrowth:	No
Longitude:	-122.122006	Susceptible to ponding/flooding:	Yes
Property type:	Public	Sediment/debris depth (%):	5
Access:	Good	Type of sediment/debris	Silt, Vegetation
Traffic:	Light	Infiltration:	None
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 2 - Good
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	8.3		
Water level (%):	5		
Devices:	None		

#### Notes

Projecting reinforcing steel and exposed aggregate at upper east inlet, probably due to break-in connection. Cracking in catch basin walls. No evidence of infiltration.

#### Photos

**SDFA 4 - Chalda Way**
**Catch Basin Z3\_NODE\_S4**


Sketch



Location view.



Location view.



View inside catch basin.

## SDFA 4 - Chalda Way

### Catch Basin Z3\_NODE\_S4



Down view of structure.



Down view of structure.



View of inlets.



Projecting reinforcing steel and exposed aggregate.

## SDFA 4 - Chalda Way

### **Pipe Z3\_LINK\_S4\_P1**

Evaluation date/time: 6/26/2014 2:36 PM

Address/location: Chalda Way

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 40

Upstream feature ID: Z3\_NODE\_S4

Downstream feature ID:

Upstream rim-inv. (ft.): 8.3

Downstream rim-inv. (ft.):

Material: PEP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

0

VANDA Condition Rating: N/A

Prioritization Rating: Level 1 - Excellent

Prioritization Rationale: Condition

#### Notes

Lining delaminated at opening to outlet. Please refer to included videos for visuals.

#### Photos

## SDFA 4 - Chalda Way

### Pipe Z3\_LINK\_S4\_P2

Evaluation date/time: 6/26/2014 2:36 PM

Address/location: Chalda Way

Weather: Dry

#### General Information

Property type: Public

Diameter (in):

Upstream feature ID:

Downstream feature ID: Z3\_NODE\_S4

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 8.3

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 5

Type of sediment: Silt, Rock

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location

#### Notes

North inlet pipe. Pipe runs under roadway. Unable to determine diameter due to position within catch basin. Please refer to included videos for visuals.

#### Photos

## SDFA 4 - Chalda Way

### ***Pipe Z3\_LINK\_S4\_P3***

Evaluation date/time: 6/26/2014 2:36 PM

Address/location: Chalda Way

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 40

Upstream feature ID:

Downstream feature ID: Z3\_NODE\_S4

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 7.7

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location

#### Notes

Northeast inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 4 - Chalda Way

### ***Pipe Z3\_LINK\_S4\_P4***

Evaluation date/time: 6/26/2014 2:36 PM

Address/location: Chalda Way

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 24

Upstream feature ID:

Downstream feature ID: Z3\_NODE\_S4

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 5

Material: PVC

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: N/A

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location


#### Notes

East inlet pipe. Appears to have an offset joint. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 5 - Camino Ricardo

## Area Map



## SDFA 5 - Camino Ricardo

### ***Catch Basin Z4\_NODE\_0197***

Evaluation date/time: 6/26/2014 1:15 PM

Address/location: Camino Ricardo

Weather: Dry


#### General Information

Latitude:	37.850529	Susceptible to burial/overgrowth:	No
Longitude:	-122.134817	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	5
Access:	Good	Type of sediment/debris	Silt
Traffic:	None	Infiltration:	None
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 1 - No Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 1 - Excellent
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	16		
Water level (%):	5		
Devices:	None		

#### Notes

Down stream of Missouri riser. Fracturing in catch basin walls.

#### Photos

**SDFA 5 - Camino Ricardo**
**Catch Basin Z4\_NODE\_0197**


Sketch



Location view.



Down view of structure.



Down view of structure.

## SDFA 5 - Camino Ricardo

### **Pipe Z4\_LINK\_S5\_P1**

Evaluation date/time: 6/26/2014 1:15 PM

Address/location: Camino Ricardo

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	36	Type of sediment:	None
Upstream feature ID:	Z4_NODE_0198	Infiltration:	Stain/Encrustation
Downstream feature ID:	Z4_NODE_0197	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	16	VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

Outlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 5 - Camino Ricardo

### **Pipe Z4\_LINK\_S5\_P2**

Evaluation date/time: 6/26/2014 1:15 PM

Address/location: Camino Ricardo

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 48

Upstream feature ID: Z4\_NODE\_0197

Downstream feature ID: Z4\_NODE\_0195

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 16

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 10

Type of sediment: Silt

Infiltration: Stain/Encrustation

Obstruction/Deflection (%) 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location


#### Notes

Inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 6 - Moraga Rd

## Area Map



## SDFA 6 - Moraga Rd

### ***Catch Basin Z3\_NODE\_0068***

Evaluation date/time: 6/26/2014 2:01 PM

Address/location: Moraga Rd

Weather: Dry


#### General Information

Latitude:	37.84731	Susceptible to burial/overgrowth:	No
Longitude:	-122.125826	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	0
Access:	Good	Type of sediment/debris	None
Traffic:	Heavy	Infiltration:	None
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 1 - No Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 2 - Good
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	6.7		
Water level (%):	5		
Devices:	None		

#### Notes

Good condition.

#### Photos

**SDFA 6 - Moraga Rd**
**Catch Basin Z3\_NODE\_0068**


Sketch



View inside catch basin.



View of east inlet.



View of outlet.

## SDFA 6 - Moraga Rd

### ***Catch Basin Z3\_NODE\_0068***



View of north inlet.



View of catch basin.

## SDFA 6 - Moraga Rd

### Pipe Z3\_LINK\_S6\_P1

Evaluation date/time: 6/26/2014 2:01 PM

Address/location: Moraga Rd

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 24

Upstream feature ID: Z3\_NODE\_0068

Downstream feature ID:

Upstream rim-inv. (ft.): 6.7

Downstream rim-inv. (ft.):

Material: CMP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

0

VANDA Condition Rating: Level 4 - Severe/Significant Damage

Prioritization Rating: Level 5 - Immediate Attention

Prioritization Rationale: Condition, Location

#### Notes

Outlet pipe. Significant surface corrosion. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 6 - Moraga Rd

### Pipe Z3\_LINK\_S6\_P2

Evaluation date/time: 6/26/2014 2:01 PM

Address/location: Moraga Rd

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 16

Upstream feature ID:

Downstream feature ID: Z3\_NODE\_0068

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 5.8

Material: PEP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: N/A

Prioritization Rating: Level 1 - Excellent

Prioritization Rationale: Condition

#### Notes

North inlet pipe. Pipe runs under sidewalk. Please refer to included videos for visuals.

#### Photos

## SDFA 6 - Moraga Rd

### Pipe Z3\_LINK\_S6\_P3

Evaluation date/time: 6/26/2014 2:01 PM

Address/location: Moraga Rd

Weather: Dry

#### General Information

Property type: Private

Diameter (in): 24

Upstream feature ID:

Downstream feature ID: Z3\_NODE\_0068

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 6.3

Material: CMP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

0

VANDA Condition Rating: Level 3 - Moderate Damage

Prioritization Rating: Level 4 - Poor

Prioritization Rationale: Condition, Location

#### Notes

East inlet pipe. Changes diameter and material. Upstream portion is a RCP in good condition. Significant to moderate surface corrosion. Pipe runs under residence. Please refer to included videos for visuals.

#### Photos

**SDFA 7 - Willow Springs Ct*****Area Map***

## SDFA 7 - Willow Springs Ct

### ***Catch Basin Z3\_NODE\_S7***

Evaluation date/time: 6/26/2014 11:24 AM

Address/location: Willow Springs Ct

Weather: Dry


#### General Information

Latitude:	37.845358	Susceptible to burial/overgrowth:	No
Longitude:	-122.123637	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	0
Access:	Good	Type of sediment/debris	None
Traffic:	None	Infiltration:	None
Ground surface type:	Asphalt	VANDA Condition Rating:	Level 1 - No Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 2 - Good
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	2.9		
Water level (%):	0		
Devices:	None		

#### Notes

Good condition.

#### Photos

**SDFA 7 - Willow Springs Ct**
**Catch Basin Z3\_NODE\_S7**


Sketch



Location view.



View inside catch basin.



View of outlet. Concrete slab obstructing pipe.

## SDFA 7 - Willow Springs Ct

### Pipe Z3\_LINK\_S7\_P1

Evaluation date/time: 6/26/2014 11:24 AM

Address/location: Willow Springs Ct

Weather: Dry

#### General Information

Property type: Public

Diameter (in):

Upstream feature ID: Z3\_NODE\_S7

Downstream feature ID:

Upstream rim-inv. (ft.): 2.9

Downstream rim-inv. (ft.):

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 10

Type of sediment: Silt Vegetation

Infiltration: None

Obstruction/Deflection (%): 25

VANDA Condition Rating: Level 1 - No Damage


Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Obstruction

#### Notes

Concrete slab obstructing outlet pipe. Appears to have an offset joint. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

**SDFA 8 - Corliss Dr****Area Map**

## SDFA 8 - Corliss Dr

### ***Catch Basin Z4\_NODE\_0160***

Evaluation date/time: 6/27/2014 1:56 PM

Address/location: 67 Corliss Dr

Weather: Dry


#### General Information

Latitude:	37.844943	Susceptible to burial/overgrowth:	No
Longitude:	-122.136266	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	0
Access:	Good	Type of sediment/debris	None
Traffic:	Light	Infiltration:	None
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 1 - No Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 1 - Excellent
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	4.8		
Water level (%):	0		
Devices:	None		

#### Notes

Good condition.

#### Photos

**SDFA 8 - Corliss Dr**
**Catch Basin Z4\_NODE\_0160**



Sketch



Location view.



View inside catch basin.



Down view of structure.

## SDFA 8 - Corliss Dr

## Catch Basin Z4\_NODE\_0160



View of inlet.

## SDFA 8 - Corliss Dr

### **Pipe Z4\_LINK\_0052**

Evaluation date/time: 6/27/2014 1:56 PM

Address/location: 67 Corliss Dr

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 36

Upstream feature ID: Z4\_NODE\_0160

Downstream feature ID: Z4\_NODE\_0159

Upstream rim-inv. (ft.): 4.8

Downstream rim-inv. (ft.):

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: Stain

Obstruction/Deflection (%) 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 1 - Excellent

Prioritization Rationale: Condition

#### Notes

West inlet pipe. Pipe runs under sidewalk. Please refer to included videos for visuals.

#### Photos

## SDFA 8 - Corliss Dr

### **Pipe Z4\_LINK\_0053**

Evaluation date/time: 6/27/2014 1:56 PM

Address/location: 67 Corliss Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	36	Type of sediment:	None
Upstream feature ID:	Z4_NODE_0161	Infiltration:	None
Downstream feature ID:	Z4_NODE_0160	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	4.8	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition

#### Notes

Outlet pipe. Sediment/debris buildup at next catch basin structure. Uncertain of pipe condition at this point, but appears it may be offset. Pipe runs under sidewalk. Please refer to included videos for visuals.

#### Photos

## SDFA 8 - Corliss Dr

### **Pipe Z4\_LINK\_0067**

Evaluation date/time: 6/27/2014 1:56 PM

Address/location: 67 Corliss Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	18	Type of sediment:	None
Upstream feature ID:	Z4_NODE_0165	Infiltration:	Stain
Downstream feature ID:	Z4_NODE_0160	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	4	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location


#### Notes

South inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

SDFA 9 - Bedford PI and Fernwood Dr

## *Area Map*



## SDFA 9 - Bedford PI and Fernwood Dr

### **Manhole Z3\_NODE\_0027**

Evaluation date/time: 6/26/2014 10:48 AM

Address/location: Bedford PI and Fernwood Dr

Weather: Dry

#### General Information

Latitude: 37.84363

Longitude: -122.121556

Property type: Public

Access: Good

Traffic: Light

Ground surface type: Asphalt

Dia./Ht. (in.): 24

Width (in.): 24

Material: Concrete

Grade/rim-invert (ft.): 7.5

Water level (%): 5

Devices: None

#### Condition Information and Ratings

Susceptible to burial/overgrowth: No

Susceptible to ponding/flooding: No

Sediment/debris depth (%): 0

Type of sediment/debris: None

Infiltration: None

VANDA Condition Rating: Level 2 - Minor Damage

Prioritization Rating: Level 2 - Good


Prioritization Rationale: Condition

Illegal dumping evidence: No

#### Notes

Poorly consolidated concrete.

#### Photos

**SDFA 9 - Bedford PI and Fernwood Dr**
**Manhole Z3\_NODE\_0027**


Sketch



Location view.



Down view of structure.



View of outlet.

**SDFA 9 - Bedford PI and Fernwood Dr*****Manhole Z3\_NODE\_0027***

View of inlets.



View of inlets.

## SDFA 9 - Bedford PI and Fernwood Dr

### **Pipe Z3\_LINK\_0019**

Evaluation date/time: 6/26/2014 10:48 AM

Address/location: Bedford PI and Fernwood Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	40	Type of sediment:	None
Upstream feature ID:	Z3_NODE_0027	Infiltration:	None
Downstream feature ID:	Z3_NODE_0025	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	7.42	VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

Outlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 9 - Bedford PI and Fernwood Dr

### **Pipe Z3\_LINK\_0020**

Evaluation date/time: 6/26/2014 10:48 AM

Address/location: Bedford PI and Fernwood Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	32	Type of sediment:	None
Upstream feature ID:	Z3_NODE_0038	Infiltration:	None
Downstream feature ID:	Z3_NODE_0027	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	7	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

West inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 9 - Bedford PI and Fernwood Dr

### ***Pipe Z3\_LINK\_0037***

Evaluation date/time: 6/26/2014 10:48 AM

Address/location: Bedford PI and Fernwood Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	28	Type of sediment:	None
Upstream feature ID:	Z3_NODE_0030	Infiltration:	Stain/Encrustation
Downstream feature ID:	Z3_NODE_0027	Obstruction/Deflection (%)	25
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	7	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

North inlet pipe. Concrete slab obstructing inlet pipe at upstream catch basin. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 9 - Bedford PI and Fernwood Dr

### ***Pipe Z3\_LINK\_0046***

Evaluation date/time: 6/26/2014 10:48 AM

Address/location: Bedford PI and Fernwood Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	18	Type of sediment:	None
Upstream feature ID:	Z3_NODE_0028	Infiltration:	None
Downstream feature ID:	Z3_NODE_0027	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	6	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location


#### Notes

Southwest inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 10 - Donald Dr and Fernwood Dr

## Area Map



## SDFA 10 - Donald Dr and Fernwood Dr

### Catch Basin Z3\_NODE\_0141

Evaluation date/time: 6/26/2014 10:04 AM

Address/location: Donald Dr and Fernwood Dr

Weather: Dry

#### General Information

Latitude: 37.844617

Longitude: -122.113059

Property type: Public

Access: Good

Traffic: Light

Ground surface type: Concrete

Dia./Ht. (in.): 36

Width (in.): 24

Material: Concrete

Grade/rim-invert (ft.): 10

Water level (%): 15

Devices: None

#### Condition Information and Ratings

Susceptible to burial/overgrowth: No

Susceptible to ponding/flooding: Yes

Sediment/debris depth (%): 10

Type of sediment/debris: Sand

Infiltration: None

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 1 - Excellent


Prioritization Rationale: Condition

Illegal dumping evidence: Yes

#### Notes

Nearby resident mentioned that a truck was seen two weeks ago dumping water into an inlet. Verify if this was town cleaning.

#### Photos




Sketch

## SDFA 10 - Donald Dr and Fernwood Dr

### ***Catch Basin Z3\_NODE\_0141***



Location view.



Down view of structure.



View of inlet.

## SDFA 10 - Donald Dr and Fernwood Dr

### **Pipe Z3\_LINK\_0133**

Evaluation date/time: 6/26/2014 10:04 AM

Address/location: Donald Dr and Fernwood Dr

Weather: Dry

#### General Information

Property type: Public

Diameter (in):

Upstream feature ID: Z3\_NODE\_0144

Downstream feature ID: Z3\_NODE\_0141

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 10

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: Stain/Encrustation

Obstruction/Deflection (%) 0

VANDA Condition Rating: Level 2 - Minor Damage

Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Condition, Location

#### Notes

North inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 10 - Donald Dr and Fernwood Dr

### **Pipe Z3\_LINK\_0141**

Evaluation date/time: 6/26/2014 10:04 AM

Address/location: Donald Dr and Fernwood Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	18	Type of sediment:	None
Upstream feature ID:	Z3_NODE_0143	Infiltration:	None
Downstream feature ID:	Z3_NODE_0141	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	3	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

Northeast inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 10 - Donald Dr and Fernwood Dr

### Pipe Z3\_LINK\_S10\_P1

Evaluation date/time: 6/26/2014 10:04 AM

Address/location: Donald Dr and Fernwood Dr

Weather: Dry

#### General Information

Property type: Private

Diameter (in):

Upstream feature ID: Z3\_NODE\_0141

Downstream feature ID:

Upstream rim-inv. (ft.): 10

Downstream rim-inv. (ft.):

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 100

Type of sediment: Silt, Vegetation

Infiltration: Stain

Obstruction/Deflection (%): 0

VANDA Condition Rating: Unknown

Prioritization Rating: Level 5 - Immediate Attention

Prioritization Rationale: Condition, Obstruction

#### Notes

Outlet pipe. The pipe is either completely blocked with sediment, or the pipe may have collapsed. Pipe runs under residence. The pipe outlet is potentially in an area where a large pool of stagnant water is located. Nearby residence said this area is prone to odor issues. Please refer to included videos for visuals.

#### Photos

## SDFA 10 - Donald Dr and Fernwood Dr

### Pipe Z3\_LINK\_0142

Evaluation date/time: 6/26/2014 10:04 AM

Address/location: Donald Dr and Fernwood Dr

Weather: Dry


#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	16	Type of sediment:	None
Upstream feature ID:	Z3_NODE_0142	Infiltration:	None
Downstream feature ID:	Z3_NODE_0141	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	3	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

Inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

**SDFA 11 - Joseph Dr and Bollinger Canyon Rd****Area Map**

## SDFA 11 - Joseph Dr and Bollinger Canyon Rd

### Manhole Z5\_NODE\_0126

Evaluation date/time: 6/27/2014 1:17 PM  
Address/location: Joseph Dr and Bollinger Canyon Rd

Weather: Dry

#### General Information

Latitude:	37.843858	Susceptible to burial/overgrowth:	No
Longitude:	-122.105694	Susceptible to ponding/flooding:	Yes
Property type:	Public	Sediment/debris depth (%):	0
Access:	Good	Type of sediment/debris	None
Traffic:	Light	Infiltration:	None
Ground surface type:	Asphalt	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	24	Prioritization Rating:	Level 2 - Good
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	6.1		
Water level (%):	0		
Devices:	None		


#### Notes

Scouring on structure bottom. Minor spalling at chimney.

#### Photos

## SDFA 11 - Joseph Dr and Bollinger Canyon Rd

## Manhole Z5\_NODE\_0126



Sketch



Location view.



Down view of structure.



View inside manhole. Spalled concrete on manhole chimney.

**SDFA 11 - Joseph Dr and Bollinger Canyon Rd*****Manhole Z5\_NODE\_0126***

View of inlet and outlet.



View of inlet.

## SDFA 11 - Joseph Dr and Bollinger Canyon Rd

### Pipe Z5\_LINK\_S11\_P1

Evaluation date/time: 6/27/2014 1:17 PM  
Address/location: Joseph Dr and Bollinger Canyon Rd

Weather: Dry

#### General Information

Property type:	Public	Sediment depth (%):	5
Diameter (in):	18	Type of sediment:	Silt, Gravel
Upstream feature ID:	Z5_NODE_0126	Infiltration:	None
Downstream feature ID:		Obstruction/Deflection (%)	15
Upstream rim-inv. (ft.):	6.1	VANDA Condition Rating:	Level 3 - Moderate Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 4 - Poor
Material:	CMP	Prioritization Rationale:	Condition, Location

#### Notes

Outlet pipe. Surface corrosion on invert of outlet pipe. Concrete slab obstructing inlet of pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 11 - Joseph Dr and Bollinger Canyon Rd

### Pipe Z5\_LINK\_S11\_P2

Evaluation date/time: 6/27/2014 1:17 PM  
Address/location: Joseph Dr and Bollinger Canyon Rd

Weather: Dry

#### General Information

Property type:	Public	Sediment depth (%):	5
Diameter (in):	18	Type of sediment:	Vegetation
Upstream feature ID:	Z5_NODE_0127	Infiltration:	None
Downstream feature ID:	Z5_NODE_0126	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 2 - Minor Damage
Downstream rim-inv. (ft.):	6	Prioritization Rating:	Level 3 - Fair
Material:	RCP	Prioritization Rationale:	Condition

#### Notes

Inlet pipe. Concrete degredation at inlet of pipe. Please refer to included videos for visuals.

#### Photos

## SDFA 11 - Joseph Dr and Bollinger Canyon Rd

### Pipe Z5\_LINK\_S11\_P3

Evaluation date/time: 6/27/2014 1:17 PM  
Address/location: Joseph Dr and Bollinger Canyon Rd

Weather: Dry

#### General Information

Property type:	Public	Sediment depth (%):	0
Diameter (in):	18	Type of sediment:	None
Upstream feature ID:	Z5_NODE_0130	Infiltration:	None
Downstream feature ID:	Z5_NODE_0126	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 4 - Severe/Significant Damage
Downstream rim-inv. (ft.):	5.6	Prioritization Rating:	Level 5 - Immediate Attention
Material:	RCP	Prioritization Rationale:	Condition, Location


#### Notes

Invert missing on inlet pipe. Void visible. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 12 - Del Rio Way

## Area Map



## SDFA 12 - Del Rio Way

### ***Catch Basin Z5\_NODE\_0056***

Evaluation date/time: 6/27/2014 12:41 PM

Address/location: Del Rio Way

Weather: Dry

#### General Information

Latitude: 37.842036

Longitude: -122.117454

Property type: Public

Access: Good

Traffic: None

Ground surface type: Asphalt

Dia./Ht. (in.): 36

Width (in.): 24

Material: Concrete

Grade/rim-invert (ft.): 3.75

Water level (%): 0

Devices: None

#### Condition Information and Ratings

Susceptible to burial/overgrowth: No

Susceptible to ponding/flooding: No

Sediment/debris depth (%): 5

Type of sediment/debris: Silt, Gravel

Infiltration: None

VANDA Condition Rating: Level 2 - Minor Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition

Illegal dumping evidence: No


#### Notes

Scouring at inlet. Exposed aggregate.

#### Photos

**SDFA 12 - Del Rio Way**
**Catch Basin Z5\_NODE\_0056**


Sketch



Location view.



Down view of structure.



View of outlet.

**SDFA 12 - Del Rio Way****Catch Basin Z5\_NODE\_0056**

View of inlet. Scouring on structure floor.

## SDFA 12 - Del Rio Way

### Pipe Z5\_LINK\_S12\_P1

Evaluation date/time: 6/27/2014 12:41 PM

Address/location: Del Rio Way

Weather: Dry

#### General Information

Property type:	Public	Sediment depth (%):	0
Diameter (in):	18	Type of sediment:	None
Upstream feature ID:	Z5_NODE_0056	Infiltration:	None
Downstream feature ID:	Z5_NODE_0050	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	3.75	VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

Outlet pipe. Please refer to included videos for visuals.

#### Photos

## SDFA 12 - Del Rio Way

### Pipe Z5\_LINK\_S12\_P2

Evaluation date/time: 6/27/2014 12:41 PM

Address/location: Del Rio Way

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 16

Upstream feature ID:

Downstream feature ID: Z5\_NODE\_0056

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 3.66

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 30

Type of sediment: Silt, Rock

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 1 - No Damage


Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Sediment

#### Notes

Inlet pipe. Scouring at pipe inlet. Please refer to included videos for visuals.

#### Photos

**SDFA 13 - Country Club Dr and School St****Area Map**

## SDFA 13 - Country Club Dr and School St

### Manhole Z6\_NODE\_0039

Evaluation date/time: 6/26/2014 9:18 AM

Address/location: Country Club Dr and School St

Weather: Dry


#### General Information

Latitude:	37.834221	Susceptible to burial/overgrowth:	No
Longitude:	-122.131705	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	0
Access:	Good	Type of sediment/debris	None
Traffic:	Light	Infiltration:	None
Ground surface type:	Concrete	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	24	Prioritization Rating:	Level 2 - Good
Width (in.):		Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	4.7		
Water level (%):	0		
Devices:	None		

#### Notes

Thin metal lining over chimney, possibly served as a construction form. Concrete degradation at pipe connections.

#### Photos

**SDFA 13 - Country Club Dr and School St**
***Manhole Z6\_NODE\_0039***


Sketch



Location view.



Location view.



View of outlet.

**SDFA 13 - Country Club Dr and School St*****Manhole Z6\_NODE\_0039***

View of inlet.



Delaminating metal lining on manhole chimney.

## SDFA 13 - Country Club Dr and School St

### Pipe Z6\_LINK\_S13\_P1

Evaluation date/time: 6/26/2014 9:18 AM  
Address/location: Country Club Dr and School St

Weather: Dry

#### General Information

Property type:	Public	Sediment depth (%):	5
Diameter (in):	26	Type of sediment:	Silt, Vegetation
Upstream feature ID:	Z6_NODE_0040	Infiltration:	None
Downstream feature ID:	Z6_NODE_0039	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	4.7	Prioritization Rating:	Level 1 - Excellent
Material:	RCP	Prioritization Rationale:	Condition

#### Notes

Outlet pipe. Pipe runs under sidewalk. Please refer to included videos for visuals.

#### Photos

## SDFA 13 - Country Club Dr and School St

### Pipe Z6\_LINK\_S13\_P2

Evaluation date/time: 6/26/2014 9:18 AM  
Address/location: Country Club Dr and School St

Weather: Dry

#### General Information

Property type:	Public	Sediment depth (%):	0
Diameter (in):	26	Type of sediment:	None
Upstream feature ID:	Z6_NODE_0039	Infiltration:	None
Downstream feature ID:	Z6_NODE_0038	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	4.7	VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location


#### Notes

Inlet pipe. Pipe runs under sidewalk and roadway. Please refer to included videos for visuals.

#### Photos

SDFA 14 - Country Club Dr

## *Area Map*



## SDFA 14 - Country Club Dr

### ***Catch Basin Z7\_NODE\_0089***

Evaluation date/time: 6/27/2014 3:09 PM

Address/location: Country Club Dr

Weather: Dry


#### General Information

Latitude:	37.832698	Susceptible to burial/overgrowth:	No
Longitude:	-122.1257	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	0
Access:	Good	Type of sediment/debris	None
Traffic:	Light	Infiltration:	None
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 1 - No Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 1 - Excellent
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	6		
Water level (%):	5		
Devices:	None		

#### Notes

Good condition.

#### Photos

**SDFA 14 - Country Club Dr**
**Catch Basin Z7\_NODE\_0089**


Sketch



Down view of structure.



View of inlet and outlet.



View of inlet.

## SDFA 14 - Country Club Dr

### Pipe Z7\_LINK\_S14\_P1

Evaluation date/time: 6/27/2014 3:09 PM

Address/location: Country Club Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	30	Type of sediment:	None
Upstream feature ID:	Z7_NODE_0089	Infiltration:	None
Downstream feature ID:	Z7_NODE_0087	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	6	VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

Outlet pipe. Please refer to included videos for visuals.

#### Photos

## SDFA 14 - Country Club Dr

### Pipe Z7\_LINK\_S14\_P2

Evaluation date/time: 6/27/2014 3:09 PM

Address/location: Country Club Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	24	Type of sediment:	None
Upstream feature ID:	Z7_NODE_0099	Infiltration:	None
Downstream feature ID:	Z7_NODE_0089	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	5.6	Prioritization Rating:	Level 2 - Good
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

Inlet pipe. Please refer to included videos for visuals.

#### Photos

## SDFA 14 - Country Club Dr

### Pipe Z7\_LINK\_S14\_P3

Evaluation date/time: 6/27/2014 3:09 PM

Address/location: Country Club Dr

Weather: Dry

#### General Information

Property type: Private

Diameter (in): 18

Upstream feature ID: Z7\_NODE\_0090

Downstream feature ID: Z7\_NODE\_0089

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 5.4

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%) 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location

#### Notes

Inlet pipe. Please refer to included videos for visuals.

#### Photos

**SDFA 15 - Rimer Dr*****Area Map***

## SDFA 15 - Rimer Dr

### ***Catch Basin Z7\_NODE\_S15***

Evaluation date/time: 6/26/2014 8:17 AM

Address/location: Rimer Dr

Weather: Dry

#### General Information

Latitude: 37.82257

Longitude: -122.129302

Property type: Public

Access: Good

Traffic: Light

Ground surface type: Concrete

Dia./Ht. (in.): 36

Width (in.): 24

Material: Concrete

Grade/rim-invert (ft.): 8

Water level (%): 0

Devices: None

#### Condition Information and Ratings

Susceptible to burial/overgrowth: No

Susceptible to ponding/flooding: No

Sediment/debris depth (%): 5

Type of sediment/debris Silt, Vegetation

Infiltration: None

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 1 - Excellent

Prioritization Rationale: Condition

Illegal dumping evidence: No


#### Notes

Good condition.


#### Photos

## SDFA 15 - Rimer Dr

## Catch Basin Z7\_NODE\_S15



Sketch



Location view.



Down view of structure.

## SDFA 15 - Rimer Dr

### Pipe Z7\_LINK\_S15\_P1

Evaluation date/time: 6/26/2014 8:17 AM

Address/location: Rimer Dr

Weather: Dry

#### General Information

Property type: Private

Diameter (in): 24

Upstream feature ID: Z7\_NODE\_S15

Downstream feature ID:

Upstream rim-inv. (ft.): 8

Downstream rim-inv. (ft.):

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 20

Type of sediment: Silt, Rock, Vegetation

Infiltration: Stain

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Sediment, Location

#### Notes

Outlet pipe. Pipe runs under residence. Please refer to included videos for visuals.

#### Photos

## SDFA 15 - Rimer Dr

### Pipe Z7\_LINK\_S15\_P2

Evaluation date/time: 6/26/2014 8:17 AM

Address/location: Rimer Dr

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 18

Upstream feature ID:

Downstream feature ID: Z7\_NODE\_S15

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 8

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%): 25

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Obstruction

#### Notes

Northeast inlet pipe. Pipe appears to be obstructed by a board of unknown material. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

**SDFA 15 - Rimer Dr****Pipe Z7\_LINK\_S15\_P3**

Evaluation date/time: 6/26/2014 8:17 AM

Address/location: Rimer Dr

Weather: Dry

General Information

Property type: Public

Diameter (in): 18

Upstream feature ID:

Downstream feature ID: Z7\_NODE\_S15

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 8

Material: RCP

Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location


Notes

East inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

Photos

## SDFA 16 - Deerfield Dr

## Area Map



## SDFA 16 - Deerfield Dr

### ***Catch Basin Z7\_NODE\_0158***

Evaluation date/time: 6/27/2014 8:57 AM

Address/location: Deerfield Dr

Weather: Dry


#### General Information

Latitude:	37.815815	Susceptible to burial/overgrowth:	No
Longitude:	-122.124003	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	0
Access:	Good	Type of sediment/debris	None
Traffic:	None	Infiltration:	Weeper
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 1 - No Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 2 - Good
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	6.8		
Water level (%):	5		
Devices:	None		

#### Notes

Infiltration stains on catch basin structure walls.

#### Photos

**SDFA 16 - Deerfield Dr**
**Catch Basin Z7\_NODE\_0158**


Sketch



Location view.



View of outlet.



Down view of structure. Water infiltration staining.

## SDFA 16 - Deerfield Dr

## Catch Basin Z7\_NODE\_0158



Down view of structure. Water infiltration staining.

## SDFA 16 - Deerfield Dr

### Pipe Z7\_LINK\_S16\_P1

Evaluation date/time: 6/27/2014 8:57 AM

Address/location: Deerfield Dr

Weather: Dry

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	42	Type of sediment:	None
Upstream feature ID:	Z7_NODE_0158	Infiltration:	None
Downstream feature ID:	Z7_NODE_0157	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	6.8	VANDA Condition Rating:	Level 2 - Minor Damage
Downstream rim-inv. (ft.):		Prioritization Rating:	Level 3 - Fair
Material:	RCP	Prioritization Rationale:	Condition, Location

#### Notes

Outlet pipe. Pipe runs under roadway. Concrete degradation at invert. Please refer to included videos for visuals.

#### Photos

## SDFA 16 - Deerfield Dr

### Pipe Z7\_LINK\_S16\_P2

Evaluation date/time: 6/27/2014 8:57 AM

Address/location: Deerfield Dr

Weather: Dry

#### General Information

Property type: Private

Diameter (in): 36

Upstream feature ID: Z7\_NODE\_0159

Downstream feature ID: Z7\_NODE\_0158

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 5.6

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 2 - Minor Damage

Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Condition, Location


#### Notes

Inlet pipe. Pipe runs under residence. Concrete degradation at invert. Please refer to included videos for visuals.

#### Photos

## SDFA 17 - Deerfield Dr and Stoneridge Pl

## Area Map



## SDFA 17 - Deerfield Dr and Stoneridge PI

### ***Catch Basin Z7\_NODE\_0203***

Evaluation date/time: 6/27/2014 8:22 AM

Address/location: Deerfield Dr and Stonefield PI

Weather: Dry

#### General Information

Latitude:	37.813634	Susceptible to burial/overgrowth:	No
Longitude:	-122.118609	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	5
Access:	Good	Type of sediment/debris	Vegetation
Traffic:	Light	Infiltration:	None
Ground surface type:	Asphalt, Concrete	VANDA Condition Rating:	Level 1 - No Damage
Dia./Ht. (in.):	36	Prioritization Rating:	Level 1 - Excellent
Width (in.):	24	Prioritization Rationale:	Condition
Material:	Concrete	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	11		
Water level (%):	0		
Devices:	None		


#### Notes

Minor build up of leaves.

#### Photos

## SDFA 17 - Deerfield Dr and Stoneridge Pl

### Catch Basin Z7\_NODE\_0203



Sketch



Location view.



Location view.



Down view of structure.

**SDFA 17 - Deerfield Dr and Stoneridge Pl*****Catch Basin Z7\_NODE\_0203***

Down view of structure.

## SDFA 17 - Deerfield Dr and Stoneridge PI

### Pipe Z7\_LINK\_S17\_P1

Evaluation date/time: 6/27/2014 8:22 AM

Address/location: Deerfield Dr and Stonefield PI

Weather: Dry

#### General Information

Property type: Public

Diameter (in):

Upstream feature ID: Z7\_NODE\_0203

Downstream feature ID: Z7\_NODE\_0204

Upstream rim-inv. (ft.): 11

Downstream rim-inv. (ft.):

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location

#### Notes

Outlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

## SDFA 17 - Deerfield Dr and Stoneridge PI

### Pipe Z7\_LINK\_S17\_P2

Evaluation date/time: 6/27/2014 8:22 AM

Address/location: Deerfield Dr and Stonefield PI

Weather: Dry

#### General Information

Property type: Public

Diameter (in):

Upstream feature ID: Z7\_NODE\_0202

Downstream feature ID: Z7\_NODE\_0203

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 11

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location

#### Notes

Inlet pipe. Pipe runs under roadway. Please refer to included videos for visuals.

#### Photos

**SDFA 18 - Rheem Blvd and Center St*****Area Map***

## SDFA 18 - Rheem Blvd and Center St

### ***Catch Basin Z3\_NODE\_S18***

Evaluation date/time: 10/14/14 9:00 AM  
Address/location: Rheem Blvd and Center St  
  
Weather: Dry

#### General Information

Latitude: Susceptible to burial/overgrowth: No  
Longitude: Susceptible to ponding/flooding: No  
Property type: Public Sediment/debris depth (%): 0  
Access: Good Type of sediment/debris: None  
Traffic: Heavy Infiltration: Weeper  
Ground surface type: Asphalt, Concrete VANDA Condition Rating: Level 1 - No Damage  
Dia./Ht. (in.): 36 Prioritization Rating: Level 2 - Good  
Width (in.): 36 Prioritization Rationale: Condition  
Material: Concrete Illegal dumping evidence: No  
Grade/rim-invert (ft.): 22.6  
Water level (%): 5  
Devices: Filter

#### Condition Information and Ratings

#### Notes

Filter removed in order to access for assessment. Opening cut in crown of CMP (2 ft. x 2 ft.). Weeper infiltration at 14 ft. from grade.

#### Photos



Catch Basin Topside (1)

**SDFA 18 - Rheem Blvd and Center St****Catch Basin Z3\_NODE\_S18**

Catch Basin Topside (2)



Catch Basin Topside (3)



Catch Basin Topside (4)



Catch Basin Topside (5)



Catch Basin Down Catch Basin (1)

## SDFA 18 - Rheem Blvd and Center St

### ***Catch Basin Z3\_NODE\_S18***



Catch Basin Down Catch Basin (2)



Catch Basin Down Catch Basin (3)



Catch Basin Pointing Downstream



Catch Basin 14' Infiltration

## SDFA 18 - Rheem Blvd and Center St

### ***Catch Basin Z3\_LINK\_S18\_P1***

Evaluation date/time: 10/14/14 9:00 AM

Address/location: Rheem Blvd and Center St

Weather: Dry

#### General Information

Property type: Public  
 Diameter (in): 96  
 Upstream feature ID: Z3\_NODE\_S18  
 Downstream feature ID:  
 Upstream rim-inv. (ft.): 22.6  
 Downstream rim-inv. (ft.):  
 Material: CMP

#### Condition Information and Ratings

Sediment depth (%): 5  
 Type of sediment: Silt, Vegetation  
 Infiltration: Stain/Encrustation  
 Obstruction/Deflection (%): 0  
 VANDA Condition Rating: Level 4 - Severe/Significant Damage  
 Prioritization Rating: Level 5 - Immediate Attention  
 Prioritization Rationale: Condition, Location


#### Notes

Outlet pipe. Pipe runs under roadway, parking lot, and commercial buildings. Multiple points of infiltration/encrustation. Significant/severe corrosion at invert. Perforations in invert with voids visible. Voids are about 3 in. deep. Pipe buckled/deformed in various places by approx. 10 percent. Portion of pipe invert has been rehabilitated with a concrete overlay.

#### Photos



Downstream 3' Infiltration (1)



Downstream 5' Encrustation

## SDFA 18 - Rheem Blvd and Center St

### Catch Basin Z3\_LINK\_S18\_P1



Downstream 10' Infiltration



Downstream 13' Holes Void Visible




Downstream 20' Deformed (IMG\_2580)



Downstream 20' Deformed (IMG\_2583)



Downstream 20' Holes Void Visible



Downstream 40' Patch Repair

## SDFA 18 - Rheem Blvd and Center St


### Catch Basin Z3\_LINK\_S18\_P1



Downstream 77' Defective Pipe Size Change (1)




Downstream 77' Defective Pipe Size Change (2)



Downstream 77' Defective Pipe Size Change (3)



Downstream 186' Deformed (IMG\_2636)



Downstream 207' Deformed (1)



Downstream 207' Deformed (2)

## SDFA 18 - Rheem Blvd and Center St

### ***Catch Basin Z3\_LINK\_S18\_P1***



Downstream 270' Deformed (IMG\_2644)



Downstream 337' Deformed



Downstream 411' Hole Void Visible  
(IMG\_2654)

## SDFA 18 - Rheem Blvd and Center St

### ***Catch Basin Z3\_LINK\_S18\_P2***

Evaluation date/time: 10/14/14 9:00 AM

Address/location: Rheem Blvd and Center St

Weather: Dry

#### General Information

Property type: Public

Diameter (in): 96

Upstream feature ID:

Downstream feature ID: Z3\_NODE\_S18

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 22.6

Material: CMP

#### Condition Information and Ratings

Sediment depth (%): 5

Type of sediment: Silt, Vegetation

Infiltration: Stain/Encrustation

Obstruction/Deflection (%)

0

VANDA Condition Rating: Level 4 - Severe/Significant Damage

Prioritization Rating: Level 5 - Immediate Attention

Prioritization Rationale: Condition, Location


#### Notes

Inlet pipe. Pipe runs under roadway, parking lot, and commercial buildings. Multiple points of infiltration/encrustation. Significant/severe corrosion at invert. Perforations in invert with voids visible. Voids are between 4 in. to 10 in. deep. Hole with void visible on east pipe wall near assessment entry point. Pipe changes from CMP to RCP of same diameter. Connection appears to be of sheet metal and wood boards. RCP is in good condition with some infiltration staining/encrustation. Mortar missing at RCP joints (1 in. gap between pipe segments). Evidence of vandalism/unauthorized access warrants additional safety concerns.

#### Photos



Upstream 2' Infiltration



Upstream 2' Infiltration (2)

## SDFA 18 - Rheem Blvd and Center St

### ***Catch Basin Z3\_LINK\_S18\_P2***



Upstream Infiltration (4)



Upstream 8' Broken Pipe (1)



Upstream 8' Broken Pipe (2)



Upstream 8' Broken Pipe (3)




Upstream 8' Hole Void Visible (1)



Upstream 8' Hole Void Visible (2)

## SDFA 18 - Rheem Blvd and Center St

### Catch Basin Z3\_LINK\_S18\_P2



Upstream 10' Infiltration



Upstream 15' Hole Void Visible



Upstream 15' Holes



Upstream 18' Deformation



Upstream 21' Open Joint



Upstream 44' Hole Void Visible

## SDFA 18 - Rheem Blvd and Center St

### Catch Basin Z3\_LINK\_S18\_P2



Upstream 44' Staining



Upstream 45.5' Defective Tap Connection (1)



Upstream 45.5' Defective Tap Connection (4)



Upstream 46' Defective Pipe Material Change (1)



Upstream 46' Defective Pipe Material Change (2)



Upstream 46' Defective Pipe Material Change (3)

**SDFA 18 - Rheem Blvd and Center St****Catch Basin Z3\_LINK\_S18\_P2**

Upstream 46' Defective Pipe Material Change (4)



Upstream 55' Longitudinal Cracks at Joint (1)



Upstream 55' Longitudinal Cracks at Joint (2)



Upstream 65' Missing Mortar (1)



Upstream 65' Missing Mortar (2)



Upstream 73' Infiltration Stains

## SDFA 18 - Rheem Blvd and Center St

### ***Catch Basin Z3\_LINK\_S18\_P2***



Upstream 73' Longitudinal Cracks, Staining (1)



Upstream 81' Longitudinal Cracks, Staining (3)

**SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr*****Area Map***

## SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr

### Culvert Z5\_NODE\_S19\_N1

Evaluation date/time: 11/20/2014 9:21 AM  
Address/location: Bollinger Canyon Rd and Valley Hill Dr

Weather: Damp

#### General Information

Latitude:	37.838116	Susceptible to burial/overgrowth:	No
Longitude:	-122.097931	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	10
Access:	Fair	Type of sediment/debris	Silt, Sand, Gravel
Traffic:	Light	Infiltration:	None
Ground surface type:	Asphalt, Grass/Dirt	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	6	Prioritization Rating:	Level 3 - Fair
Width (in.):	13	Prioritization Rationale:	Condition, Location
Material:	CMP	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	10		
Water level (%):	0		
Devices:	Headwall		

#### Notes

Outlet to culvert. Minor to moderate surface corrosion at base of pipe wall. Nearby CMP outlet.

#### Photos

## SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr

### Culvert Z5\_NODE\_S19\_N1



Location view.



View of outlet area.



View of outlet.



View of outlet.



View of nearby outlet.



View downstream

## SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr

### Culvert Z5\_NODE\_S19\_N1



View of nearby outlet.



View inside nearby outlet.



View inside nearby outlet.

## SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr

### Culvert Z5\_LINK\_S19

Evaluation date/time: 11/20/2014 9:21 AM

Address/location: Bollinger Canyon Rd and Valley Hill Dr

Weather: Damp


#### General Information

Property type:	Public	Sediment depth (%):	10
Diameter (in):	6	Type of sediment:	Silt, Sand, Gravel
Upstream feature ID:	Z5_NODE_S19	Infiltration:	None
Downstream feature ID:	Z5_NODE_S19	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	10	VANDA Condition Rating:	Level 2 - Minor Damage
Downstream rim-inv. (ft.):	10	Prioritization Rating:	Level 3 - Fair
Material:	CMP	Prioritization Rationale:	Condition, Location

#### Notes

Pipe runs under roadway. Accessed from outlet and proceeded towards inlet. Minor to moderate surface corrosion at base of pipe wall.

#### Photos



Sketch



Corrosion on pipe wall.

## SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr

### Culvert Z5\_LINK\_S19



View inside pipe from outlet.



View of pipe wall from outlet.



Corrosion on pipe wall.



View inside pipe from outlet.



Corrosion on pipe wall



View of pipe wall from outlet.

## SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr

### Culvert Z5\_NODE\_S19\_N2

Evaluation date/time: 11/20/2014 9:21 AM  
Address/location: Bollinger Canyon Rd and Valley Hill Dr

Weather: Damp

#### General Information

Latitude:		Susceptible to burial/overgrowth:	No
Longitude:		Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	10
Access:	Fair	Type of sediment/debris	Silt, Sand, Gravel
Traffic:	Light	Infiltration:	None
Ground surface type:	Asphalt, Grass/Dirt	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	6	Prioritization Rating:	Level 3 - Fair
Width (in.):	13	Prioritization Rationale:	Condition, Location
Material:	CMP	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	10		
Water level (%):	0		
Devices:	Headwall		

#### Notes

Inlet to culvert. Minor to moderate surface corrosion at base of pipe wall.

#### Photos

## SDFA 19 - Bollinger Canyon Rd and Valley Hill Dr

### Culvert Z5\_NODE\_S19\_N2



Location view.



View of inlet area.



View of inlet.



View upstream.

**SDFA 20 - 1528 St Marys Rd*****Area Map***

## SDFA 20 - 1528 St Marys Rd

### **Culvert Z5\_NODE\_S20\_N1**

Evaluation date/time: 11/20/2014 10:02 AM

Address/location: 1528 St Marys Rd

Weather: Damp

#### General Information

Latitude:	37.841497	Susceptible to burial/overgrowth:	Yes
Longitude:	-122.121683	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	0
Access:	Fair	Type of sediment/debris	None
Traffic:	Heavy	Infiltration:	None
Ground surface type:	Asphalt, Grass/Dirt	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	50	Prioritization Rating:	Level 5 - Immediate Attention
Width (in.):		Prioritization Rationale:	Safety
Material:	CMP	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	10		
Water level (%):	0		
Devices:	Debris/Trash Rack		

#### Notes

Heavy vegetation surrounding outlet. Buildup of sediment at outlet. Outlet is 48 in. while inlet is 50 in. indicating possible pipe deformation.

#### Photos

## SDFA 20 - 1528 St Marys Rd

### Culvert Z5\_NODE\_S20\_N1



View of downstream area.



View of outlet.



View of outlet.



View of outlet.



View downstream.



View of downstream area.

## SDFA 20 - 1528 St Marys Rd

### Culvert Z5\_LINK\_S20

Evaluation date/time: 11/20/2014 10:02 AM

Address/location: 1528 St Marys Rd

Weather: Damp

#### General Information

Property type: Public

Diameter (in): 50

Upstream feature ID: Z5\_NODE\_S20

Downstream feature ID: Z5\_NODE\_S20

Upstream rim-inv. (ft.): 5

Downstream rim-inv. (ft.): 10

Material: CMP

#### Condition Information and Ratings

Sediment depth (%): 55

Type of sediment: Silt, Sand, Gravel

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 2 - Minor Damage


Prioritization Rating: Level 5 - Immediate Attention

Prioritization Rationale: Sediment

#### Notes

Pipe appears to slope down, then bend into a flat horizontal section. This slope change could be the reason for the buildup of sediment at the outlet. Outlet is 48 in. while inlet is 50 in. indicating possible pipe deformation.

#### Photos



Sketch



View inside pipe from inlet.

**SDFA 20 - 1528 St Marys Rd**

**Culvert Z5\_LINK\_S20**



View inside pipe from outlet.



View of pipe wall from outlet.



View inside pipe from outlet.



View inside pipe from outlet.

## SDFA 20 - 1528 St Marys Rd

### **Culvert Z5\_NODE\_S20\_N2**

Evaluation date/time: 11/20/2014 10:02 AM

Address/location: 1528 St Marys Rd

Weather: Damp

#### General Information

Latitude:

Susceptible to burial/overgrowth: Yes

Longitude:

Susceptible to ponding/flooding: No

Property type:

Public

Sediment/debris depth (%): 55

Access:

Fair

Type of sediment/debris Silt, Sand, Gravel

Traffic:

Heavy

Infiltration: None

Ground surface type:

Asphalt, Grass/Dirt

VANDA Condition Rating: Level 2 - Minor Damage

Dia./Ht. (in.):

50

Prioritization Rating: Level 5 - Immediate Attention

Width (in.):

Prioritization Rationale: Sediment

Material:

CMP

Illegal dumping evidence: No

Grade/rim-invert (ft.):

10

Water level (%):

0

Devices: Debris/Trash Rack

#### Notes

Area surrounding inlet appears unstable. Near a mailbox and could pose a safety concern if someone fell. Possibly a debris/trash rack at inlet. Outlet is 48 in. while inlet is 50 in. indicating possible pipe deformation.

#### Photos

## SDFA 20 - 1528 St Marys Rd

### Culvert Z5\_NODE\_S20\_N2



Location view.



View of inlet area.



View of inlet.



View of inlet.



View of inlet. Mailbox to right.



View of inlet.

**SDFA 20 - 1528 St Marys Rd*****Culvert Z5\_NODE\_S20\_N2***

View of inlet area.

**SDFA 21 - 423 Canyon Rd*****Area Map***

## SDFA 21 - 423 Canyon Rd

### **Culvert Z6\_NODE\_S21\_N1**

Evaluation date/time: 11/20/2014 11:26 AM

Address/location: 423 Canyon Rd

Weather: Light Rain

#### General Information

Latitude: 37.822537

Longitude: -122.133379

Property type: Public

Access: Good

Traffic: Light

Ground surface type: Asphalt, Grass/Dirt

Dia./Ht. (in.): 10

Width (in.): 15

Material: CMP

Grade/rim-invert (ft.): 5

Water level (%): 10

Devices: None

#### Condition Information and Ratings

Susceptible to burial/overgrowth: Yes

Susceptible to ponding/flooding: No

Sediment/debris depth (%): 20

Type of sediment/debris: Silt, Vegetation

Infiltration: None

VANDA Condition Rating: Level 4 - Severe/Significant Damage

Prioritization Rating: Level 5 - Immediate Attention

Prioritization Rationale: Condition, Location

Illegal dumping evidence: No

#### Notes

Outlet to culvert. Significant/severe corrosion with lower half of pipe missing. Significant scouring of pipe bedding.

#### Photos

## SDFA 21 - 423 Canyon Rd

### ***Culvert Z6\_NODE\_S21\_N1***



Location view.



View of outlet area.



View downstream.

**SDFA 21 - 423 Canyon Rd**
**Culvert Z6\_LINK\_S21**

Evaluation date/time: 11/20/2014 11:26 AM

Address/location: 423 Canyon Rd


Weather: Light Rain

**General Information**

Property type:	Public	Sediment depth (%):	20
Diameter (in):	10	Type of sediment:	Silt, Vegetation
Upstream feature ID:	Z6_NODE_S21	Infiltration:	None
Downstream feature ID:	Z6_NODE_S21	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	4	VANDA Condition Rating:	Level 4 - Severe/Significant Damage
Downstream rim-inv. (ft.):	5	Prioritization Rating:	Level 5 - Immediate Attention
Material:	CMP	Prioritization Rationale:	Condition, Location

**Notes**

Pipe runs under roadway. Significant/severe corrosion with lower half of pipe missing. Significant scouring of pipe bedding.

**Photos**


Sketch



View inside pipe from inlet.

**SDFA 21 - 423 Canyon Rd****Culvert Z6\_LINK\_S21**

View inside pipe from inlet.



View inside pipe from outlet.



View inside pipe from outlet.



View of pipe wall at outlet.

## SDFA 21 - 423 Canyon Rd

### **Culvert Z6\_NODE\_S21\_N2**

Evaluation date/time: 11/20/2014 11:26 AM

Address/location: 423 Canyon Rd

Weather: Light Rain

#### General Information

Latitude:

Longitude:

Property type: Public

Access: Good

Traffic: Light

Ground surface type: Asphalt, Grass/Dirt

Dia./Ht. (in.): 10

Width (in.): 15

Material: CMP

Grade/rim-invert (ft.): 5

Water level (%): 10

Devices: None

#### Condition Information and Ratings

Susceptible to burial/overgrowth: Yes

Susceptible to ponding/flooding: No

Sediment/debris depth (%): 20

Type of sediment/debris: Silt, Vegetation

Infiltration: None

VANDA Condition Rating: Level 4 - Severe/Significant Damage

Prioritization Rating: Level 5 - Immediate Attention

Prioritization Rationale: Condition, Location

Illegal dumping evidence: No

#### Notes

Inlet to culvert. Significant/severe corrosion with lower half of pipe missing. Significant scouring of pipe bedding.

#### Photos

## SDFA 21 - 423 Canyon Rd

### Culvert Z6\_NODE\_S21\_N2



Location view.



View of inlet area.



View of inlet.



View of exterior pipe crown at inlet.



Minor perforations in pipe crown at inlet.

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### *Area Map*

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_NODE\_S22\_N1

Evaluation date/time: 11/20/2014 12:03 PM

Address/location: Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

Weather: Light Rain

#### General Information

Latitude:	37.815178	Susceptible to burial/overgrowth:	No
Longitude:	-122.116237	Susceptible to ponding/flooding:	No
Property type:	Public	Sediment/debris depth (%):	0
Access:	Fair	Type of sediment/debris	None
Traffic:	Light	Infiltration:	Stain
Ground surface type:	Grass/Dirt	VANDA Condition Rating:	Level 2 - Minor Damage
Dia./Ht. (in.):	80	Prioritization Rating:	Level 2 - Good
Width (in.):		Prioritization Rationale:	Condition
Material:	CMP	Illegal dumping evidence:	No
Grade/rim-invert (ft.):	15		
Water level (%):	5		
Devices:	Headwall, Wingwall(s)		

#### Notes

Outlet to culvert. There is a 16-in. RCP near the outlet. Evidence of vandalism/unauthorized access warrants safety concerns.

#### Photos

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_NODE\_S22\_N1



Location view.



Location view.



View of outlet area.



View of outlet.



View of outlet.



View of outlet.

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_NODE\_S22\_N1



View downstream.



View of nearby 16-in. RCP outlet.



View inside nearby 16-in. RCP outlet.



Offset joint inside nearby 16-in. RCP outlet.



View of outlet.

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_LINK\_S22

Evaluation date/time: 11/20/2014 12:03 PM

Address/location: Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

Weather: Light Rain


#### General Information

Property type:	Public	Sediment depth (%):	0
Diameter (in):	80	Type of sediment:	None
Upstream feature ID:	Z7_NODE_S22	Infiltration:	Stain
Downstream feature ID:	Z7_NODE_S22	Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):	15	VANDA Condition Rating:	Level 2 - Minor Damage
Downstream rim-inv. (ft.):	15	Prioritization Rating:	Level 3 - Fair
Material:	CMP	Prioritization Rationale:	Condition, Location

#### Notes

Pipe runs under roadway. The pipe is in overall good condition. There is some infiltration staining/encrustation. There is one hole in the pipe wall near the bend, but there is another layer of metal material behind the hole. The invert has a concrete formed channel. There is a coating on the upstream portion of the pipe. There is some minor surface corrosion near the concrete invert.

#### Photos



Sketch



View inside pipe from outlet.

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_LINK\_S22



View of invert at outlet.



View inside pipe from outlet.



View outside pipe from outlet.



Joint seal.



Infiltration staining.



View inside pipe heading from outlet to inlet.

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_LINK\_S22



View of encrustation on pipe wall.




Hole in pipe wall.



View inside hole in pipe wall. Appears to be another layer of metal material within the hole.



View inside hole in pipe wall. Appears to be another layer of metal material within the hole.



View of pipe bend before inlet.



View inside pipe towards inlet.

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_LINK\_S22



View inside pipe towards outlet.



View of pipe wall at bend.



View of pipe wall at inlet.

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### **Culvert Z7\_NODE\_S22\_N2**

Evaluation date/time: 11/20/2014 12:03 PM

Address/location: Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

Weather: Light Rain

#### General Information

Latitude:

Longitude:

Property type: Public

Access: Fair

Traffic: Light

Ground surface type: Grass/Dirt

Dia./Ht. (in.): 80

Width (in.):

Material: CMP

Grade/rim-invert (ft.): 15

Water level (%): 5

Devices: Headwall,

Wingwall(s)

#### Condition Information and Ratings

Susceptible to burial/overgrowth: No

Susceptible to ponding/flooding: No

Sediment/debris depth (%): 0

Type of sediment/debris: None

Infiltration: Stain

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Safety

Illegal dumping evidence: No

#### Notes

Inlet to culvert. There is a 16-in. RCP and a 30-in. CMP near the inlet.

#### Photos

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_NODE\_S22\_N2



View of inlet.



View of inlet area.



View upstream.



View of inlet area.




View of nearby 16-in. RCP outlet.



View inside nearby 16-in. RCP outlet.

## SDFA 22 - Moraga Creek crossing near Camino Pablo and Sanders Ranch Rd

### Culvert Z7\_NODE\_S22\_N2



View inside nearby 16-in. RCP outlet.



View of nearby 30-in. CMP outlet.



View inside nearby 30-in. CMP outlet.



View of invert of nearby 30-in. CMP outlet.




View of inlet.



Location view.

## SDFA 23 - Larch Ave and Ross Dr

## Area Map



## SDFA 23 - Larch Ave and Ross Dr

### Culvert Z7\_NODE\_0022

Evaluation date/time: 11/20/2014 2:03 PM  
 Address/location: Larch Ave and Ross Dr

Weather: Damp

#### General Information

Latitude: 37.828569  
 Longitude: -122.128301  
 Property type: Public  
 Access: Good  
 Traffic: Light  
 Ground surface type: Asphalt, Concrete  
 Dia./Ht. (in.): 24  
 Width (in.):  
 Material: RCP  
 Grade/rim-invert (ft.): 4.7  
 Water level (%): 10  
 Devices: Debris/Trash Rack


#### Condition Information and Ratings

Susceptible to burial/overgrowth: No  
 Susceptible to ponding/flooding: Yes  
 Sediment/debris depth (%): 5  
 Type of sediment/debris: Silt, Vegetation  
 Infiltration: None  
 VANDA Condition Rating: Level 1 - No Damage  
 Prioritization Rating: Level 2 - Good  
 Prioritization Rationale: Condition, Location  
 Illegal dumping evidence: No

#### Notes

Good condition.

#### Photos



Sketch



Location view.

## SDFA 23 - Larch Ave and Ross Dr

### Culvert Z7\_NODE\_0022



Debris buildup and ponding.



View of catch basin.



Location view.



View of inlet pipe.



View of outlet pipe.



View inside catch basin.

**SDFA 23 - Larch Ave and Ross Dr****Culvert Z7\_NODE\_0022**

Direction of flow.

## SDFA 23 - Larch Ave and Ross Dr

### **Culvert Z7\_LINK\_S23\_P1**

Evaluation date/time: 11/20/2014 2:03 PM

Address/location: Larch Ave and Ross Dr

Weather: Damp

#### General Information

Property type: Public

Diameter (in): 24

Upstream feature ID: Z7\_NODE\_0022

Downstream feature ID:

Upstream rim-inv. (ft.): 4.7

Downstream rim-inv. (ft.):

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 5

Type of sediment: Silt, Vegetation

Infiltration: None

Obstruction/Deflection (%)

0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location

#### Notes

Outlet pipe. Pipe runs under roadway. Pipe is noted as CMP per GIS, but is actually RCP. Please refer to included videos for visuals.

#### Photos

## SDFA 23 - Larch Ave and Ross Dr

### **Culvert Z7\_LINK\_S23\_P2**

Evaluation date/time: 11/20/2014 2:03 PM

Address/location: Larch Ave and Ross Dr

Weather: Damp

#### General Information

Property type: Public

Diameter (in): 24

Upstream feature ID:

Downstream feature ID: Z7\_NODE\_0022

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 4.7

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 5

Type of sediment: Silt, Vegetation

Infiltration: None

Obstruction/Deflection (%): 0

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition, Location

#### Notes

Inlet pipe. Pipe runs under roadway. Pipe is noted as CMP per GIS, but is actually RCP. Please refer to included videos for visuals.

#### Photos

**SDFA 24 - Paseo Del Rio*****Area Map***

## SDFA 24 - Paseo Del Rio

### Catch Basin Z1\_NODE\_0204

Evaluation date/time: 11/20/2014 4:50 PM

Address/location: Paseo Del Rio

Weather: Damp

#### General Information

Latitude: 37.872624  
 Longitude: -122.131201  
 Property type: Public  
 Access: Good  
 Traffic: None  
 Ground surface type: Asphalt, Concrete  
 Dia./Ht. (in.): 36  
 Width (in.): 32  
 Material: Concrete  
 Grade/rim-invert (ft.): 9  
 Water level (%): 5  
 Devices: Debris/Trash Rack


#### Condition Information and Ratings

Susceptible to burial/overgrowth: No  
 Susceptible to ponding/flooding: No  
 Sediment/debris depth (%): 0  
 Type of sediment/debris: None  
 Infiltration: None  
 VANDA Condition Rating: Level 1 - No Damage  
 Prioritization Rating: Level 1 - Excellent  
 Prioritization Rationale: Condition  
 Illegal dumping evidence: No

#### Notes

Connected to two 36 in. RCP, 16 in. CMP, and unknown diameter RCP. Unable to determine RCP dimensions and grade to invert due to position within catch basin.

#### Photos



Sketch

## SDFA 24 - Paseo Del Rio

## Catch Basin Z1\_NODE\_0204



View of catch basin.



View inside catch basin.



View of 36-in. RCP outlet and 16-in. CMP inlet.



Direction of flow.



View of 36-in. RCP inlet.

**SDFA 24 - Paseo Del Rio*****Catch Basin Z1\_NODE\_0204***

View of 16-in. CMP inlet.



Location view.

## SDFA 24 - Paseo Del Rio

### ***Catch Basin Z1\_LINK\_0162***

Evaluation date/time: 11/20/2014 4:50 PM

Address/location: Paseo Del Rio

Weather: Damp

#### General Information

		<u>Condition Information and Ratings</u>	
Property type:	Public	Sediment depth (%):	0
Diameter (in):	15	Type of sediment:	None
Upstream feature ID:	Z1_NODE_0204	Infiltration:	None
Downstream feature ID:		Obstruction/Deflection (%)	0
Upstream rim-inv. (ft.):		VANDA Condition Rating:	Level 1 - No Damage
Downstream rim-inv. (ft.):	0	Prioritization Rating:	Level 1 - Excellent
Material:	RCP	Prioritization Rationale:	Condition

#### Notes

Outlet 36 in. RCP. Please refer to included videos for visuals.

#### Photos

## SDFA 24 - Paseo Del Rio

### ***Catch Basin Z1\_LINK\_0175***

Evaluation date/time: 11/20/2014 4:50 PM

Address/location: Paseo Del Rio

Weather: Damp

#### General Information

Property type: Public

Diameter (in): 15

Upstream feature ID:

Downstream feature ID: Z1\_NODE\_0204

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 0

Material: CMP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

VANDA Condition Rating: Level 2 - Minor Damage

Prioritization Rating: Level 2 - Good

Prioritization Rationale: Condition

#### Notes

West inlet 16 in. CMP. Please refer to included videos for visuals.

#### Photos

## SDFA 24 - Paseo Del Rio

### ***Catch Basin Z1\_LINK\_0163***

Evaluation date/time: 11/20/2014 4:50 PM

Address/location: Paseo Del Rio

Weather: Damp

#### General Information

Property type: Public

Diameter (in): 15

Upstream feature ID:

Downstream feature ID: Z1\_NODE\_0204

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 0

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 1 - Excellent

Prioritization Rationale: Condition

#### Notes

North inlet 36 in. RCP. Please refer to included videos for visuals.

#### Photos

## SDFA 24 - Paseo Del Rio

### **Catch Basin Z1\_LINK\_0176**

Evaluation date/time: 11/20/2014 4:50 PM

Address/location: Paseo Del Rio

Weather: Damp

#### General Information

Property type: Public

Diameter (in): 24

Upstream feature ID:

Downstream feature ID: Z1\_NODE\_0204

Upstream rim-inv. (ft.):

Downstream rim-inv. (ft.): 0

Material: RCP

#### Condition Information and Ratings

Sediment depth (%): 0

Type of sediment: None

Infiltration: None

Obstruction/Deflection (%)

VANDA Condition Rating: Level 1 - No Damage

Prioritization Rating: Level 1 - Excellent

Prioritization Rationale: Condition


#### Notes

East inlet unknown diameter RCP. Unable to determine RCP dimensions and grade to invert due to position within catch basin. Please refer to included videos for visuals.

#### Photos

## SDFA 25 - Draeger Dr

## Area Map



## SDFA 25 - Draeger Dr

### ***Catch Basin Z3\_NODE\_0174***

Evaluation date/time: 11/20/2014 5:17 PM

Address/location: Draeger Dr

Weather: Light Rain

#### General Information

Latitude:

Longitude:

Property type: Public

Access: Good

Traffic: Light

Ground surface type: Asphalt, Concrete

Dia./Ht. (in.): 36

Width (in.): 32

Material: Concrete

Grade/rim-invert (ft.): 0

Water level (%): 5

Devices: Debris/Trash Rack

#### Condition Information and Ratings

Susceptible to burial/overgrowth: No

Susceptible to ponding/flooding: No

Sediment/debris depth (%):

Type of sediment/debris Unknown

Infiltration: Unknown

VANDA Condition Rating: Unknown

Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Condition

Illegal dumping evidence: No

#### Notes

Unable to evaluate due to bolted catch basin grate.

#### Photos



Location view.

## SDFA 25 - Draeger Dr

### ***Catch Basin Z3\_LINK\_0173***

Evaluation date/time: 11/20/2014 5:17 PM

Address/location: Draeger Dr

Weather: Light Rain

#### General Information

Property type: Public

Diameter (in):

Upstream feature ID: Z3\_NODE\_0174

Downstream feature ID:

Upstream rim-inv. (ft.): 0

Downstream rim-inv. (ft.): 0

Material: Unknown

#### Condition Information and Ratings

Sediment depth (%):

Type of sediment: Unknown

Infiltration: Unknown

Obstruction/Deflection (%)

VANDA Condition Rating: Unknown

Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Condition

#### Notes

Outlet pipe. Unable to evaluate due to bolted catch basin grate. Pipe runs under roadway and residence. Pipe appears to be CMP.

#### Photos

## SDFA 25 - Draeger Dr

### ***Catch Basin Z3\_LINK\_0174***

Evaluation date/time: 11/20/2014 5:17 PM

Address/location: Draeger Dr

Weather: Light Rain

#### General Information

Property type: Public

Diameter (in):

Upstream feature ID:

Downstream feature ID: Z3\_NODE\_0174

Upstream rim-inv. (ft.): 0

Downstream rim-inv. (ft.): 0

Material: Unknown

#### Condition Information and Ratings

Sediment depth (%):

Type of sediment: Unknown

Infiltration: Unknown

Obstruction/Deflection (%)

VANDA Condition Rating: Unknown

Prioritization Rating: Level 3 - Fair

Prioritization Rationale: Condition

#### Notes

Inlet pipe. Unable to evaluate due to bolted catch basin grate. Pipe runs under roadway and residence. Pipe appears to be CMP.

#### Photos



# **APPENDIX B**

## **Culvert Field Sheets and Photos**

JOB # TMOR.01.14  
DATE 4-2-15  
OBSERVED BY RJ/LNF

CREEK Larch LOCATION Wandel Lac C1

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE:

BRIDGE

CULVERT:

BOX



PIPE

LENGTH OF ROADWAY 12 (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH 581 (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>1</u>	<u>388" (H) x 88" (W)</u> <u>64"</u>	<u>Ø</u>

**N-VALUES**

UPSTREAM

LOB .055

Channel .05

ROB .055

DOWNSTREAM

LOB .025

Channel .093

ROB .045

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
# SPACING \_\_\_\_\_


**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Weir drop v/s invert

D/s right bank concrete rip rap

**SKETCH:**



JOB # TMOR.01.14  
DATE 4-2-05  
OBSERVED BY RJL/LNF

CREEK Larch LOCATION Camino Pablo Lacc2

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE:

BRIDGE

CULVERT:

BOX



PIPE

LENGTH OF ROADWAY 35' (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH google st. (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtwN BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>RCP CMP</u>	<u>2</u>	<u>72"</u>	<u>2'</u>

**N-VALUES**

UPSTREAM

LOB .03 (above wall)

Channel .04

ROB .045

DOWNSTREAM

LOB .04

Channel .03

ROB .04

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 8'5"

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
# SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: U/S left bank is concrete wall 3½'  
Culverts have concrete lining then CMP pipe.  
on Left U/S culvert CMP is tearing away.  
Recommend future monitoring of condition.

**SKETCH:**





JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY RJL/LNF

CREEK Larch LOCATION Corte Maria Lac 2.5

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX **PIPE**  
LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH \_\_\_\_\_ (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>RCP Arch</u>		<u>16'10" W x 54" (H)</u>	

**N-VALUES**

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE metal

HEIGHT 4'

LENGTH \_\_\_\_\_

% OPEN SPACE 90

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #   # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
#   SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM		<u>45°</u>	
DOWNSTREAM		<del>45°</del> <u>none</u>	



NOTES: Not previously studied, perhaps new development. Looks new. U/S has some sediment. Private? 13 yr. old. Property owners own land that is creek. \$ paid for sketch: Cleaning on culvert.

JOB # TMOR-0114  
DATE 4-2-15  
OBSERVED BY RJL/LNF

CREEK Larch Creek LOCATION LacC3

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY 50' (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH 12' (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtw BOX
<u>CBC</u>	<u>1</u>	<u>10'</u>	<u>84-1/2 ft</u>	

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES

**N-VALUES**

**UPSTREAM**

LOB 0.05  
Channel .035  
ROB 0.05

**DOWNSTREAM**

LOB .05  
Channel .035  
ROB .05

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
<b>Natural streams - minor streams (top width at floodstage &lt; 100 ft)</b>			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_


**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 6'

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Problem area noted by town staff  
Bad smell

**SKETCH:**



JOB # TMOR.01.14

DATE 4-2-15

OBSERVED BY RJL/LNF

CREEK Las Trampas

LOCATION St. Marys Rd. LTC 1

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE:

BRIDGE

CULVERT:

BOX



PIPE

LENGTH OF ROADWAY 51' (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH google est. (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_  
*steep!*



**CULVERT DATA**

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX
<u>RCP</u>	<u>1</u>	<u>8'</u>	<u>8'</u>	

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES

**N-VALUES**

UPSTREAM

LOB .05

Channel .04

ROB .05

DOWNSTREAM

LOB .04

Channel .035

ROB .035

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD ~28'

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
#  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM		<u>0°</u>	
DOWNSTREAM		<u>~0°</u>	

NOTES: Very deep & steep channel. Not too much vegetation but woody and rocky. Nice artwork!

**SKETCH:**





JOB # T MOR.01.14  
DATE 4-9-15  
OBSERVED BY EJL/LNF

CREEK Las Trampas LOCATION LTC2, trib.

ROADWAY DATA (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH 90'0" (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>1</u>	<u>55 5/8" N x 32"</u>	

### N-VALUES

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
#  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Pipe suppose to be circular but lots of sediment, Model as arch. Pipe also has significant drop.

**SKETCH:**



JOB # TM02.01.14  
DATE 4-9-15  
OBSERVED BY RJL/LNF



CREEK Las Trampas LOCATION Bollinger Canyon LTC3

ROADWAY DATA (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE

LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH 80' (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



CULVERT DATA

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CM P</u>	<u>1</u>	<u>158" (W) x 58" (H)</u>	<u>66" (H) o/s.</u>

N-VALUES

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 #  #  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Large arch, VBA inspected? Check report.  
Lots of sediment inside culvert.  
Sediment on downstream side makes  
capacity lower. Model smaller dimension.



**SKETCH:**

JOB # TMOR.01.14  
DATE 4-2-15  
OBSERVED BY RJL/LNF

CREEK St Marys Creek LOCATION Moraga Rd. SM 1

ROADWAY DATA (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY 20' (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH google (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

#### BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

#### PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP/Asphalt lined</u>	<u>1</u>	<u>60"</u>	<u>Ø</u>

### N-VALUES

#### UPSTREAM

LOB .045  
Channel .035  
ROB .045

#### DOWNSTREAM

LOB .045  
Channel .035  
ROB .045

### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 15'

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #   # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
#   SPACING \_\_\_\_\_

**WINGWALL DATA**

Beveled 0's

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Beveled cmp w/ Asphalt lining. Rip rap channel v/s for ~20' No wing walls.  
Pipe goes under park. Downstream  
inaccessible.

**SKETCH:**

JOB # TMOR.01.14  
DATE 4-2-15  
OBSERVED BY RJL/LNF



CREEK St. Mary Trib LOCATION St. Mary's Rd. SMTZ

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT:  BOX  PIPE

LENGTH OF ROADWAY 20' (ft) SKEW 90° (deg) (L up strm)

BOT. WIDTH google est. (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>HDPE</u>	<u>2</u>	<u>48"</u>	<u>8' 1"</u>

**N-VALUES**

**UPSTREAM**

LOB .05  
Channel .03, .045  
ROB .05

**DOWNSTREAM**

LOB .04  
Channel .03  
ROB .04

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
# SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

**NOTES:** Concrete chunks in channel. Pipes elevated above channel bottom 12". Pipes protrude out w/ no headwall, 7' downstream pipes 15' from roadway.

**SKETCH:**





JOB # TMOR-01-14  
DATE 4-2-15  
OBSERVED BY RJL/LNF

CREEK St Mary's LOCATION Stafford STM3

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY 81 (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH 40' (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtw BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>HDPE</u>	<u>1</u>	<u>36"</u>	<u>Ø</u>

**N-VALUES**

UPSTREAM  
LOB \_\_\_\_\_  
Channel \_\_\_\_\_  
ROB \_\_\_\_\_

DOWNSTREAM  
LOB .04  
Channel .035  
ROB .04

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_


**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 4'

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: D/s pipe 12' from roadway. U/s pipe is 5' from roadway d/s pipe has significant sedimentation.

**SKETCH:**

JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY RJL/LNF

CREEK St. Marys Trib LOCATION STM4 \*new\* under trail

ROADWAY DATA (All data shall be given looking downstream)

TYPE:

BRIDGE

CULVERT:

BOX



PIPE

LENGTH OF ROADWAY \_\_\_\_\_ (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH 37' (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtwn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>1</u>	<u>72"</u>	

### N-VALUES

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 #  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Culvert under trail, just downstream  
of 2x40"

**SKETCH:**



JOB # TMOR.0.14  
DATE 4-2-15  
OBSERVED BY RJL/LNF



CREEK Moraga LOCATION Ivy Drive MC1

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT:  BOX PIPE

LENGTH OF ROADWAY 25' (ft) SKEW 0 (deg) (L up strm)

BOT. WIDTH 46' (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>Arch</u> <u>CMP</u>	<u>1</u>	<u>8' x 13'</u>	

**N-VALUES**

**UPSTREAM**

LOB .035 .04  
Channel .025 .03  
ROB .035 .04

**DOWNSTREAM**

LOB .035  
Channel .025  
ROB .035

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 12'

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  
#



# SETS OF PIERS \_\_\_\_\_

SPACING \_\_\_\_\_


WIDTH \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNTSTREAM	<u>NONE</u>		

NOTES: Arched CMP. Culvert likely in Orinda. Noted wing wall separated from pipe coming from school!  
Minor erosion on R o/s. 8" pipe runs through  
culvert

**SKETCH:**



JOB # TMOP.01.14  
DATE 4-2-15  
OBSERVED BY RJL/LNF



CREEK Moraga LOCATION Miramonte, MC2

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT:  BOX PIPE

LENGTH OF ROADWAY 24' (ft) SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH 70' (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CM P</u>	<u>1</u>	<u>(w)15' x 8.5' (H)</u>	<u>Ø</u>

**N-VALUES**

**UPSTREAM**

LOB 0.03

Channel 0.025

ROB 0.03

**DOWNSTREAM**

LOB 0.025

Channel 0.025

ROB 0.025

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 13'

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 SPACING \_\_\_\_\_


**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM		<u>45°</u>	
DOWNSTREAM		<u>45°</u>	

NOTES: Concrete headwall.

\_\_\_\_\_

**SKETCH:**



JOB # TMOR.01.14  
DATE 4-2-15  
OBSERVED BY PJL/LNF

CREEK Moraga LOCATION St. Andrews  
Camino Ricardo MB3

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE:

BRIDGE

CULVERT:

BOX



PIPE

LENGTH OF ROADWAY 23' (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH google estimate (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>Arch</u> <u>CMP</u>	<u>1</u>	<u>22' x 8'</u>	

**N-VALUES**

UPSTREAM

LOB .025

Channel .03

ROB .025

DOWNSTREAM

LOB .045

Channel .035

ROB .045

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

## BRIDGE DATA

## RAILING

TYPE Metal

HEIGHT 21

## LENGTH

% OPEN SPACE 80

## HEIGHTS

## INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 17'

## LOW CHORD TO TOP OF ROAD


## PIER DATA


SHAPE: #   # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 #   SPACING \_\_\_\_\_  


## WINGWALL DATA

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

**NOTES:** Downstream very overgrown but only for about 100' then clears up. Upstream has unusual headwall, may be too complex to model

**SKETCH:** Profile 



JOB # TMOR 01.14  
DATE 4-2-15  
OBSERVED BY RJL/LNA

CREEK Moraga Creek LOCATION Canyon Rd MC4

ROADWAY DATA (All data shall be given looking downstream)

Bridge

TYPE:



CULVERT:

BOX



PIPE

LENGTH OF ROADWAY google (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH google (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES

### N-VALUES

UPSTREAM

LOB .03

Channel .025

ROB .03

DOWNSTREAM

LOB .03

Channel .025

ROB .03

### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #



#



# SETS OF PIERS

*~2*

WIDTH \_\_\_\_\_

SPACING \_\_\_\_\_

*I-beams*

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: *No access to bridge. Very large channel & small piers. Could model as free spanning bridge. Piers are I-beams*

**SKETCH:**

JOB # TMOR.01  
DATE 4-2-15  
OBSERVED BY RJL/LNF



CREEK Ivy LOCATION ID1

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT:  BOX PIPE  X2

LENGTH OF ROADWAY 20' (ft) SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH 37' (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST btwn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>2</u>	<u>(70" x 45'H)</u>	<u>2'</u>

**N-VALUES**

UPSTREAM

LOB 0.1

Channel 0.1

ROB 0.1

DOWNSTREAM

LOB 0.045

Channel 0.04

ROB 0.045

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 6' \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  #  #  # # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM		<u>45°</u>	<u>10'</u>

NOTES: Could not access due to chain fence. Dimensions estimates. D/S has shelf, ~3'

**SKETCH:**



JOB # TMGR.01.14  
DATE 4-2-15  
OBSERVED BY RJL/LNF



CREEK Ivy LOCATION Moraga Rd. 1D2

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT:  BOX PIPE

LENGTH OF ROADWAY 25' (ft) SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH Est. in Google (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>RCP</u>	<u>1</u>	<u>66"</u>	<u>8</u>

**N-VALUES**

**UPSTREAM**

LOB 0.04  
Channel .035  
ROB 0.04

**DOWNSTREAM**

LOB .025  
Channel .025  
ROB .025

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
<b>Natural streams - minor streams (top width at floodstage &lt; 100 ft)</b>			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no riffs or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 8.5'

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
# SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Noted large inflow to RCP pipe from Moraga Rd.

**SKETCH:**



JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY RJL/LNF

CREEK Corliss Trib LOCATION Corliss Dr. CD1

ROADWAY DATA (All data shall be given looking downstream)

TYPE:

BRIDGE

CULVERT:

BOX





LENGTH OF ROADWAY \_\_\_\_\_ (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH google map (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u> Ashpatt lined.	1	<u>60" 68"</u>	

### N-VALUES

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM		45°	
DOWNSTREAM		45°	

NOTES: v/s good condition, channel cleared.  
dls has some sediment, not too bad  
Height on dls is 43"



**SKETCH:**

JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY B4LNF

CREEK Rheem Trib LOCATION Scofield RT 1

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH google (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>RC P/CMF</u> D15 u/s	1	<u>CMP-58"</u> <u>RCP-15" x 27"</u>	

**N-VALUES**

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
<b>Natural streams - minor streams (top width at floodstage &lt; 100 ft)</b>			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

## BRIDGE DATA

## RAILING

## TYPE

## HEIGHT

## LENGTH

## % OPEN SPACE

## HEIGHTS

## INVERT TO LOW CHORD

## INVERT TO TOP OF ROAD

## LOW CHORD TO TOP OF ROAD

## PIER DATA


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 #  SPACING  
   

## WINGWALL DATA

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

**NOTES:** D/S outlet cracked, pipe oval. 15"(H) x 21"(W)  
cracked all the way. V/S is CMP  
V/S has heavy debris. Possibly pipe is  
collapsed. 2 pipes, RCP from roadway & CMP

**SKETCH:** is creek covered. RCP needs replacing & CMP needs attention. 2024





JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY RL/LNF

CREEK Rheem Trib. LOCATION Harold RT2

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE:	BRIDGE	CULVERT:	BOX	PIPE
LENGTH OF ROADWAY	(ft)	SKEW	(deg)	(L up strm)
BOT. WIDTH	<u>google</u> (ft)	SIDE SLOPES L _____ R _____		



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>LCP</u>	<u>1</u>	<u>42"</u>	

**N-VALUES**

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
<b>Natural streams - minor streams (top width at floodstage &lt; 100 ft)</b>			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #   # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 #  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: O/S sedimented perhaps 25%. Large channel.

**SKETCH:**

JOB # TM0 R.01.14

DATE 4-2-15

OBSERVED BY RJL/LNF

CREEK Rheem Trib. LOCATION RT3

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE

CULVERT: BOX



PIPE

LENGTH OF ROADWAY \_\_\_\_\_ (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH unknown (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>RCP</u>	<u>1</u>	<u>54" (4.5')</u>	

**N-VALUES**

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
#  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: v/s has lots of rocks & vegetation.  
 RCP pipe in good condition. Pipe ends @ junction w/ Laguna. Model boundary to be Laguna creek depth @ 100yr.



SKETCH:

JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY RS/LNF

CREEK Laguna Trib LOCATION TL1

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH \_\_\_\_\_ (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>1</u>	<u>64"</u>	

**N-VALUES**

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
<b>Natural streams - minor streams (top width at floodstage &lt; 100 ft)</b>			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_


**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
#  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Not in 2008 Study, might be in  
WRECO study. Pipe goes under parking lot



**SKETCH:**

JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY RSL/LNF

CREEK Laguna Trib LOCATION TL2

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH \_\_\_\_\_ (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>1</u>	<u>72"</u>	

**N-VALUES**

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
<b>Natural streams - minor streams (top width at floodstage &lt; 100 ft)</b>			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

## BRIDGE DATA

## RAILING

TYPE \_\_\_\_\_

## HEIGHT

## LENGTH

### % OPEN SPACE

## HEIGHTS

## INVERT TO LOW CHORD

## INVERT TO TOP OF ROAD

## LOW CHORD TO TOP OF ROAD

## PIER DATA

SHAPE: #   # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 #   SPACING \_\_\_\_\_

## WINGWALL DATA

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Inside Aciencia, check WRECO study.

## SKETCH:

JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY RSL/LNF



CREEK Tri D laguna LOCATION TL3

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE

LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH \_\_\_\_\_ (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>1</u>	<u>72"</u>	

**N-VALUES**

UPSTREAM  
LOB \_\_\_\_\_  
Channel \_\_\_\_\_  
ROB \_\_\_\_\_

DOWNSTREAM  
LOB \_\_\_\_\_  
Channel \_\_\_\_\_  
ROB \_\_\_\_\_

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**



SHAPE: #  #  #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Shorter pipe, ~20½ long. Under trail

**SKETCH:**





JOB # TMOR.a.15  
DATE 4-2-15  
OBSERVED BY RJL/LNF

CREEK South Maraga (River) LOCATION SMC1

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH \_\_\_\_\_ (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtwn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>1</u>	<u>102"</u>	

*\* Assumed no access*

**N-VALUES**

**UPSTREAM**

LOB .03  
Channel .025  
ROB .03

**DOWNSTREAM**

LOB .03  
Channel .025  
ROB .03

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD ? \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Assumed pipe diameter b/c no access, lacked fence. Appears private properties extend to creek. Culvert is about 10-15' from roadway



**SKETCH:**

JOB # TMOR 01.14  
DATE 4-2-2015  
OBSERVED BY EJL/LNF

CREEK S. Maraga (River) LOCATION Camino Pable SMC2

ROADWAY DATA (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH \_\_\_\_\_ (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

#### BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

#### PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>CMP</u>	<u>1</u>	<u>80" (H)</u>	<u>NA</u>

78" (H) x 80" (W)

#### N-VALUES

##### UPSTREAM

LOB .04  
Channel .03  
ROB .04

##### DOWNSTREAM

LOB .045  
Channel .035  
ROB .045

#### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
#  SPACING \_\_\_\_\_


**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM		45°	
DOWNSTREAM		45°	

NOTES: Culvert makes a bend.

D/s drop 2' out of culvert

**SKETCH:**





JOB # TMOR.01.14  
DATE 4-9-15  
OBSERVED BY EJL/LNF

CREEK Laguna Creek LOCATION LC1 - Campolindo

ROADWAY DATA (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY \_\_\_\_\_ (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH goggle (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>RCP</u>	<u>1</u>	<u>48"</u>	

### N-VALUES

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
# SPACING \_\_\_\_\_


**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Large tree inside culvert & blocking culvert. Culvert is long, need to get length on google earth. Stagnant water on d/s side. D/s across from bus stop.

**SKETCH:**

Campolindo



Moraga Rd

JOB # TMOL014  
DATE 4-9-15  
OBSERVED BY RJL/LNF

CREEK Laguna Creek LOCATION LC2 - Woodford Dr.

ROADWAY DATA (All data shall be given looking downstream)

TYPE:

BRIDGE

CULVERT:

BOX



PIPE

LENGTH OF ROADWAY \_\_\_\_\_ (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH \_\_\_\_\_ (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>RCP</u>	<u>1</u>	<u>42"</u>	

### N-VALUES

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: On u/s there is a spillway that drops about 2-3' this holding back flow in channel w/ standing water

SKETCH: u/s @ house on Moraga Rd.



JOB # TMOR.01.14

DATE 4-9-15

OBSERVED BY RJL/LNF

CREEK Laguna Creek LOCATION Haciend LC4 & LCS

ROADWAY DATA (All data shall be given looking downstream)

TYPE:

BRIDGE

CULVERT:

BOX



PIPE

LENGTH OF ROADWAY \_\_\_\_\_ (ft)

SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH \_\_\_\_\_ (ft)

SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



### CULVERT DATA

BOX:

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

PIPE:

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
	<u>2</u>	<u>LCS-96" CMP</u> <u>LCS - Box RCP 12' x 10'</u>	

### N-VALUES

UPSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

DOWNSTREAM

LOB \_\_\_\_\_

Channel \_\_\_\_\_

ROB \_\_\_\_\_

### Manning's n for Channels (Chow, 1959).

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no riffs or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
 #  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			

NOTES: Get dimensions & data from WRECO study  
 Drop weir v/s side 20"

**SKETCH:**





JOB # TMOR.01.14  
DATE RJL/LNF  
OBSERVED BY 4-9-15

CREEK Laguna Creek LOCATION Lynwood LC7

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE:	BRIDGE	CULVERT:	BOX	PIPE
LENGTH OF ROADWAY	(ft)	SKEW	(deg)	(L up strm)
BOT. WIDTH	(ft)	SIDE SLOPES L _____ R _____		



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
CMP	1	12'	

**N-VALUES**

UPSTREAM  
LOB \_\_\_\_\_  
Channel \_\_\_\_\_  
ROB \_\_\_\_\_

DOWNSTREAM  
LOB \_\_\_\_\_  
Channel \_\_\_\_\_  
ROB \_\_\_\_\_

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
1. Main Channels			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE \_\_\_\_\_

HEIGHT \_\_\_\_\_

LENGTH \_\_\_\_\_

% OPEN SPACE \_\_\_\_\_

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: #  # SETS OF PIERS \_\_\_\_\_ WIDTH \_\_\_\_\_  
#  SPACING \_\_\_\_\_

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM		45°	
DOWNSTREAM		45°	

NOTES: Large CMP pipe Headwall cracked  
on top of d/s. Need inlet on street  
to drain low point of street.

**SKETCH:**



JOB # TMOR.01.14  
DATE 4-2-15  
OBSERVED BY RJL/CNF



CREEK Laguna Creek LOCATION Moraga Rd LCB

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE: BRIDGE CULVERT: BOX PIPE

LENGTH OF ROADWAY 29 (ft) SKEW \_\_\_\_\_ (deg) (L up strm)

BOT. WIDTH googlest. (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX
<u>CBC</u>	<u>2</u>	<u>13'</u>	<u>10'</u>	<u>11</u>

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES
<u>DRR</u>	<u>24</u>		

**N-VALUES**

**UPSTREAM**

LOB 0.045, 0.05  
Channel 0.045  
ROB 0.04, 0.05

**DOWNSTREAM**

LOB 0.045  
Channel 0.045  
ROB 0.045

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no riffs or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE Chain

HEIGHT 4'

LENGTH \_\_\_\_\_

% OPEN SPACE 90

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD \_\_\_\_\_

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**


SHAPE: # ■■■■ — # SETS OF PIERS 1 WIDTH \_\_\_\_\_  
 # ●●●● — SPACING Middle  
— —

**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM		<u>60°</u>	
DOWNSTREAM		<u>45°</u>	

NOTES: Looks more like bridge, could be modeled as 2 boxes or bridge. Major debris buildup at 1/3 pier and downstream opening

**SKETCH:**





JOB # TMOP.01-14  
DATE 4-2-15  
OBSERVED BY RJL/LNF

CREEK Laguna LOCATION Country Club LC9

**ROADWAY DATA** (All data shall be given looking downstream)

TYPE:  BRIDGE CULVERT: BOX PIPE  
LENGTH OF ROADWAY 31' (ft) SKEW \_\_\_\_\_ (deg) (L up strm)  
BOT. WIDTH 47' (ft) SIDE SLOPES L \_\_\_\_\_ R \_\_\_\_\_



**CULVERT DATA**

**BOX:**

TYPE	# OF BOXES	WIDTH	HEIGHT	DIST bwtn BOX

**PIPE:**

TYPE	# OF PIPES	DIAMETER	DIST btwn PIPES

**N-VALUES**

**UPSTREAM**

LOB .045  
Channel .04  
ROB .045

**DOWNSTREAM**

LOB .045  
Channel .04  
ROB .045

**Manning's n for Channels (Chow, 1959).**

Type of Channel and Description	Minimum	Normal	Maximum
Natural streams - minor streams (top width at floodstage < 100 ft)			
<b>1. Main Channels</b>			
a. clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
b. same as above, but more stones and weeds	0.030	0.035	0.040
c. clean, winding, some pools and shoals	0.033	0.040	0.045
d. same as above, but some weeds and stones	0.035	0.045	0.050
e. same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
f. same as "d" with more stones	0.045	0.050	0.060
g. sluggish reaches, weedy, deep pools	0.050	0.070	0.080
h. very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150
<b>2. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages</b>			
a. bottom: gravels, cobbles, and few boulders	0.030	0.040	0.050
b. bottom: cobbles with large boulders	0.040	0.050	0.070

**BRIDGE DATA**

**RAILING**

TYPE concrete

HEIGHT 42" (3.5')

LENGTH 63'

% OPEN SPACE 50%

**HEIGHTS**

INVERT TO LOW CHORD \_\_\_\_\_

INVERT TO TOP OF ROAD 141

LOW CHORD TO TOP OF ROAD \_\_\_\_\_

**PIER DATA**

SHAPE: # ■■■■ — # SETS OF PIERS 1 WIDTH \_\_\_\_\_  
 # ●●●● — SPACING \_\_\_\_\_  
— —


**WINGWALL DATA**

	TYPE (str8 / warped)	ANGLE (from CL)	LENGTH
UPSTREAM			
DOWNSTREAM			


NOTES: Bridge is larger than listed in 2008 study.

Heavily vegetated & sediment bank on left side



**SKETCH:**




Culvert: CD1



Culvert: ID1




Culvert: ID2




Culvert: LacC1





Culvert: LacC2





Culvert: LacC2.5





Culvert: LacC3





Culvert: LC1



Culvert: LC2






Culvert: LC3




Culvert: LC5/6




Culvert: LC7





Culvert: LC8



Culvert: LC9





Culvert: LTC1



Culvert: LTC2






Culvert: LTC3




Culvert: MB3



Culvert: MC1



Culvert: MC2



Culvert: RT1




Culvert: RT2



Culvert: RT3



Culvert: SMC1



Culvert: SMC2



Culvert: STM1



Culvert: STM2




Culvert: STM3



Culvert: STM4




Culvert: TL1



Culvert: TL2



Culvert: TL3



## **APPENDIX C**

### **Street Pavement Storm Drain Repairs**

TO: Edric Kwan, PE DATE: October 31, 2014  
FROM: Dan Schaaf, PE JOB #: TMOR.01.14  
Robin Lee, PE  
SUBJECT: **2015 Street Pavement Project Storm Drain Improvements**

---

## Introduction and Purpose

This technical memorandum presents the findings of televising the storm drain network that lies under the streets that are to be repaved in 2015 in the Town of Moraga. Presidio Systems Inc. spent five days in the field televising storm drains. Approximately 9,000 linear feet of pipe was inspected under the streets to be repaved in 2015. The results of these videos showed that the majority of the Town's system is in fair condition, with the exception of a few pipes that need complete replacement and several that need spot repairs. Timing the rehabilitation and replacement of pipes that are impaired with the street pavement projects means that the streets are only torn up once and residents are not disrupted by construction at two separate times. It is anticipated that there will be a cost savings in aligning these storm drain projects to coincide with the pavement projects. Attachment 1 provides a table of the street pavement projects for 2015.

In addition, several pipes were noted with high levels of sediment and in some cases large boulders and/or cement blocks. Six pipes were cleared of sediment and debris by Presidio System Inc. Some of these pipes will require heavy duty cleaning that could take more than a day. To minimize the impacts to residents, it is also recommended that these pipes are maintained at the same time as the street pavement projects.

## Severity of Storm Drain Defects

Presidio Systems Inc. (PSI) has a rating scale of 1-5 for the pipe defects that they notice on the televised videos. These are shown in Table 1.

**Table 1: Storm Drain Pipe Impairment Rating**

Level	Severity
1	Light
2	Moderate
3	Average
4	Heavy
5	Severe

An example of a light severity defect is longitudinal cracking in a reinforced concrete pipe (RCP) that does not show signs of infiltration or weakened structure. An example of a severe defect is a hole in a pipe that is allowing soil, roots, or sediment. Any defect that limits the conveyance capacity of a pipe is considered Heavy to Severe. In some instances, sediment or debris might be considered a Heavy or Severe defect if it is thought that the limit in capacity may result in flooding. The locations of the street repairs and the storm drain impairments are shown in Figure 1. Figure 2 shows examples of debris and broken pipe defects.




Figure 1: Storm Drain Pipe Impairment Locations



Figure 2: Pipe Impairment Examples: Broken Pipe (left) Pipe Debris (right)

## Cost Estimates

All estimates were developed in accordance to current Bay Area practices. The estimates are based on project experience with other jurisdictions and engineering judgment. Project costs are in 2014 dollars. Projects are separated into replacement and rehabilitation by CIPP. The cost for pipe replacement includes a ten foot wide trench with approximately five feet of cover above the pipe. The majority of pipes inspected were RCP and in fair condition, therefore, complete replacement is not recommended, instead, a patch repair on the impaired section of pipe is recommended. Patch repair costs assume two 8-ft sections of pipe are required to make repair. These cost estimates are to be used for planning level decisions, but should not be relied upon for basis of design.

Tables 2 shows the unit costs for replacement and CIPP lining of pipes by diameter.

Table 2: Storm Drain Pipe Unit Costs for Repairs

Diameter (inches)	Cost Replace (\$/ft)	Cost CIPP (\$/ft)	Patch Repair (\$/repair)
8	\$200	\$80	\$3,200
12	\$225	\$90	\$3,600
15	\$250	\$100	\$4,000
18	\$270	\$110	\$4,320
21	\$290	\$120	\$4,640
24	\$325	\$130	\$5,200
27	\$350	\$145	\$5,600
30	\$375	\$160	\$6,000
33	\$400	\$175	\$6,400
36	\$425	\$190	\$6,800
42	\$475	\$250	\$7,600
48	\$525	\$300	\$8,400



Diameter (inches)	Cost Replace (\$/ft)	Cost CIPP (\$/ft)	Patch Repair (\$/repair)
54	\$575	\$390	\$9,200
60	\$625	\$500	\$10,000
66	\$675	\$510	\$10,800
72	\$725	\$520	\$11,600
78	\$780	\$530	\$12,480
84	\$830	\$540	\$13,280

Total project costs include an additional 40% increase for design, administration, and contingency. Some projects require maintenance such as removal of boulder, cement, or sediment. These projects are classified into a cleaning project and the cost is set to \$275/hr based on cost estimates from Presidio System Inc.

## Prioritization

### Condition Related Improvements

Project costs were developed by priority and by project type. Table 3 summarizes the costs by priority level and Table 4 details the projects by project type. Costs in Tables 3, 4, and 5 include the 40% increase.

**Table 3: Storm Drain Improvement Costs by Priority**

Level	Severity	Cost
1	Light	\$3,000
2	Moderate	\$21,000
3	Average	\$126,000
4	Heavy	\$103,000
5	Severe	\$260,000
<b>TOTAL</b>		<b>\$513,000</b>

Of the 97 pipes inspected, roughly half did not require any maintenance or improvement. Of the specified improvement projects, roughly half are spot repairs and cleaning. Table 4 summarize the projects by type.

**Table 4: Improvement Projects by Type**

Project Type	Number of Projects	Cost
Cleaning	21	\$55,000
Spot Repair	20	\$204,000
Private Improvement	4	\$145,000
Spot Repair & Cleaning	3	\$48,000
CIPP	2	\$61,000
No Improvement Needed	41	-
Cleaning Completed	6	-

Attachment 2 to this memo contains a detailed table of all the identified impairments located under the street to be repaved in 2015. Table 5 provides a brief summary of the Severe and Heavy rated impairment and the associated projects including the location, pipe size, priority, project type and cost. The projects that are rated Light, Moderate, and Average are recommended to be completed within the next 10 years, and are therefore, not of the highest priority. It is suggested that these projects are lumped into the Storm Drain Master Plan and the Severe and Heavy projects are completed with the road repavement projects.

Attachment 3 of this memo contains maps of each street and the associated projects.

**Table 5: Storm Drain Improvement Costs by Street**

Street	Pipe Size (in)	Length Surveyed	Severity	Project Type	Cost
Alderbrook Place	24	63	Heavy	Patch Repair	\$14,560
Bollinger	24	37	Heavy	Cleaning & 2 Patch Repairs	\$15,330
Buckingham	24	148	Heavy	Cleaning & Patch Repairs	\$8,820
Camino Pablo	15	15.1	Severe	none	-
Campolindo	48	10	Severe	Cleaning & 2 Patch Repairs	\$24,290
Campolindo	48	140	Severe	Cleaning	\$770
Corliss	30	612	Severe	Patch Repair	\$16,800
Corliss	15	0	Severe	Private Cleaning	\$21,560
Corliss	24	112	Heavy	CIPP	\$20,384
Corliss	24	0	Heavy	Cleaning Completed	-
Corliss	18	145	Heavy	Patch Repair	\$6,048
Country Club	15	21	Heavy	Cleaning	\$1,540
Del Monte	48	4	Severe	Cleaning	\$21,560
Del Monte Way	15	220	Severe	Patch Repair	\$5,600



Street	Pipe Size (in)	Length Surveyed	Severity	Project Type	Cost
Del Rio	15	39	Severe	Cleaning Completed	-
Larch	18	62	Severe	Patch Repair	\$12,096
Larch	15	0	Severe	none	-
Larch	30	180	Heavy	Patch Repair	\$8,400
Larch	18	34	Heavy	Cleaning	\$1,540
Larch	24	120	Heavy	Cleaning	\$3,080
Larch	18	33	Heavy	Cleaning	\$1,540
Larch	15	12	Heavy	Cleaning Completed	-
Larch	42	77	Heavy	Cleaning Completed	-
Natalie	24	290	Severe	Patch Repair	\$7,280
Natalie	18	34	Severe	Patch Repair	\$6,048
Natalie	24	134	Severe	Patch Repair	\$14,560
Natalie	30	36	Heavy	Cleaning Completed	-
Natalie	30	245	Heavy	Patch Repair	\$8,400
Sandringham	24	123	Heavy	Patch Repair	\$7,280
Scofield	18	110	Severe	Private Replacement	\$41,580
Scofield	24	83	Severe	Private Replacement	\$37,765
Scofield	24	97	Severe	Private Replacement	\$44,135
Scofield	18	263	Heavy	Patch Repair	\$6,048

### Capacity Related Improvement

The Town's mapped storm drain infrastructure was modeled using DHI's MIKE URBAN software to identify any undersized pipes that require upsizing. None of the pipes under the streets to be repaved showed signs of flooding or limited capacity during a 10-year storm event with 100-year depth in the receiving creeks. At this time, there are no recommend projects to increase pipe capacity under the streets to be repaved in 2015.

### Future Storm Drain Master Planning

Additional condition and capacity related projects will be identified and detailed in the Town's Storm Drain Management Plan. Because it is anticipated that other Heavy and Severe impairments will be identified in upcoming modeling and condition assessment work, it is suggested that only the Severe and Heavy projects are completed at the same time as the street repavement projects. The rest of the projects will be added to the Storm Drain Master Plan and should be addressed within the next ten years.

## APPENDIX 1

### **2015 Pavement Repair Project List**

**Town of Moraga  
2015 Pavement Repair Project  
Preliminary Street List**

Name	Begin Location	End Location	2011 PCI	FC	Lanes	Length (ft)	Area (sf)	Preliminary Treatment	Preliminary Unit cost	Preliminary Treatment Cost (\$/sy)
<b>Base Street List</b>										
Bollinger Canyon Rd	St Marys Rd	Joseph Dr	16	C	2	1,725	46,575	Reconstruct Structure	\$72.00	\$372,600
Corliss Dr	Wakefield Dr	Camino Ricardo	27, 31	C	2	1,660	59,760	Reconstruct Structure	\$72.00	\$478,080
Del Monte Ct	Carter Dr	W End	14	R	2	670	19,430	Reconstruct Structure	\$52.00	\$112,262
Del Monte Wy	Carter Dr	S End	15	R	2	1,285	41,120	Reconstruct Structure	\$52.00	\$237,582
Larch Ave	#1160 Larch Ave	Camino Pablo	26 - 29	C	2	2,860	97,240	Reconstruct Structure	\$72.00	\$777,920
Natalie Dr	Campolindo Dr	Buckingham Dr	21 - 39	C	2	2,460	88,560	Reconstruct Structure	\$52.00	\$511,680
Scofield Dr	Harold Dr	Rheem Blvd	31, 32	R	2	2,255	72,160	Reconstruct Structure	\$52.00	\$416,924
<b>Base Street List Subtotals</b>							<b>12,915</b>			<b>\$2,907,049</b>
<b>Additional Street List</b>										
Alderbrook Pl	Fernwood Dr	N End	24	R	2	415	12,035	Reconstruct Structure	\$52.00	\$69,536
Chalda Wy	225ft N/O Williams Dr	Rheem Blvd	23	R	2	570	18,240	Thick Overlay	\$30.00	\$60,800
Country Club Dr	Southard Ct	Sandringham South	25	C	2	1,770	70,800	Reconstruct Structure	\$52.00	\$409,067
Harold Dr	Rheem Blvd	S End	25, 36	R	2	760	27,360	Reconstruct Structure	\$52.00	\$158,080
Marie Pl	W End	Larch Ave	23	R	2	235	6,580	Thick Overlay	\$30.00	\$21,933
Scofield Dr	Goodfellow Dr	Harold Dr	27	R	2	1,040	26,000	Reconstruct Structure	\$52.00	\$150,222
Winslow Pl	Corliss Dr	N End	25	R	2	170	6,120	Thick Overlay	\$30.00	\$20,400
<b>Additional Street List Subtotals</b>							<b>4,960</b>			<b>\$890,038</b>
<b>Grand Total</b>							<b>17,875</b>			<b>\$3,797,087</b>

## APPENDIX 2

### **Storm Drain Improvements for 2015 Street Pavement**

**Town of Moraga 2015 Street Pavement  
Storm Drain Repair, Rehabilitation, and Maintenance Projects DRAFT**

Street	From	To	Link_MUID	Size	Length	Observations	Severity	Project Type	Unit Cost	Qty	Cost	Cost + 40%
Alderbrook Place	Z3_Node_0029	Z3_Node_0027	Z3_Link_0045	24	63	Egg shape deformation and concrete obstacle	Heavy	Patch Repair	\$5,200	2	\$ 10,400	\$ 14,560
Alderbrook Place	Z3_Node_0030	Z3_Node_0027	Z3_Link_0037	24	221	Infiltration runner and concrete deposit	Average	CIPP	\$130	221	\$ 28,730	\$ 40,222
Alderbrook Place	Z3_Node_0031	Z3_Node_0030	Z3_Link_0038	24	135	Longitudinal Crack	Moderate	none	\$0	0	\$ -	\$ -
Alderbrook Place	Z3_Node_0032	Z3_Node_0031	Z3_Link_0039	24	113	Concrete in pipe and roots at joint	Light	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Bollinger	Z5_Node_0127	Z5_Node_0126	Z5_Link_0099	24	37	Long hinge, cut outs, sediment	Heavy	Cleaning & 2 Patch Repairs	\$10,950	1	\$ 10,950	\$ 15,330
Bollinger	Z5_Node_0126	outfall	unnamed link	24	62	Rocks	Average	Cleaning	\$275	2	\$ 550	\$ 770
Bollinger	Z5_Node_0130	Z5_Node_0126	Z5_Link_0098	24	39	sediment, clay soil buildup,	Moderate	none	\$0	1	\$ -	\$ -
Buckingham	Z1_Node_0046	Z1_Node_0045	Z1_Link_0199	24	148	Long hinge fracture, long cracks	Heavy	Cleaning & Patch Repairs	\$6,300	1	\$ 6,300	\$ 8,820
Buckingham	Z1_Node_0063	Z1_Node_0045	Z1_Link_0047	30	55	Rocks	Moderate	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Camino Pablo	Z7_Node_0228	Z7_Node_0226	Z7_Link_0202	15	15.1	collapsed, rerouted	Severe	none	\$0	\$	\$ -	\$ -
Camino Pablo	Z7_Node_0226	Z7_Node_0223	Z7_Link_0200	18	49	cracks	Average	none	\$0	\$	\$ -	\$ -
Camino Pablo	Z7_Node_0227	Z7_Node_0226	Z7_Link_0206	15	6	heavy debris, camera can't get through	Light	Cleaning Completed	\$0	0	\$ -	\$ -
Campolindo	Z1_Node_0013A	Z1_Node_0013		48	10	heavy sediment and water in pipe	Severe	Cleaning & 2 Patch Repairs	\$17,350	1	\$ 17,350	\$ 24,290
Campolindo	Z1_Node_0014	Z1_Node_0013A		48	140	long hinge, tree trunk in pipe	Severe	Cleaning	\$275	2	\$ 550	\$ 770
Campolindo	Z1_Node_0014A	Z1_Node_0013A		18	26	pipe broken in small section, storm filter	Severe	Patch Repair	\$4,320	1	\$ 4,320	\$ 6,048
Carter	Z5_Node_0054	Z5_Node_0053		15	45	Good condition	Good	none	\$0	\$	\$ -	\$ -
Corliss	Z4_Node_0161	Z4_Node_0160	Z4_Link_0053	30	612	Square cuts, infil stain, broken soil visible, fracture	Severe	Patch Repair	\$6,000	2	\$ 12,000	\$ 16,800
Corliss	Z4_Node_0168	Z4_Node_0167	Z4_Link_0070	15	0	Outlet is 50% covered with concrete, NEEDS repair	Severe	Private Cleaning	\$275	56	\$ 15,400	\$ 21,560
Corliss	Z4_Node_0091	Z4_Node_0071	Z4_Link_0088	24	112	Crack, rocks, clay soil	Heavy	CIPP	\$130	112	\$ 14,560	\$ 20,384
Corliss	Z4_Node_0093	Z4_Node_0092	Z4_Link_0090	24	0	1/2 pipe full sediment, needs cleaning	Heavy	Cleaning Completed	\$0	0	\$ -	\$ -
Corliss	Z4_Node_0177	Z4_Node_0162	Z4_Link_0058	18	145	Fracture, roots at joint	Heavy	Patch Repair	\$4,320	1	\$ 4,320	\$ 6,048
Corliss	Z4_Node_0071	Z4_Node_0070	Z4_Link_0050	30	575	Infil stains, roots intruding,	Average	Patch Repair	\$6,000	2	\$ 12,000	\$ 16,800
Corliss	Z4_Node_0163	Z4_Node_0162	Z4_Link_0055	24	295	Infil, deposits	Average	none	\$0	0	\$ -	\$ -
Corliss	Z4_Node_0171	Z4_Node_0161	Z4_Link_0061	18	43	Construction debris	Moderate	Cleaning	\$275	2	\$ 550	\$ 770
Corliss	Z4_Node_0172	Z4_Node_0171	Z4_Link_0062	18	92	Long cracks	Moderate	Patch Repair	\$4,320	2	\$ 8,640	\$ 12,096
Corliss	Z4_Node_0092	Z4_Node_0091	Z4_Link_0089	24	102	1/4 full sediment, needs cleaning, crack	Light	Cleaning Completed	\$0	0	\$ -	\$ -
Corliss	Z4_Node_0159	Z4_Node_0160	Z4_Link_0052	30	39	Infil stains	Light	none	\$0	0	\$ -	\$ -
Corliss	Z4_Node_0162	Z4_Node_0161	Z4_Link_0054	24	185	Infil stains	Light	none	\$0	0	\$ -	\$ -
Corliss	Z4_Node_0164	Z4_Node_0163	Z4_Link_0057	18	367	Good condition	Good	none	\$0	0	\$ -	\$ -
Corliss	Z4_Node_0167	Z4_Node_0166	Z4_Link_0069	15	32	Good condition	Good	none	\$0	0	\$ -	\$ -
Corliss	Z4_Node_0176	Z4_Node_0161	Z4_Link_0059	18	140	Good condition	Good	none	\$0	0	\$ -	\$ -
Corliss	Z4_Node_0178	Z4_Node_0163	Z4_Link_0056	18	59	Good condition	Good	none	\$0	0	\$ -	\$ -
Country Club	Z7_Node_0088	Z7_Node_0087	Z7_Link_0078	15	21	Same as one above, reverse direction	Heavy	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Country Club	Z7_Node_0089	Z7_Node_0087	Z7_Link_0079	24	294	Tap breaking, pipe in good condition	Good	none	\$0	0	\$ -	\$ -
Country Club	Z7_Node_0099	Z7_Node_0089	Z7_Link_0080	24	208	Good condition	Good	none	\$0	0	\$ -	\$ -
Country Club	Z7_Node_0100	Z7_Node_0099	Z7_Link_0081	18	34	Clay soil, good condition	Good	none	\$0	0	\$ -	\$ -
Del Monte	Z5_Node_0086	Z5_Node_0064	unnamed link	48	4	1/2 full of debris, NEEDS CLENAING	Severe	Cleaning	\$275	56	\$ 15,400	\$ 21,560
Del Monte Ct	Z5_Node_0046	Z5_Node_0045	Z5_Link_0060	24	169	Offset joint	Light	none	\$0	0	\$ -	\$ -
Del Monte Ct	Z5_Node_0047	Z5_Node_0046	Z5_Link_0061	24	83	Good condition	Good	none	\$0	0	\$ -	\$ -
Del Monte Ct	Z5_Node_0048	Z5_Node_0047	Z5_Link_0062	21	133	Good condition	Good	none	\$0	0	\$ -	\$ -
Del Monte Way	Z5_Node_0056	Z5_Node_0050	Z5_Link_0065	15	220	Broken pipe, deposits, and chip	Severe	Patch Repair	\$4,000	1	\$ 4,000	\$ 5,600
Del Monte Way	Z5_Node_0053	Z5_Node_0050	Z5_Link_0067	24	45	Good condition	Good	none	\$0	0	\$ -	\$ -
Del Rio	Z5_Node_0057	Z5_Node_0056	Z5_Link_0066	15	39	Large amount of clay, NEEDS CLEANING	Severe	Cleaning Completed	\$0	0	\$ -	\$ -
Goodfellow	Z2_Node_0164	Z2_Node_0163		18	26	Good condition	Good	none	\$0	0	\$ -	\$ -
Larch	Z7_Node_0242	Z7_Node_0243	Z7_Link_0224	18	62	broken, rebar exposed,	Severe	Patch Repair	\$4,320	2	\$ 8,640	\$ 12,096
Larch	Z7_Node_0256	Z7_Node_0255	Z7_Link_0213	15	0	Concrete blocking pipe	Severe	none	\$0	0	\$ -	\$ -
Larch	Z7_Node_0233	Z7_Node_0232	Z7_Link_0214	30	180	long hinge, cut outs,	Heavy	Patch Repair	\$6,000	1	\$ 6,000	\$ 8,400
Larch	Z7_Node_0245	Z7_Node_0244	Z7_Link_0226	18	34	Settled gravel,	Heavy	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Larch	Z7_Node_0246	Z7_Node_0244	Z7_Link_0225	24	120	Concrete debris, cut outs, sediment	Heavy	Cleaning	\$275	8	\$ 2,200	\$ 3,080
Larch	Z7_Node_0247	Z7_Node_0248	Z7_Link_0223	18	33	Deposits, gravel,	Heavy	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Larch	Z7_Node_0256	Z7_Node_0255	Z7_Link_0213	15	12	rocks in the way	Heavy	Cleaning Completed	\$0	0	\$ -	\$ -
Larch	Z7_Node_0257	Z7_Node_0254	Z7_Link_0211	42	77	clay soil, large rocks	Heavy	Cleaning Completed	\$0	0	\$ -	\$ -

**Town of Moraga 2015 Street Pavement  
Storm Drain Repair, Rehabilitation, and Maintenance Projects DRAFT**

Street	From	To	Link_MUID	Size	Length	Observations	Severity	Project Type	Unit Cost	Qty	Cost	Cost + 40%
Larch	Z7_Node_0254	Z7_Node_0253	Z7_Link_0210	42	207	fracture long, roots in joint	Average	Patch Repair	\$7,600	2	\$ 15,200	\$ 21,280
Larch	Z7_Node_0255	Z7_Node_0254	Z7_Link_0212	15	68	heavy rock and concrete	Average	Cleaning	\$275	16	\$ 4,400	\$ 6,160
Larch	Z7_Node_0234	Z7_Node_0233	Z7_Link_0215	18	37	construction debris,	Moderate	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Larch	Z7_Node_0241	Z7_Node_0236	Z7_Link_0218	24	386	heavy debris, water, sag in pipe	Moderate	Cleaning	\$275	6	\$ 1,650	\$ 2,310
Larch	Z7_Node_0236	Z7_Node_0235	Z7_Link_0228	30	141	cut outs,	Good	none	\$0	\$	-	\$ -
Larch	Z7_Node_0237	Z7_Node_0236	Z7_Link_0217	18	40	Good condition	Good	none	\$0	\$	-	\$ -
Larch	Z7_Node_0242	Z7_Node_0241	Z7_Link_0220	24	43	cut outs, infil stain,	Good	none	\$0	\$	-	\$ -
Larch	Z7_Node_0244	Z7_Node_0243	Z7_Link_0221	24	200	cut outs, infil stain,	Good	none	\$0	\$	-	\$ -
Larch	Z7_Node_0248	Z7_Node_0244	Z7_Link_0222	24	541	Infil stain, cut outs, clay soil	Good	none	\$0	0	\$	\$ -
Natalie	Z1_Node_0019	Z1_Node_0015	Z1_Link_0052	24	290	Cut outs, soil visible, infil stains, clay soil, HOLE	Severe	Patch Repair	\$5,200	1	\$ 5,200	\$ 7,280
Natalie	Z1_Node_0020	Z1_Node_0019	Z1_Link_0183	18	34	Soil and rebar visible, offset joint	Severe	Patch Repair	\$4,320	1	\$ 4,320	\$ 6,048
Natalie	Z1_Node_0061	Z1_Node_0060	Z1_Link_0041	24	134	Rocks, long cracks, rocks	Severe	Patch Repair	\$5,200	2	\$ 10,400	\$ 14,560
Natalie	Z1_Node_0053	Z1_Node_0052	Z1_Link_0034	30	36	Rocks	Heavy	Cleaning Completed	\$0	0	\$	\$ -
Natalie	Z1_Node_0060	Z1_Node_0059	Z1_Link_0040	30	245	Broken, cut outs, clay soil	Heavy	Patch Repair	\$6,000	1	\$ 6,000	\$ 8,400
Natalie	Z1_Node_0021	Z1_Node_0020	Z1_Link_0184	18	130	Pipe broken	Average	Patch Repair	\$4,320	1	\$ 4,320	\$ 6,048
Natalie	Z1_Node_0025	Z1_Node_0024	Z1_Link_0055	24	56	Dead animal, 20% sediment	Average	Cleaning	\$275	2	\$ 550	\$ 770
Natalie	Z1_Node_0052	Z1_Node_0048	Z1_Link_0033	30	49	Rocks and debris	Average	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Natalie	Z1_Node_0053	Z1_Node_0052	Z1_Link_0034	30	302	Cut outs, long cracks, infil stain, large rocks	Average	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Natalie	Z1_Node_0058	Z1_Node_0053	Z1_Link_0035	30	206	Infil stains, cutouts, chipped,	Average	Patch Repair	\$6,000	1	\$ 6,000	\$ 8,400
Natalie	Z1_Node_0022	Z1_Node_0019	Z1_Link_0056	18	154	Tap breaking, gravel deposit	Moderate	none	\$0	0	\$	\$ -
Natalie	Z1_Node_0050	Z1_Node_0049	Z1_Link_0043	18	43	Sediment and rocks	Moderate	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Natalie	Z1_Node_0023	Z1_Node_0019	Z1_Link_0053	24	392	Cut outs	Light	none	\$0	0	\$	\$ -
Natalie	Z1_Node_0059	Z1_Node_0058	Z1_Link_0039	30	37	Fracture, RCP to metal pipe	Light	none	\$0	0	\$	\$ -
Natalie	Z1_Node_0015	Z1_Node_0067		24	173	Good condition	Good	none	\$0	0	\$	\$ -
Natalie	Z1_Node_0016	Z1_Node_0015	Z1_Link_0182	18	33	Good condition	Good	none	\$0	0	\$	\$ -
Natalie	Z1_Node_0049	Z1_Node_0048	Z1_Link_0029	30	45	Cut outs, clay soil,	Good	none	\$0	4	\$	\$ -
Natalie	Z1_Node_0064	Z1_Node_0058	Z1_Link_0036	30	149	Cut outs, clay soil,	Good	none	\$0	\$	\$	\$ -
Sandringham	Z7_Node_0092	Z7_Node_0091	Z7_Link_0092	24	123	Broken, rebar visible,	Heavy	Patch Repair	\$5,200	1	\$ 5,200	\$ 7,280
Sandringham	Z7_Node_0090	Z7_Node_0089	Z7_Link_0090	24	118	Broken, rebar exposed	Average	Patch Repair	\$5,200	2	\$ 10,400	\$ 14,560
Sandringham	Z7_Node_0093	Z7_Node_0092	Z7_Link_0093	24	104	1/4 pipe full sediment,	Light	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Sandringham	Z7_Node_0091	Z7_Node_0090	Z7_Link_0091	24	56	Good condition	Good	none	\$0	0	\$	\$ -
Scofield	Z2_Node_0125	Z2_Node_0124	Z2_Link_0087	18	110	Long. Cracks, rocks, broken, broken with void	Severe	Private Replacement	\$270	110	\$ 29,700	\$ 41,580
Scofield	Z2_Node_0162	Z2_Node_0160	Z2_Link_0110	24	83	Long. Cracks	Severe	Private Replacement	\$325	83	\$ 26,975	\$ 37,765
Scofield	Z2_Node_0163	Z2_Node_0162		24	97	Long. Cracks, broken, severely damaged, private	Severe	Private Replacement	\$325	97	\$ 31,525	\$ 44,135
Scofield	Z2_Node_0161	Z2_Node_0160	Z2_Link_0109	18	263	Broken, rebar exposed, diameter change 21-18	Heavy	Patch Repair	\$4,320	1	\$ 4,320	\$ 6,048
Scofield	Z2_Node_0159	Z2_Node_0157	Z2_Link_0107	18	136	Manhole 159 buried, rebar exposed,	Average	Patch Repair	\$4,320	1	\$ 4,320	\$ 6,048
Scofield	Z2_Node_0160	Z2_Node_0159	Z2_Link_0108	21	199	Concrete deposits, long. Cracks	Average	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Scofield	Z2_Node_0065A	Z2_Node_0066A		18	215	Debris	Moderate	Cleaning	\$275	4	\$ 1,100	\$ 1,540
Scofield	Z2_Node_0066A	Z2_Node_0066		18	29	Separated medium, soil visible	Moderate	none	\$0	0	\$	\$ -
Scofield	Z2_Node_0065	Z2_Node_0066A		18	4	Good condition, add manhole 66A to GIS	Good	none	\$0	0	\$	\$ -
Scofield	Z2_Node_0103	Z2_Node_0102		18	37	Good condition	Good	none	\$0	0	\$	\$ -
Scofield	Z2_Node_0114	Z2_Node_0113		30	31	Good condition	Good	none	\$0	0	\$	\$ -
Scofield	Z2_Node_0126	Z2_Node_0125	Z2_Link_0088	18	34	Good condition	Good	none	\$0	0	\$	\$ -
Scofield	Z2_Node_0156	Z2_Node_0158		21	23	Good condition	Good	none	\$0	0	\$	\$ -

## APPENDIX 3

### **Street Improvement Maps**

**Town of Moraga  
2015 Pavement Repair  
Storm Drain Projects**

**Alderbrook Place**

**Pipe Impairment Severity**

— 1-Light

— 2-Moderate

— 3-Average

— 4-Heavy

— 5-Severe

— No Impairment

— 2015 Street Repavements

0 25 50 75 100 Feet




Z3\_NODE\_0032


Z3\_NODE\_0031


Z3\_NODE\_0030


Z3\_NODE\_0029

N












## Schaaf & Wheeler
















# APPENDIX D

## Capacity Improvement Project Sheets

<b>A. Project ID: C01</b>	<b>B. Project Name: Paseo Grande</b>																															
<b>C. Project Location: Intersection of Paseo Grande and Paseo Del Rio</b>																																
<b>D. Priority: High (Capacity)</b>																																
<b>E. Project Description:</b> Overflows occur on both Paseo Grande and Paseo Del Rio. This is a location where two large systems combine into an undersized 60-inch pipe that travels under Campolindo High School. Project includes replacing two pipes on Paseo Del Rio, three pipes on Paseo Grande, and two pipes on private property.																																
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr><td>42</td><td>54</td><td>36</td><td>51</td></tr> <tr><td>48</td><td>54</td><td>30</td><td>237</td></tr> <tr><td>48</td><td>54</td><td>30</td><td>542</td></tr> <tr><td>54</td><td>66</td><td>36</td><td>192</td></tr> <tr><td>54</td><td>66</td><td>36</td><td>89</td></tr> <tr><td>60</td><td>66</td><td>30</td><td>172</td></tr> <tr><td>60</td><td>66</td><td>30</td><td>149</td></tr> </tbody> </table>	Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	42	54	36	51	48	54	30	237	48	54	30	542	54	66	36	192	54	66	36	89	60	66	30	172	60	66	30	149
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)																													
42	54	36	51																													
48	54	30	237																													
48	54	30	542																													
54	66	36	192																													
54	66	36	89																													
60	66	30	172																													
60	66	30	149																													
<b>F. Project Cost.....</b>	<b>\$1,256,500</b>																															
<b>G. Contingency.....</b>	<b><u>\$377,000</u></b>																															
<b>H. Total Preliminary CIP Cost.....</b>	<b>\$1,633,500</b>																															
 <p>Note: Dimensions shown are for improved pipe diameters.</p> <table border="1"> <tr> <td>Project: Paseo Grande</td> <td>Priority: High</td> <td> <b>Priority</b>            High (Private, Outfall)            Moderate (Existing Pipe, Node)            Low (Stream)         </td> <td>  <b>Schaaf &amp; Wheeler</b>            CONSULTING CIVIL ENGINEERS         </td> </tr> <tr> <td colspan="2"></td> <td>  </td> <td></td> </tr> </table>		Project: Paseo Grande	Priority: High	<b>Priority</b> High (Private, Outfall) Moderate (Existing Pipe, Node) Low (Stream)	 <b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS																											
Project: Paseo Grande	Priority: High	<b>Priority</b> High (Private, Outfall) Moderate (Existing Pipe, Node) Low (Stream)	 <b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS																													
																																

<b>A. Project ID: C02</b>	<b>B. Project Name: School St.</b>																												
<b>C. Project Location: School St. to intersection with Hazelwood Pl.</b>																													
<b>D. Priority: High (Capacity)</b>																													
<b>E. Project Description:</b> Overflows occur on School St. This is a location where an undersized outlet and pipes are causing severe storm drain overflows. Project includes rerouting existing outlet pipe to a higher capacity system, replacing three pipes on school St, replacing one pipe on Hazelwood Pl, and replacing the outlet pipe under private property.																													
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>N/A</td><td>36</td><td>N/A</td><td>351</td></tr> <tr> <td>18</td><td>36</td><td>33</td><td>102</td></tr> <tr> <td>18</td><td>36</td><td>33</td><td>48</td></tr> <tr> <td>24</td><td>36</td><td>30</td><td>583</td></tr> <tr> <td>30</td><td>36</td><td>24</td><td>110</td></tr> <tr> <td>48</td><td>60</td><td>36</td><td>341</td></tr> </tbody> </table>		Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	N/A	36	N/A	351	18	36	33	102	18	36	33	48	24	36	30	583	30	36	24	110	48	60	36	341
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)																										
N/A	36	N/A	351																										
18	36	33	102																										
18	36	33	48																										
24	36	30	583																										
30	36	24	110																										
48	60	36	341																										
<b>F. Project Cost.....</b> <b>\$939,200</b>																													
<b>G. Contingency.....</b> <b>\$281,800</b>																													
<b>H. Total Preliminary CIP Cost.....</b> <b>\$1,221,000</b>																													
 <p>Project: School St.      Priority: High</p> <p><b>Priority</b></p> <ul style="list-style-type: none"> <li>High (Red)</li> <li>Moderate (Yellow)</li> <li>Low (Green)</li> </ul> <p><b>Legend</b></p> <ul style="list-style-type: none"> <li>Private (Red line)</li> <li>Other CIP (Blue line)</li> <li>Existing Pipe (Black line)</li> <li>Outfall (Blue triangle)</li> <li>Node (Blue diamond)</li> <li>Stream (Blue line)</li> </ul> <p>Note: Dimensions shown are for improved pipe diameters.</p> <p><b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS</p> <p>0 60 120 240 Feet</p>																													


<b>A. Project ID:</b> C03	<b>B. Project Name:</b> Campolindo																							
<b>C. Project Location:</b> Campolindo Dr. between Corte Mateo and Campolindo Ct.																								
<b>D. Priority:</b> Moderate (Capacity)																								
<b>E. Project Description:</b> Overflows caused by undersized pipes occur on Campolindo Dr. Project includes replacing five pipes on Campolindo Dr.																								
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>30</td><td>42</td><td>33</td><td>453</td></tr> <tr> <td>30</td><td>42</td><td>33</td><td>383</td></tr> <tr> <td>30</td><td>42</td><td>33</td><td>31</td></tr> <tr> <td>30</td><td>42</td><td>33</td><td>21</td></tr> <tr> <td>30</td><td>42</td><td>33</td><td>330</td></tr> </tbody> </table>	Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	30	42	33	453	30	42	33	383	30	42	33	31	30	42	33	21	30	42	33	330
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)																					
30	42	33	453																					
30	42	33	383																					
30	42	33	31																					
30	42	33	21																					
30	42	33	330																					
<b>F. Project Cost</b> ..... \$749,000																								
<b>G. Design Contingency</b> ..... <u>\$224,700</u>																								
<b>H. Total Preliminary CIP Cost</b> ..... \$973,700																								
 <p>Note: Dimensions shown are for improved pipe diameters.</p> <table border="1"> <tr> <td>Project: Campolindo</td> <td>Priority: Moderate</td> <td> <b>Priority</b>            High (Private)            Moderate (Existing Pipe)            Low (Stream)            ▲ Outfall            ● Node         </td> <td>  </td> <td> <b>Schaaf &amp; Wheeler</b>            CONSULTING CIVIL ENGINEERS   </td> </tr> </table>		Project: Campolindo	Priority: Moderate	<b>Priority</b> High (Private) Moderate (Existing Pipe) Low (Stream) ▲ Outfall ● Node		<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS 																		
Project: Campolindo	Priority: Moderate	<b>Priority</b> High (Private) Moderate (Existing Pipe) Low (Stream) ▲ Outfall ● Node		<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS 																				

<b>A. Project ID: C04</b>	<b>B. Project Name: Devin</b>																
<b>C. Project Location: Devin Dr. near intersection with Moraga Rd.</b>																	
<b>D. Priority: Moderate (Capacity)</b>																	
<b>E. Project Description:</b> Overflows caused by undersized pipes occur on Devin Dr. Project includes replacing two pipes under private property on Devin Dr. and one in the public right-of-way on Moraga Rd.																	
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>24</td><td>36</td><td>30</td><td>249</td></tr> <tr> <td>24</td><td>36</td><td>30</td><td>311</td></tr> <tr> <td>24</td><td>36</td><td>30</td><td>90</td></tr> </tbody> </table>	Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	24	36	30	249	24	36	30	311	24	36	30	90	
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)														
24	36	30	249														
24	36	30	311														
24	36	30	90														
<b>F. Project Cost.....</b>	<b>\$351,000</b>																
<b>G. Design Contingency.....</b>	<b>\$105,300</b>																
<b>H. Total Preliminary CIP Cost.....</b>	<b>\$456,300</b>																
 <p>Note: Dimensions shown are for improved pipe diameters.</p> <table border="1"> <tr> <td>Project: Devin</td> <td>Priority: Moderate</td> <td> <b>Priority</b>            High (Red)            Moderate (Yellow)            Low (Green)         </td> <td> <b>Symbol Legend</b>            ●: Private            —: Existing Pipe            —: Stream            ▲: Outfall            ◆: Node         </td> <td>  </td> <td> <b>Schaaf &amp; Wheeler</b>            CONSULTING CIVIL ENGINEERS         </td> </tr> <tr> <td colspan="2"></td> <td colspan="2"></td> <td>  </td> <td></td> </tr> </table>	Project: Devin	Priority: Moderate	<b>Priority</b> High (Red) Moderate (Yellow) Low (Green)	<b>Symbol Legend</b> ●: Private —: Existing Pipe —: Stream ▲: Outfall ◆: Node		<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS											
Project: Devin	Priority: Moderate	<b>Priority</b> High (Red) Moderate (Yellow) Low (Green)	<b>Symbol Legend</b> ●: Private —: Existing Pipe —: Stream ▲: Outfall ◆: Node		<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS												
																	

**A. Project ID: C05****B. Project Name: Camino Ricardo 1****C. Project Location: On Private Property Between Camino Ricardo & Woodside Dr.****D. Priority: Moderate (Capacity)**

**E. Project Description:** Overflows occur behind houses located along Camino Ricardo and Woodside Dr. Project includes replacing one pipe crossing Camino Ricardo and installing five new pipes along Camino Ricardo to move part of the system to public right-of-way.

Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)
N/A	24	N/A	51
N/A	24	N/A	109
N/A	24	N/A	420
N/A	24	N/A	470
N/A	24	N/A	318
N/A	24	N/A	491
18	36	33	43

**F. Project Cost..... \$707,300****G. Design Contingency..... \$212,200****H. Total Preliminary CIP Cost..... \$919,500**Project:  
CaminoRicardo1Priority:  
Moderate




Priority  
 — High  
 — Moderate  
 — Low

□: Private  
 —: Existing Pipe  
 —: Stream

▲: Outfall  
 •: Node



**Schaaf & Wheeler**  
 CONSULTING CIVIL ENGINEERS  
 0 60 120 240  
 Feet

<b>A. Project ID: C06</b>	<b>B. Project Name: Alta Mesa</b>																								
<b>C. Project Location: On Moraga Rd. South of Corner with Alta Mesa</b>																									
<b>D. Priority: Moderate (Capacity)</b>																									
<b>E. Project Description:</b> Significant storm drain overflows adjacent to Moraga Rd. occur where two steep pipes join into one relatively flat, undersized pipe. Project includes replacing one pipe under Moraga Rd. and four pipes that run under private property.																									
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr><td>36</td><td>48</td><td>30</td><td>337</td></tr> <tr><td>36</td><td>48</td><td>30</td><td>81</td></tr> <tr><td>36</td><td>48</td><td>30</td><td>237</td></tr> <tr><td>36</td><td>48</td><td>30</td><td>462</td></tr> <tr><td>36</td><td>48</td><td>30</td><td>99</td></tr> </tbody> </table>		Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	36	48	30	337	36	48	30	81	36	48	30	237	36	48	30	462	36	48	30	99
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)																						
36	48	30	337																						
36	48	30	81																						
36	48	30	237																						
36	48	30	462																						
36	48	30	99																						
<b>F. Project Cost.....</b> <b>\$833,800</b>																									
<b>G. Design Contingency.....</b> <b>\$250,100</b>																									
<b>H. Total Preliminary CIP Cost.....</b> <b>\$1,083,900</b>																									
 <p>Note: Dimensions shown are for improved pipe diameters.</p> <table border="1"> <tr> <td>Project: Alta Mesa</td> <td>Priority: Moderate</td> <td> <b>Priority</b>            — High            - - - Moderate            — Low         </td> <td>           ● Private            — Existing Pipe            — Stream         </td> <td>           ▲ Outfall            ◆ Node         </td> <td>  </td> <td> <b>Schaaf &amp; Wheeler</b>            CONSULTING CIVIL ENGINEERS   </td> </tr> </table>		Project: Alta Mesa	Priority: Moderate	<b>Priority</b> — High - - - Moderate — Low	● Private — Existing Pipe — Stream	▲ Outfall ◆ Node		<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS 																	
Project: Alta Mesa	Priority: Moderate	<b>Priority</b> — High - - - Moderate — Low	● Private — Existing Pipe — Stream	▲ Outfall ◆ Node		<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS 																			

**A. Project ID: C07****B. Project Name: Hazelwood****C. Project Location: Hazelwood Pl. near intersection with School St.****D. Priority: Moderate (Capacity)****E. Project Description:** Overflows caused by undersized pipes occur on Hazelwood Pl.

This project is adjacent to the School St. High Priority Project. Project includes replacing two pipes on Hazelwood Pl.


Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)
18	48	48	38
24	54	48	383

**F. Project Cost.....** **\$335,900**

**G. Design Contingency.....** **\$100,800**

**H. Total Preliminary CIP Cost.....** **\$436,700**



<b>A. Project ID: C08</b>	<b>B. Project Name: St. Andrews</b>																			
<b>C. Project Location: Corner of St. Andrews Dr. and Augusta Dr.</b>																				
<b>D. Priority: Moderate (Capacity)</b>																				
<b>E. Project Description:</b> Overflows caused by undersized pipes occur on the corner of St. Andrew's Dr. and Augusta Dr. Project includes replacing one pipe on Augusta Dr. and three pipes on St. Andrews Dr.																				
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>24</td><td>42</td><td>36</td><td>51</td></tr> <tr> <td>30</td><td>36</td><td>24</td><td>237</td></tr> <tr> <td>30</td><td>42</td><td>33</td><td>542</td></tr> <tr> <td>36</td><td>42</td><td>24</td><td>192</td></tr> </tbody> </table>	Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	24	42	36	51	30	36	24	237	30	42	33	542	36	42	24	192
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)																	
24	42	36	51																	
30	36	24	237																	
30	42	33	542																	
36	42	24	192																	
<b>F. Project Cost.....</b> <b>\$466,200</b>																				
<b>G. Design Contingency.....</b> <b>\$139,900</b>																				
<b>H. Total Preliminary CIP Cost.....</b> <b>\$606,100</b>																				
 <p><b>Note:</b> Dimensions shown are for improved pipe diameters.</p> <table border="1"> <tr> <td>Project: St. Andrews</td> <td>Priority: Moderate</td> <td> <b>Priority</b>            — High            — Moderate            — Low         </td> <td> <b>Private</b>            — Other CIP            — Existing Pipe         </td> <td> <b>Outfall</b>            ▲ Node            — Stream         </td> <td>           N   </td> <td> <b>Schaaf &amp; Wheeler</b>            CONSULTING CIVIL ENGINEERS         </td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>  </td> </tr> </table>		Project: St. Andrews	Priority: Moderate	<b>Priority</b> — High — Moderate — Low	<b>Private</b> — Other CIP — Existing Pipe	<b>Outfall</b> ▲ Node — Stream	N 	<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS												
Project: St. Andrews	Priority: Moderate	<b>Priority</b> — High — Moderate — Low	<b>Private</b> — Other CIP — Existing Pipe	<b>Outfall</b> ▲ Node — Stream	N 	<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS														
																				

**A. Project ID: C09****B. Project Name: Larch****C. Project Location: Larch Ave. Between Batix Dr. and Sparrow Ct.****D. Priority: Moderate (Capacity)**


**E. Project Description:** Overflows caused by undersized pipes occur on the Larch Ave. between Batix Dr. and Wandel Dr. Project includes replacing seven pipes along Larch Ave.

Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)
18	36	33	172
18	36	33	100
18	36	33	59
18	36	33	124
24	36	30	579
24	36	30	113
24	36	30	175

**F. Project Cost.....** **\$713,000**

**G. Design Contingency.....** **\$213,900**

**H. Total Preliminary CIP Cost.....** **\$926,900**



Project:  
Larch

Priority:  
Moderate

Priority  
High  
Moderate  
Low


Private  
Existing Pipe  
Stream

Outfall  
Node

N

**Schaaf & Wheeler**  
CONSULTING CIVIL ENGINEERS

0 60 120 240 Feet

<b>A. Project ID:</b> C10	<b>B. Project Name:</b> Thune																
<b>C. Project Location:</b> Thune Ave. Between Larch Ave. and Dickenson Dr.																	
<b>D. Priority:</b> Moderate (Capacity)																	
<b>E. Project Description:</b> Overflows caused by undersized pipes occur on Thune Ave. Project includes replacing one pipe on Thune Ave. and moving one pipe on private property to public right-of way.																	
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>24</td><td>36</td><td>36</td><td>598</td></tr> <tr> <td>N/A</td><td>36</td><td>N/A</td><td>356</td></tr> </tbody> </table>	Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	24	36	36	598	N/A	36	N/A	356					
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)														
24	36	36	598														
N/A	36	N/A	356														
<b>F. Project Cost</b> ..... \$478,500 <b>G. Design Contingency</b> ..... <u>\$143,600</u> <b>H. Total Preliminary CIP Cost</b> ..... \$622,100																	
 <p data-bbox="1013 1824 1393 1843">Note: Dimensions shown are for improved pipe diameters.</p> <table border="1" data-bbox="251 1843 1393 1926"> <tr> <td>Project: Thune</td> <td>Priority: Moderate</td> <td> <b>Priority</b>            High (red line)            Moderate (yellow line)            Low (green line)         </td> <td> <b>Private</b>            Private (red line)  <b>Existing Pipe</b>            Existing Pipe (black line)         </td> <td> <b>Outfall</b>            Outfall (purple line)         </td> <td> <b>Node</b>            Node (green diamond)         </td> <td>           N   </td> <td> <b>Schaaf &amp; Wheeler</b>            CONSULTING CIVIL ENGINEERS         </td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>  </td> <td>0 60 120 240 Feet</td> </tr> </table>	Project: Thune	Priority: Moderate	<b>Priority</b> High (red line) Moderate (yellow line) Low (green line)	<b>Private</b> Private (red line) <b>Existing Pipe</b> Existing Pipe (black line)	<b>Outfall</b> Outfall (purple line)	<b>Node</b> Node (green diamond)	N 	<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS								0 60 120 240 Feet	
Project: Thune	Priority: Moderate	<b>Priority</b> High (red line) Moderate (yellow line) Low (green line)	<b>Private</b> Private (red line) <b>Existing Pipe</b> Existing Pipe (black line)	<b>Outfall</b> Outfall (purple line)	<b>Node</b> Node (green diamond)	N 	<b>Schaaf &amp; Wheeler</b> CONSULTING CIVIL ENGINEERS										
							0 60 120 240 Feet										

A. Project ID: C11 – C19	B. Project Name:												
C. Project Location:													
D. Priority: Low (Capacity)													
E. Project Description: Minor overflows from Low Priority projects are shown in the figure below. See pages A.12 – A.14 for individual project descriptions.													
F. Low Priority Projects Cost.....	\$1,563,000												
G. Design Contingency.....	<u>\$470,000</u>												
H. Total Preliminary Low Priority CIP Cost.....	\$2,032,000												
Priority: Low	<table border="1"> <thead> <tr> <th>Priority</th> <th>Symbol</th> <th>Legend Description</th> </tr> </thead> <tbody> <tr> <td>High</td> <td>Red line</td> <td>Private</td> </tr> <tr> <td>Moderate</td> <td>Yellow line</td> <td>Other CIP</td> </tr> <tr> <td>Low</td> <td>Green line</td> <td>Existing Pipe</td> </tr> </tbody> </table> <p>Stream Outfall Node</p> <p>N</p> <p>Schaaf &amp; Wheeler CONSULTING CIVIL ENGINEERS</p> <p>0 700 1,400 2,800 Feet</p>	Priority	Symbol	Legend Description	High	Red line	Private	Moderate	Yellow line	Other CIP	Low	Green line	Existing Pipe
Priority	Symbol	Legend Description											
High	Red line	Private											
Moderate	Yellow line	Other CIP											
Low	Green line	Existing Pipe											

<b>A. Project ID:</b> C11	<b>B. Project Name:</b> Rheem																
<b>C. Project Location:</b> Rheem Blvd. Between Harold Dr. and Scofield Dr.																	
<b>D. Priority:</b> Low (Capacity)																	
<b>E. Project Description:</b> Minor overflows on Rheem Blvd. caused by undersized pipes crossing Rheem Blvd. Project includes pipes located on private property.																	
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>18</td><td>24</td><td>18</td><td>71</td></tr> <tr> <td>18</td><td>24</td><td>18</td><td>63</td></tr> <tr> <td>18</td><td>24</td><td>18</td><td>75</td></tr> </tbody> </table>		Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	18	24	18	71	18	24	18	63	18	24	18	75
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)														
18	24	18	71														
18	24	18	63														
18	24	18	75														
<b>F. Total Preliminary CIP Cost</b> ..... \$149,000																	

<b>A. Project ID:</b> C12	<b>B. Project Name:</b> Harold												
<b>C. Project Location:</b> Adjacent to Corner of Harold Dr. and Rheem Blvd.													
<b>D. Priority:</b> Low (Capacity)													
<b>E. Project Description:</b> Minor overflows on Rheem Blvd. caused by undersized pipes. Project includes pipes located on private property.													
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>21</td><td>30</td><td>24</td><td>124</td></tr> <tr> <td>21</td><td>30</td><td>24</td><td>62</td></tr> </tbody> </table>		Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	21	30	24	124	21	30	24	62
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)										
21	30	24	124										
21	30	24	62										
<b>F. Total Preliminary CIP Cost</b> ..... \$146,000													

<b>A. Project ID:</b> C13	<b>B. Project Name:</b> Scofield								
<b>C. Project Location:</b> 214 Scofield Dr.									
<b>D. Priority:</b> Low (Capacity)									
<b>E. Project Description:</b> Minor overflows on Scofield Dr. caused by an undersized pipe on Scofield Dr.									
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>18</td><td>24</td><td>18</td><td>206</td></tr> </tbody> </table>		Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	18	24	18	206
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)						
18	24	18	206						
<b>F. Total Preliminary CIP Cost</b> ..... \$116,000									

<b>A. Project ID:</b> C14	<b>B. Project Name:</b> Fernwood		
<b>C. Project Location:</b> 821 Fernwood Dr.			
<b>D. Priority:</b> Low (Capacity)			
<b>E. Project Description:</b> Minor flooding on Fernwood Dr. caused by an undersized pipe on Fernwood Dr.			
<b>Ex. Diameter (in)</b>	<b>Imp. Diameter (in)</b>	<b>Equivalent Parallel (in)</b>	<b>Length (ft)</b>
18	30	24	323
<b>F. Total Preliminary CIP Cost</b> ..... \$200,000			

<b>A. Project ID:</b> C15	<b>B. Project Name:</b> Camino Ricardo 2		
<b>C. Project Location:</b> Corner of Moraga Way, Camino Ricardo, and St. Andrews			
<b>D. Priority:</b> Low (Capacity)			
<b>E. Project Description:</b> Minor overflows on Camino Ricardo caused by an undersized pipe flowing under Moraga Way.			
<b>Ex. Diameter (in)</b>	<b>Imp. Diameter (in)</b>	<b>Equivalent Parallel (in)</b>	<b>Length (ft)</b>
48	54	30	159
<b>F. Total Preliminary CIP Cost</b> ..... \$184,000			

<b>A. Project ID:</b> C16	<b>B. Project Name:</b> Golf Course		
<b>C. Project Location:</b> Behind 782 Augusta Dr.			
<b>D. Priority:</b> Low (Capacity)			
<b>E. Project Description:</b> Minor overflows on golf course property caused by an undersized pipe behind 782 Augusta Dr. Pipe is located on private property.			
<b>Ex. Diameter (in)</b>	<b>Imp. Diameter (in)</b>	<b>Equivalent Parallel (in)</b>	<b>Length (ft)</b>
18	24	18	227
<b>F. Total Preliminary CIP Cost</b> ..... \$124,000			

<b>A. Project ID: C17</b>	<b>B. Project Name: Augusta</b>								
<b>C. Project Location:</b> On Golf Course Property near 651 Augusta Dr.									
<b>D. Priority: Low (Capacity)</b>									
<b>E. Project Description:</b> Minor overflows on Golf Course property caused by an undersized pipe traveling between 651 Augusta Dr. and the tennis courts. Pipe flows on private property.									
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>48</td><td>54</td><td>30</td><td>154</td></tr> </tbody> </table>		Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	48	54	30	154
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)						
48	54	30	154						
<b>F. Total Preliminary CIP Cost.....</b> <b>\$180,000</b>									


<b>A. Project ID: C18</b>	<b>B. Project Name: Wandel</b>																				
<b>C. Project Location:</b> Between houses located on Wandel Dr. and Flueti Dr.																					
<b>D. Priority: Low (Capacity)</b>																					
<b>E. Project Description:</b> Undersized pipes located on private property cause minor overflows between houses.																					
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>30</td><td>36</td><td>24</td><td>89</td></tr> <tr> <td>30</td><td>36</td><td>24</td><td>116</td></tr> <tr> <td>30</td><td>36</td><td>24</td><td>217</td></tr> <tr> <td>34</td><td>36</td><td>18</td><td>334</td></tr> </tbody> </table>		Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	30	36	24	89	30	36	24	116	30	36	24	217	34	36	18	334
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)																		
30	36	24	89																		
30	36	24	116																		
30	36	24	217																		
34	36	18	334																		
<b>F. Total Preliminary CIP Cost.....</b> <b>\$537,000</b>																					


<b>G. Project ID: C19</b>	<b>H. Project Name: Deerfield</b>																
<b>I. Project Location:</b> Deerfield Dr. between Stonefield Pl. and Tharp Dr.																	
<b>J. Priority: Low (Capacity)</b>																	
<b>K. Project Description:</b> Minor overflows on Deerfield Dr. caused by undersized pipes.																	
<table border="1"> <thead> <tr> <th>Ex. Diameter (in)</th><th>Imp. Diameter (in)</th><th>Equivalent Parallel (in)</th><th>Length (ft)</th></tr> </thead> <tbody> <tr> <td>24</td><td>42</td><td>36</td><td>245</td></tr> <tr> <td>36</td><td>42</td><td>24</td><td>51</td></tr> <tr> <td>36</td><td>42</td><td>24</td><td>249</td></tr> </tbody> </table>		Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)	24	42	36	245	36	42	24	51	36	42	24	249
Ex. Diameter (in)	Imp. Diameter (in)	Equivalent Parallel (in)	Length (ft)														
24	42	36	245														
36	42	24	51														
36	42	24	249														
<b>L. Total Preliminary CIP Cost.....</b> <b>\$396,000</b>																	


## APPENDIX E

### Culvert Improvement Project Sheets


<b>A. Project ID: CC01</b>	<b>B. Project Name: Moraga Creek at St Andrews Drive (MC3)</b>									
<b>C. Project Location: St. Andrews Drive near Moraga Country Club Tennis Courts</b>										
<b>D. Priority: High (Capacity)</b>										
<b>E. Project Type: Culvert</b>										
<b>F. Project Description:</b> Creek flooding occurs at Moraga Country Club upstream of the culvert under St Andrews Drive. Upsizing the existing arch culvert to convey the 100-year flood flow and reduce creek flooding to below building pad elevations is recommended.										
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>22' x 8' Arch</td> <td>22' x 10' Box</td> <td>60</td> </tr> </tbody> </table>		Ex. Size	Imp. Size	Length (ft)	22' x 8' Arch	22' x 10' Box	60			
Ex. Size	Imp. Size	Length (ft)								
22' x 8' Arch	22' x 10' Box	60								
<b>G. Project Cost</b> ..... \$725,000										
<b>H. Contingency</b> ..... \$218,000										
<b>I. Total Preliminary CIP Cost</b> ..... \$943,000										
 <p><b>Project:</b> Moraga Creek at St Andrews Drive    <b>Priority:</b> High</p> <table border="1"> <tr> <td>Stream</td> <td>Priority</td> <td>Outfall</td> </tr> <tr> <td>Existing Pipe</td> <td>High</td> <td>Node</td> </tr> <tr> <td>Other CIPs</td> <td>Moderate</td> <td></td> </tr> </table> <p><b>Schaaf &amp; Wheeler Consulting Civil Engineers</b></p> <p>0 25 50 100 Feet</p>		Stream	Priority	Outfall	Existing Pipe	High	Node	Other CIPs	Moderate	
Stream	Priority	Outfall								
Existing Pipe	High	Node								
Other CIPs	Moderate									

<b>A. Project ID: CC02</b>	<b>B. Project Name: South Moraga Cr. at Camino Pablo (SMC2)</b>						
<b>C. Project Location: South Moraga Creek culvert under Camino Pablo</b>							
<b>D. Priority: High (Capacity)</b>							
<b>E. Project Description:</b> Creek flooding occurs upstream of the culvert between Larch Ave. and Sanders Ranch Rd. Upsizing the existing pipe culvert to convey 100-year flood flow is recommended.							
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>78" Pipe</td> <td>96" Pipe</td> <td>120</td> </tr> </tbody> </table>		Ex. Size	Imp. Size	Length (ft)	78" Pipe	96" Pipe	120
Ex. Size	Imp. Size	Length (ft)					
78" Pipe	96" Pipe	120					
<b>F. Project Cost</b> ..... \$267,000							
<b>G. Contingency</b> ..... <u>\$80,000</u>							
<b>H. Total Preliminary CIP Cost</b> ..... <b>\$347,000</b>							
							
Project: South Moraga Cr. at Camino Pablo	Priority: High						
Stream Existing Pipe Other CIPs	Priority High Moderate Low						
	 						
<b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers							
0 25 50 100 Feet							

<b>A. Project ID: CC03</b>	<b>B. Project Name: Laguna Creek at Woodford (LC2)</b>						
<b>C. Project Location: Laguna Creek culvert under Woodford Drive at Moraga Road</b>							
<b>D. Priority: High (Capacity)</b>							
<b>E. Project Description:</b> Creek flooding occurs upstream of Woodford Dr. near Campolindo High School. Upsizing the existing pipe culvert under Woodford Dr. to convey the 100-year flood flow is recommended.							
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>42" Pipe</td> <td>84" Pipe</td> <td>820</td> </tr> </tbody> </table>		Ex. Size	Imp. Size	Length (ft)	42" Pipe	84" Pipe	820
Ex. Size	Imp. Size	Length (ft)					
42" Pipe	84" Pipe	820					
<b>F. Project Cost</b> ..... \$1,528,000							
<b>G. Contingency</b> ..... <u>\$458,000</u>							
<b>H. Total Preliminary CIP Cost</b> ..... \$1,986,000							
							
Project: Laguna Creek at Woodford	Priority: High <ul style="list-style-type: none"> <li>Stream</li> <li>Existing Pipe</li> <li>Other CIPs</li> </ul> <ul style="list-style-type: none"> <li>▲ Outfall</li> <li>● Node</li> </ul>						
<table border="1"> <tr> <td style="text-align: center;"> Priority  <span style="color: red;">■</span> High  <span style="color: yellow;">■</span> Moderate  <span style="color: green;">■</span> Low </td> <td style="text-align: center;"> N </td> <td style="text-align: center;"> <b>Schaaf &amp; Wheeler</b>  Consulting Civil Engineers </td> </tr> </table>		Priority <span style="color: red;">■</span> High <span style="color: yellow;">■</span> Moderate <span style="color: green;">■</span> Low	N	<b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers			
Priority <span style="color: red;">■</span> High <span style="color: yellow;">■</span> Moderate <span style="color: green;">■</span> Low	N	<b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers					
0 50 100 200 Feet							

<b>A. Project ID: CC04</b>	<b>B. Project Name: Laguna Creek at Hacienda (LC5)</b>															
<b>C. Project Location: Laguna Creek culvert at Hacienda de las Flores</b>																
<b>D. Priority: High</b>																
<b>E. Project Type: Culvert</b>																
<b>F. Project Description:</b> Creek flooding occurs upstream of the culvert in the Hacienda de las Flores development. Upsizing the existing pipe culvert to convey 100-year flood flow is recommended. This project is currently being studied by WRECA and improvements should be coordinated with the detailed study.																
	<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>96" Pipe</td> <td>8' x 10' Box</td> <td>225</td> </tr> </tbody> </table>	Ex. Size	Imp. Size	Length (ft)	96" Pipe	8' x 10' Box	225									
Ex. Size	Imp. Size	Length (ft)														
96" Pipe	8' x 10' Box	225														
<b>G. Project Cost</b> .....	\$1,106,000															
<b>H. Contingency</b> .....	<u>\$332,000</u>															
<b>I. Total Preliminary CIP Cost</b> .....	<b>\$1,438,000</b>															
 <p>The map displays an aerial view of a residential area with several streets labeled: Moraga Rd, Devin Dr, and Hacienda de las Flores. A stream network is shown in blue, with a red line indicating the existing pipe. A proposed culvert is shown as a blue line with a red segment. A north arrow is present, and a scale bar indicates 0, 25, 50, and 100 feet. An inset map in the top left corner shows the project's location within the Moraga area, with the Rileem River and surrounding roads labeled.</p>																
Project: Laguna Creek at Hacienda	Priority: High	<table> <tr> <td>Stream</td> <td>Priority</td> </tr> <tr> <td>— Existing Pipe</td> <td>High</td> </tr> <tr> <td>— Other CIPs</td> <td>Moderate</td> </tr> <tr> <td>—</td> <td>Low</td> </tr> </table>	Stream	Priority	— Existing Pipe	High	— Other CIPs	Moderate	—	Low	<table> <tr> <td>▲ Outfall</td> </tr> <tr> <td>● Node</td> </tr> </table>	▲ Outfall	● Node		<b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers	
Stream	Priority															
— Existing Pipe	High															
— Other CIPs	Moderate															
—	Low															
▲ Outfall																
● Node																

<b>A. Project ID: CC05</b>	<b>B. Project Name: Moraga Creek at Ivy Drive (MC1)</b>						
<b>C. Project Location: Moraga Creek culvert under Ivy Drive at Moraga Way</b>							
<b>D. Priority: Moderate</b>							
<b>E. Project Type: Culvert</b>							
<b>F. Project Description:</b> Some creek flooding occurs upstream of Ivy Drive. Upsizing the existing arch culvert under Ivy Drive to convey 100-year flood flow is recommended. This project lies on the border between Orinda and Moraga, and will require coordination with the City of Orinda.							
<table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Diameter (in)</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>12.6' x 8' Arch</td> <td>15' x 9' Box</td> <td>46</td> </tr> </tbody> </table>		Ex. Size	Imp. Diameter (in)	Length (ft)	12.6' x 8' Arch	15' x 9' Box	46
Ex. Size	Imp. Diameter (in)	Length (ft)					
12.6' x 8' Arch	15' x 9' Box	46					
<b>G. Project Cost</b> .....	<b>\$354,000</b>						
<b>H. Contingency</b> .....	<b>\$106,000</b>						
<b>I. Total Preliminary CIP Cost</b> .....	<b>\$460,000</b>						
Project: Moraga Creek at Ivy Drive	Priority: Moderate	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%; vertical-align: top;"> <span style="color: blue;">—</span> Stream  <span style="color: black;">—</span> Existing Pipe  <span style="color: darkblue;">—</span> Other CIPs         </td> <td style="width: 25%; vertical-align: top;"> <span style="color: red;">■</span> High  <span style="color: yellow;">■</span> Moderate  <span style="color: green;">■</span> Low         </td> <td style="width: 25%; vertical-align: top;"> <span style="color: purple;">▲</span> Outfall  <span style="color: black;">●</span> Node         </td> <td style="width: 25%; vertical-align: top;"> <span style="color: black;">N</span>  </td> </tr> </table>	<span style="color: blue;">—</span> Stream <span style="color: black;">—</span> Existing Pipe <span style="color: darkblue;">—</span> Other CIPs	<span style="color: red;">■</span> High <span style="color: yellow;">■</span> Moderate <span style="color: green;">■</span> Low	<span style="color: purple;">▲</span> Outfall <span style="color: black;">●</span> Node	<span style="color: black;">N</span> 	<b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers 
<span style="color: blue;">—</span> Stream <span style="color: black;">—</span> Existing Pipe <span style="color: darkblue;">—</span> Other CIPs	<span style="color: red;">■</span> High <span style="color: yellow;">■</span> Moderate <span style="color: green;">■</span> Low	<span style="color: purple;">▲</span> Outfall <span style="color: black;">●</span> Node	<span style="color: black;">N</span> 				


<b>A. Project ID: CC06</b>	<b>B. Project Name: St. Mary's Tributary at St. Mary's Rd. (STM2)</b>														
<b>C. Project Location: St. Mary's Tributary culvert under St. Mary's Road</b>															
<b>D. Priority: Moderate</b>															
<b>E. Project Description:</b> Creek flooding occurs on the south side of St. Mary's Road. Upsizing the existing double barrel pipe culvert under St Mary's Road to a larger box section to convey 100-year flood flow is recommended.															
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>Two 48" Pipes</td> <td>9' x 5' Box</td> <td>75</td> </tr> </tbody> </table>		Ex. Size	Imp. Size	Length (ft)	Two 48" Pipes	9' x 5' Box	75								
Ex. Size	Imp. Size	Length (ft)													
Two 48" Pipes	9' x 5' Box	75													
<b>F. Project Cost</b> ..... \$216,000															
<b>G. Contingency</b> ..... <u>\$65,000</u>															
<b>H. Total Preliminary CIP Cost</b> ..... \$281,000															
															
Project: St. Mary's Trib at St. Mary's Road	Priority: Moderate	<table> <tr> <td>Stream</td> <td>Priority</td> </tr> <tr> <td>Existing Pipe</td> <td>High</td> </tr> <tr> <td>Other CIPs</td> <td>Moderate</td> </tr> <tr> <td></td> <td>Low</td> </tr> </table>	Stream	Priority	Existing Pipe	High	Other CIPs	Moderate		Low	<table> <tr> <td>▲ Outfall</td> </tr> <tr> <td>● Node</td> </tr> </table>	▲ Outfall	● Node		<b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers
Stream	Priority														
Existing Pipe	High														
Other CIPs	Moderate														
	Low														
▲ Outfall															
● Node															
															


<b>A. Project ID: CC07</b>	<b>B. Project Name: Ivy Drive Tributary at Moraga Way (ID2)</b>															
<b>C. Project Location: Ivy Drive Tributary culvert under Moraga Way</b>																
<b>D. Priority: Moderate</b>																
<b>E. Project Type: Culvert</b>																
<b>F. Project Description:</b> Creek flooding occurs on the Ivy Drive Tributary upstream of Moraga Way near residences. Upsizing the existing pipe culvert to convey 100-year flood flow into Moraga Creek is recommended.																
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>66" Pipe</td> <td>8' x 5.5' Box</td> <td>85</td> </tr> </tbody> </table>		Ex. Size	Imp. Size	Length (ft)	66" Pipe	8' x 5.5' Box	85									
Ex. Size	Imp. Size	Length (ft)														
66" Pipe	8' x 5.5' Box	85														
<b>G. Project Cost</b> ..... \$242,000																
<b>H. Contingency</b> ..... <u>\$73,000</u>																
<b>I. Total Preliminary CIP Cost</b> ..... \$315,000																
																
Project: Ivy Drive Tributary at Moraga Way	Priority: Moderate	<table> <tr> <td>Stream</td> <td>Priority</td> <td>Outfall</td> </tr> <tr> <td>Existing Pipe</td> <td>High</td> <td>Node</td> </tr> <tr> <td>Other CIPs</td> <td>Moderate</td> <td></td> </tr> <tr> <td></td> <td>Low</td> <td></td> </tr> </table>	Stream	Priority	Outfall	Existing Pipe	High	Node	Other CIPs	Moderate			Low			<b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers
Stream	Priority	Outfall														
Existing Pipe	High	Node														
Other CIPs	Moderate															
	Low															
																

<b>A. Project ID: CC08</b>	<b>B. Project Name: Corliss Drive Tributary at Corliss Drive (CD1)</b>								
<b>C. Project Location: Corliss Drive Tributary culvert under Corliss Drive</b>									
<b>D. Priority: Moderate</b>									
<b>E. Project Type: Culvert</b>									
<b>F. Project Description:</b> Minor creek flooding occurs upstream of Corliss Drive near Crossbrook Drive. Upsizing the existing pipe culvert to convey the 100-year flood flow is recommended.									
<table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>68" Pipe</td> <td>8' x 5' Box</td> <td>80</td> </tr> </tbody> </table>				Ex. Size	Imp. Size	Length (ft)	68" Pipe	8' x 5' Box	80
Ex. Size	Imp. Size	Length (ft)							
68" Pipe	8' x 5' Box	80							
<b>G. Project Cost</b> ..... \$206,000									
<b>H. Contingency</b> ..... <u>\$62,000</u>									
<b>I. Total Preliminary CIP Cost</b> ..... \$268,000									
									
Project: Corliss Drive Trib at Corliss Drive	Priority: Moderate	Stream — Existing Pipe — Other CIPs	Priority High Moderate Low						
		▲ Outfall ● Node	 <b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers						
			0 25 50 100 Feet						

<b>A. Project ID: CC09</b>	<b>B. Project Name: Moraga Creek at Miramonte Drive (MC2)</b>													
<b>C. Project Location: Moraga Creek culvert under Miramonte Drive at Moraga Way</b>														
<b>D. Priority: Moderate</b>														
<b>E. Project Type: Culvert</b>														
<b>F. Project Description:</b> Creek flooding occurs at Miramonte Drive. Upsizing the culvert under Miramonte Drive to convey 100-year flood flow is recommended.														
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>15' x 8.5' Arch</td> <td>20' x 9' Box</td> <td>70</td> </tr> </tbody> </table>			Ex. Size	Imp. Size	Length (ft)	15' x 8.5' Arch	20' x 9' Box	70						
Ex. Size	Imp. Size	Length (ft)												
15' x 8.5' Arch	20' x 9' Box	70												
<b>G. Project Cost</b> ..... \$699,000														
<b>H. Contingency</b> ..... \$210,000														
<b>I. Total Preliminary CIP Cost</b> ..... \$909,000														
														
Project: Moraga Creek at Miramonte Drive	Priority: Moderate	<table> <tr> <td>Stream</td> <td>Priority</td> <td>Outfall</td> </tr> <tr> <td>Existing Pipe</td> <td>High</td> <td>• Node</td> </tr> <tr> <td>Other CIPs</td> <td>Moderate</td> <td>▲</td> </tr> <tr> <td></td> <td>Low</td> <td></td> </tr> </table>  0 30 60 120 Feet	Stream	Priority	Outfall	Existing Pipe	High	• Node	Other CIPs	Moderate	▲		Low	
Stream	Priority	Outfall												
Existing Pipe	High	• Node												
Other CIPs	Moderate	▲												
	Low													

<b>A. Project ID: CC10</b>	<b>B. Project Name: Ivy Drive Tributary at Ivy Drive (ID1)</b>													
<b>C. Project Location: Ivy Drive Tributary culvert under Ivy Drive near Ramona Drive</b>														
<b>D. Priority: Moderate</b>														
<b>E. Project Description:</b> Creek flooding occurs on Ivy Drive Tributary upstream of Ivy Drive, between residences. Upsizing the culvert under Ivy Drive is recommended. This project lies on or near the border between Orinda and Moraga, and will require coordination with the City of Orinda.														
	<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>Two 5.8' x 3.75' Arches</td> <td>Two 6' x 4.5' Boxes</td> <td>37</td> </tr> </tbody> </table>	Ex. Size	Imp. Size	Length (ft)	Two 5.8' x 3.75' Arches	Two 6' x 4.5' Boxes	37							
Ex. Size	Imp. Size	Length (ft)												
Two 5.8' x 3.75' Arches	Two 6' x 4.5' Boxes	37												
<b>F. Project Cost</b> ..... \$71,000														
<b>G. Contingency</b> ..... <u>\$21,000</u>														
<b>H. Total Preliminary CIP Cost</b> ..... \$92,000														
Project: Ivy Drive Tributary at Ivy Drive	Priority: High	<table> <tr> <td>Stream</td> <td>Priority</td> <td>Outfall</td> </tr> <tr> <td>Existing Pipe</td> <td>High</td> <td>• Node</td> </tr> <tr> <td>Other CIPs</td> <td>Moderate</td> <td></td> </tr> <tr> <td></td> <td>Low</td> <td></td> </tr> </table>	Stream	Priority	Outfall	Existing Pipe	High	• Node	Other CIPs	Moderate			Low	
Stream	Priority	Outfall												
Existing Pipe	High	• Node												
Other CIPs	Moderate													
	Low													
		<b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers												

<b>A. Project ID: CC11</b>	<b>B. Project Name: Rheem Tributary at Hacienda (RT3)</b>								
<b>C. Project Location: Rheem Tributary culvert under Rheem Boulevard to Laguna Creek</b>									
<b>D. Priority: Moderate</b>									
<b>E. Project Type: Culvert</b>									
<b>F. Project Description:</b> Creek flooding on Rheem Boulevard is caused by an undersized culvert under Rheem Boulevard, connecting to Laguna Creek. Upsizing this culvert to convey 100-year flood flow is recommended.									
<table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>54" Pipe</td> <td>60" Pipe</td> <td>1,830</td> </tr> </tbody> </table>				Ex. Size	Imp. Size	Length (ft)	54" Pipe	60" Pipe	1,830
Ex. Size	Imp. Size	Length (ft)							
54" Pipe	60" Pipe	1,830							
<b>G. Project Cost</b> ..... \$2,445,000									
<b>H. Contingency</b> ..... <u>\$734,000</u>									
<b>I. Total Preliminary CIP Cost</b> ..... \$3,179,000									
									
Project: Rheem Tributary at Hacienda	Priority: Moderate	Stream Existing Pipe Other CIPs Priority High Moderate Low Outfall Node	 <b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers 0 50 100 200 Feet						

<b>A. Project ID: CC12</b>	<b>B. Project Name: Rheem Tributary at Scofield Drive (RT1)</b>					
<b>C. Project Location: Rheem Tributary culvert under Scofield Drive</b>						
<b>D. Priority: Moderate</b>						
<b>E. Project Type: Culvert</b>						
<b>F. Project Description:</b> The Rheem Tributary culvert under Scofield Drive is filled with sediment, and may be collapsed. Cleaning this culvert and assessing potential need for replacement is recommended (Replacement CIP estimate provided below).						
<table border="1" style="margin: auto;"> <tr> <td><b>Ex. Size</b></td> <td><b>Length (ft)</b></td> </tr> <tr> <td>60" Pipe</td> <td>110</td> </tr> </table>		<b>Ex. Size</b>	<b>Length (ft)</b>	60" Pipe	110	
<b>Ex. Size</b>	<b>Length (ft)</b>					
60" Pipe	110					
<b>G. Cleaning Project Cost</b> ..... \$25,000 <b>H. Contingency</b> ..... <u>\$8,000</u> <b>I. Total Preliminary CIP Cost</b> ..... \$33,000						
<b>J. Replacement Cost</b> ..... \$161,000 <b>K. Replacement Contingency</b> ..... <u>\$48,000</u> <b>L. Total Replacement CIP Cost</b> ..... \$209,000						
						
Project: Rheem Tributary at Scofield Drive	Priority: Moderate	Stream Existing Pipe Other CIPs	<b>Priority</b> High Moderate Low	▲ Outfall ● Node	 <b>Schaaf &amp; Wheeler</b> Consulting Civil Engineers	

<b>A. Project ID: CC13-19</b>	<b>B. Project Name: Various Projects</b>
<b>C. Project Location: Various Locations</b>	
<b>D. Priority: Low</b>	
<b>E. Project Description:</b> Low Priority culvert projects are shown in the figure below. See pages E.13 – E.14 for individual project descriptions.	
<b>F. Low Priority Projects Cost.....</b>	<b>\$1,754,000</b>
<b>G. Contingency.....</b>	<b><u>\$527,000</u></b>
<b>H. Total Preliminary Low Priority CIP Cost.....</b>	<b>\$2,281,000</b>
<p><b>Culvert Projects: Low Priority</b></p> <ul style="list-style-type: none"> <li>Low Priority</li> <li>Stream</li> <li>Existing Pipe</li> <li>Outfall</li> </ul> <p><b>City_Limits</b></p> <p><b>N</b></p> <p><b>Schaaf &amp; Wheeler Consulting Civil Engineers</b></p> <p>0 0.125 0.25 0.5 Miles</p>	

<b>A. Project ID:</b> CC13	<b>B. Project Name:</b> St. Mary's Trib at Moraga Road (STM1)							
<b>C. Project Location:</b> St. Mary's Tributary culvert under Moraga Road								
<b>D. Priority:</b> Low (Capacity)								
<b>E. Project Type:</b> Culvert								
<b>F. Project Description:</b> Minor creek flooding occurs in Moraga Commons Park. Upsizing the existing pipe culvert under Moraga Road is recommended.								
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>60" Pipe</td> <td>84" Pipe</td> <td>250</td> </tr> </tbody> </table>			Ex. Size	Imp. Size	Length (ft)	60" Pipe	84" Pipe	250
Ex. Size	Imp. Size	Length (ft)						
60" Pipe	84" Pipe	250						
<b>G. Project Cost</b> .....								
<b>H. Contingency</b> .....								
<b>I. Total Preliminary CIP Cost</b> .....								

<b>A. Project ID:</b> CC14	<b>B. Project Name:</b> Laguna Creek at Campolindo (LC1)							
<b>C. Project Location:</b> Laguna Creek culvert under Campolindo Drive								
<b>D. Priority:</b> Low								
<b>E. Project Type:</b> Culvert								
<b>F. Project Description:</b> Minor creek flooding occurs upstream of Campolindo Drive near residences. Upsizing this culvert to convey 100-year flood flow is recommended.								
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>48" Pipe</td> <td>7' x 4' Box</td> <td>260</td> </tr> </tbody> </table>			Ex. Size	Imp. Size	Length (ft)	48" Pipe	7' x 4' Box	260
Ex. Size	Imp. Size	Length (ft)						
48" Pipe	7' x 4' Box	260						
<b>G. Project Cost</b> .....								
<b>H. Contingency</b> .....								
<b>I. Total Preliminary CIP Cost</b> .....								

<b>A. Project ID:</b> CC15	<b>B. Project Name:</b> Las Trampas Creek at Bollinger Canyon (LTC3)							
<b>C. Project Location:</b> Las Trampas Creek culvert under Bollinger Canyon Road								
<b>D. Priority:</b> Low								
<b>E. Project Type:</b> Culvert								
<b>F. Project Description:</b> Minor creek flooding occurs upstream of Bollinger Canyon Road. Upsizing the culvert to convey 100-year flood flow is recommended. This project lies on the border between Orinda and Moraga, and will require coordination with the City of Orinda.								
<table border="1"> <thead> <tr> <th>Ex. Size</th> <th>Imp. Size</th> <th>Length (ft)</th> </tr> </thead> <tbody> <tr> <td>13' x 5' Arch</td> <td>12' x 10' Box</td> <td>70</td> </tr> </tbody> </table>			Ex. Size	Imp. Size	Length (ft)	13' x 5' Arch	12' x 10' Box	70
Ex. Size	Imp. Size	Length (ft)						
13' x 5' Arch	12' x 10' Box	70						
<b>G. Project Cost</b> .....								
<b>H. Contingency</b> .....								
<b>I. Total Preliminary CIP Cost</b> .....								

A. Project ID: CC16	B. Project Name: Las Trampas Creek at St. Mary's Road (LTC1)			
C. Project Location: Las Trampas Creek culvert under Bollinger Canyon Road				
D. Priority: Low (Capacity)				
E. Project Description: Minor creek flooding occurs upstream of Bollinger Canyon Road. Upsizing the existing box culvert to convey the 100-year flood flow is recommended.				
	Ex. Size	Imp. Size	Length (ft)	
	4.5' x 2.67' Arch	5' x 3' Box	80	
F. Project Cost .....		\$168,000		
G. Contingency .....		<u>\$50,000</u>		
H. Total Preliminary CIP Cost .....		\$218,000		

A. Project ID: CC17	B. Project Name: St. Mary's Tributary under Trail (STM4)			
C. Project Location: St. Mary's Tributary culvert under Lafayette/Moraga Regional Trail				
D. Priority: Low (Capacity)				
E. Project Description: Creek flooding occurs between the trail and St. Mary's Road. Upsizing the culvert under the trail to convey the 100-year flood flow is recommended.				
	Ex. Size	Imp. Size	Length (ft)	
	72" Pipe	8' x 6' Box	50	
F. Project Cost .....		\$155,000		
G. Contingency .....		<u>\$47,000</u>		
H. Total Preliminary CIP Cost .....		\$202,000		

A. Project ID: CC18	B. Project Name: Rheem Tributary at Harold Drive (RT2)			
C. Project Location: Rheem Tributary culvert under Harold Drive at Scofield Drive				
D. Priority: Low (Capacity)				
E. Project Description: The existing pipe culvert is more than 50% full of sediment. While no creek flooding occurs currently, further sedimentation could cause creek flooding for nearby residences. Cleaning the pipe to ensure its full capacity is available is recommended.				
	Ex. Size	Length (ft)		
	42" Pipe	130		
F. Project Cost .....		\$20,000		
G. Contingency .....		<u>\$6,000</u>		
H. Total Preliminary CIP Cost .....		\$26,000		