Exhibit F
Hydrant Location Approval

RECEIVED

JAN 29 2008

DK CONSULTING

Moraga-Orinda Fire District
Fire Prevention Division Plan Review

Applicant/Owner:	Richfield Investment Corp. 1900 North California Blvd. #830 Walnut Creek, CA 94596
Subject:	Moraga-Orinda Fire District Fire Hydrant Placement Palos Colorados-Subdivision 8378 Moraga, CA 94556
Date:	January 22, 2008
Contact:	**Bill Svozil, Office of the Fire Marshall**

The Moraga-Orinda Fire District, Office of the Fire Marshal has reviewed the provided plans for fire hydrant locations. Hydrant locations are marked by an orange dot on each set of plans. One minor change made from previous review, hydrant at lot 81-82 relocated to lot 82-83. Also enclosed are the completed EBMUD Hydrant Form and the approved street names for the development.

Please feel free to call me if you have any questions or concerns.

Sincerely,

Bill Svozil
Fire Inspector
Moraga-Orinda Fire District

Michael Mentink
Fire Marshal

Moraga-Orinda Fire District
33 Orinda Way
Orinda, CA 94563

Phone: (925) 258-4520
Fax: (925) 258-4527

January 21, 2009

Lori Salamack
Planning Director
Town of Moraga
329 Rheem Boulevard, Suite 2
Moraga, CA 94556

Subject: Approval of fire hydrant locations for Palos Colorados

Dear Lori,

This letter is to document the District's desire to defer approval of specific hydrant locations for the subject project until the improvement plans are developed. The placement of fire hydrant can be influenced by the location of other infrastructure which oftentimes has not been identified in the tentative maps process. As a result it is our preference to work with staff and the civil engineers preparing the improvement plans to find the best location for the hydrants that takes into account all the infrastructure specifics.

If you have any questions or if this creates a problem for you, please do not hesitate to contact me.

Sincerely,

Michael Mentink, Fire Marshal
Moraga-Orinda Fire District